



# Aviation Investigation Final Report

<b>Location:</b>	Newburyport, Massachusetts	<b>Accident Number:</b>	NYC02LA132
<b>Date &amp; Time:</b>	July 6, 2002, 13:39 Local	<b>Registration:</b>	N823DA
<b>Aircraft:</b>	Beech C23	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation		

## Analysis

The pilot-rated passenger performed the takeoff and downwind departure. As he reduced the engine power to cruise, the engine lost power. The commercial pilot immediately took control of the airplane, but was unable to restore engine power. He set up for a forced landing on a road; however, a vehicle on the road prevented the landing. The commercial pilot then side-stepped the airplane and performed a forced landing in the adjacent marsh. During ground roll, the nose wheel collapsed and the airplane nosed over. Fuel system continuity was confirmed with no evidence of contamination observed. The engine was test run, utilizing the airplane fuel system. However, the engine power was kept low due to damaged engine mounts and vibration. The carburetor was examined and found to run rich at all power settings. The richness varied from 17 percent at idle to 2 1/2 percent at takeoff power.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A power loss for undetermined reason(s), which resulted in a subsequent forced landing to unsuitable terrain. A factor was the unsuitable terrain.

## Findings

Occurrence #1: LOSS OF ENGINE POWER  
Phase of Operation: CRUISE

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

2. (C) TERRAIN CONDITION - NONE SUITABLE

## Factual Information

On July 6, 2002, at 1339 eastern daylight time, a Beech C23, N823DA, was substantially damaged during a forced landing, after departure from Plum Island Airport (2B2), Newburyport, Massachusetts. The certificated commercial pilot and the private pilot were not injured. Visual meteorological conditions prevailed for the flight destined for Beverly Municipal Airport (BVY), Beverly, Massachusetts. No flight plan had been filed for the business flight that was conducted under 14 CFR Part 91.

According to the commercial pilot, the purpose of the flight was to take a company employee from Beverly, Massachusetts (BVY), to Plum Island, and return the airplane to Beverly. A private pilot occupied the left seat and was the pilot flying, while the commercial pilot occupied the right seat. The flight to Plum Island was completed without incident. The passenger disembarked without the engine being shut down, and then the private pilot taxied the airplane to runway 28 for departure. After takeoff, he performed a left downwind departure, and flew the airplane east toward the island's shoreline.

As the airplane neared the shore line, at an altitude of about 1,000 feet, the private pilot reduced engine power to a cruise setting, and noticed that the engine power continued to further reduce to near idle. The commercial pilot immediately took control of the airplane and performed a 90 degree turn to the left, to position the airplane on a left base back to runway 28. The commercial pilot observed that he was too far from the airport to glide to it, and then made a 180 degree turn to the right to follow the shore line to the south. The commercial pilot reported that the beaches were crowded with people. While descending, the commercial pilot changed the fuel selector to the other wing tank, checked carburetor heat, and the magneto switch. His attempts to keep the engine running were not successful. At one time, the engine momentarily surged, but then lost power again, and he was still unable to restore power.

The commercial pilot also reported that he initially thought about landing on a straight stretch of road that ran north and south. As he continued toward that stretch of road, he observed one vehicle, which did not clear the road. At an altitude of about 50 feet AGL, the commercial pilot side-stepped to the right, to land in the marsh. The nosewheel struck an elevated portion of the terrain and collapsed. The nose then dug in, and the airplane came to rest inverted.

According to a Federal Aviation Administration (FAA) inspector, the engine had been pushed rearward, and the firewall was wrinkled. Some of the engine mounts had been fractured. Thumb compression was attained in all cylinders. Fuel flow continuity from the fuel tanks to the carburetor was confirmed. The carburetor fuel screen was absent of debris, and the fuel appeared clean. The spark plugs were not fouled. Electrical continuity was confirmed to the magneto switch. The baffles in the exhaust muffler were in place.

The engine was test run satisfactorily on the airframe, utilizing the airframe fuel system. The engine was not run above idle due to broken engine mounts and vibration.

The carburetor was examined under the supervision of an inspector from the FAA. According to the report, the carburetor flowed 17 percent richer than normal at idle. At the mid-range power settings, the richness decreased to about 5 percent, and at higher power settings, the richness was about 2 1/2 percent.

### Pilot Information

<b>Certificate:</b>	Commercial; Flight instructor	<b>Age:</b>	54, Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	October 30, 2001
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	September 22, 2001
<b>Flight Time:</b>	3586 hours (Total, all aircraft), 1250 hours (Total, this make and model), 3089 hours (Pilot In Command, all aircraft), 118 hours (Last 90 days, all aircraft), 55 hours (Last 30 days, all aircraft)		

### Co-pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	43, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	November 28, 2000
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	August 14, 2001
<b>Flight Time:</b>	420 hours (Total, all aircraft), 108 hours (Total, this make and model), 100 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Beech	<b>Registration:</b>	N823DA
<b>Model/Series:</b>	C23	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	M-2089
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	June 24, 2002 Annual	<b>Certified Max Gross Wt.:</b>	2450 lbs
<b>Time Since Last Inspection:</b>	91.6 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	6887.6 Hrs at time of accident	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	O-360-A4K
<b>Registered Owner:</b>	Albert Graff	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>	General Aviation Services	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	LWM, 149 ft msl	<b>Distance from Accident Site:</b>	14 Nautical Miles
<b>Observation Time:</b>	13:54 Local	<b>Direction from Accident Site:</b>	273°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	9 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	8 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	318°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.92 inches Hg	<b>Temperature/Dew Point:</b>	26°C / 13°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Newburyport, MA (2B2)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Beverly, MA (BVY)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:37 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	Newburyport 2B2	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	11 ft msl	<b>Runway Surface Condition:</b>	Unknown
<b>Runway Used:</b>	28	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	42.775001,-70.808334

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Hancock, Robert
<b>Additional Participating Persons:</b>	John A Donohue; Federal Aviation Administration; Boston, MA
<b>Original Publish Date:</b>	April 17, 2003
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=55148">https://data.ntsb.gov/Docket?ProjectID=55148</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).