



Aviation Investigation Final Report

Location:	Pollock Pines, California	Accident Number:	LAX03LA019
Date & Time:	November 2, 2002, 09:10 Local	Registration:	N2616B
Aircraft:	Bell 47G-2	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor, 2 None
Flight Conducted Under:	Part 91: General aviation - Other work use		

Analysis

During initial climb from a 3,500-foot mean sea level plateau, the helicopter's skid collided with a 3-foot-high bush. The helicopter yawed and impacted the ground. The pilot reported that the collision occurred after he had increased the helicopter's collective pitch and accelerated to about 20 knots, thereby starting to acquire effective translational lift.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain adequate obstruction clearance during initial climb, which resulted in a collision with vegetation.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: TAKEOFF

Findings

1. TERRAIN CONDITION - HIGH VEGETATION
2. (C) ALTITUDE/CLEARANCE - INADEQUATE - PILOT IN COMMAND

Occurrence #2: ROLL OVER
Phase of Operation: TAKEOFF

Factual Information

On November 2, 2002, about 0910 Pacific standard time, a Bell 47G-2, N2616B, collided with a bush and terrain during an attempted takeoff from a plateau near Pollock Pines, California. The helicopter was substantially damaged. The commercial pilot and one passenger were not injured. The second passenger received a minor injury. Visual meteorological conditions prevailed, and no flight plan was filed. The helicopter was operated for hire on a photography flight under the provisions of 14 CFR Part 91, by D. C. Rotor & Wing, Rancho Murieta, California. The flight originated from Rancho Murieta about 0810.

The pilot reported to the National Transportation Safety Board investigator that he flew to the plateau and landed. The two passengers exited the helicopter to take pictures. The helicopter's engine was kept running. Thereafter, the passengers reboarded the helicopter to continue their flight. The pilot stated that because of the ambient conditions, including the 3,500-foot mean sea level elevation and estimated 40-degree Fahrenheit temperature, the helicopter did not have adequate power to make a normal departure from a hover. However, the pilot indicated that he believed there was sufficient clear area over the rocky terrain to perform a running takeoff.

According to the pilot, during the accident sequence he increased the helicopter's collective pitch and accelerated to about 20 knots thereby starting to acquire effective translational lift. During this initial climb a skid collided with a 3-foot-tall bush. The helicopter suddenly yawed and impacted the ground.

In the pilot's completed "Aircraft Accident Report" he stated that "...the purpose of the flight was to encourage [one of the passengers] to resume her flight training with D.C. Rotor."

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	39, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	Helicopter	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	July 22, 2002
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	February 23, 2002
Flight Time:	313 hours (Total, all aircraft), 90 hours (Total, this make and model), 217 hours (Pilot In Command, all aircraft), 42 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N2616B
Model/Series:	47G-2	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2475
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	September 17, 2002 100 hour	Certified Max Gross Wt.:	2450 lbs
Time Since Last Inspection:	30 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	7232 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	VO-435-A1F
Registered Owner:	Gregory J. Desy	Rated Power:	260 Horsepower
Operator:	D. C. Rotor & Wing	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	AUN,1531 ft msl	Distance from Accident Site:	28 Nautical Miles
Observation Time:	08:50 Local	Direction from Accident Site:	280°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.1 inches Hg	Temperature/Dew Point:	13°C / -8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Pollock Pines, CA	Type of Flight Plan Filed:	None
Destination:	Rancho Murieta, CA (RIU)	Type of Clearance:	None
Departure Time:	09:10 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor, 1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 2 None	Latitude, Longitude:	38.722778,-120.601669

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne
Additional Participating Persons:	Greg Michael; Federal Aviation Administration; Sacramento, CA
Original Publish Date:	October 28, 2004
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=56014

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).