



Aviation Investigation Final Report

Location: TALKEETNA, Alaska Accident Number: ANC91LA145

Date & Time: September 4, 1991, 19:00 Local Registration: N9974X

Aircraft: CESSNA 185 Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation

Analysis

DURING THE TAKEOFF AND INITIAL CLIMBOUT, A DOWNDRAFT PUSHED THE AIRPLANE BACK ONTO THE LAKE. SHORTLY THEREAFTER THE AIRPLANE STRUCK A ROCK AT THE END OF THE LAKE AND FLIPPED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: WAS THE PILOT'S FAILURE TO MAINTAIN AIRPLANE CONTROL DURING THE TAKEOFF. CONTRIBUTING TO THE ACCIDENT WAS THE DOWNDRAFT AND UNFAVORABLE WIND.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: TAKEOFF

Findings

1. (F) WEATHER CONDITION - DOWNDRAFT

2. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (F) WEATHER CONDITION - THERMAL LIFT

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF

Page 2 of 6 ANC91LA145

Factual Information

Pilot Information

Certificate:	Commercial	Age:	51,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 1, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	4693 hours (Total, all aircraft), 1100 hours (Total, this make and model), 4693 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC91LA145

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N9974X
Model/Series:	185 185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1850174
Landing Gear Type:	Float	Seats:	4
Date/Type of Last Inspection:	December 5, 1990 Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:	160 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4013 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-520
Registered Owner:	JAMES K. BAILEY	Rated Power:	300 Horsepower
Operator:	JAMES K. BAILEY	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

- Indicate of the grown in the indicate			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	25 miles
Lowest Ceiling:	Overcast / 6000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	25 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	10°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	STEPHAN LAKE , AK (NONE)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	18:00 Local	Type of Airspace:	Class G

Page 4 of 6 ANC91LA145

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	62.45029,-149.789825(est)

Page 5 of 6 ANC91LA145

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James	
Additional Participating Persons:	NONE;	
Original Publish Date:	May 3, 1993	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=5619	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC91LA145