



Aviation Investigation Final Report

Location: BERNERS BAY, Alaska Accident Number: ANC92LA009

Date & Time: October 13, 1991, 17:00 Local Registration: N4693B

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT STATED THAT WHEN HE TURNED THE AIRPLANE AROUND IN PREPARATION FOR A TAKEOFF FROM THE BEACH, THE WHEEL ON THE INSIDE OF THE TURN DUG DOWN INTO THE SAND. WHEN POWER WAS APPLIED TO BEGIN THE TAKEOFF RUN, THE AIRPLANE NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S LOSS OF CONTROL DURING THE PRE TAKEOFF TAXI, DUE TO HIS IMPROPER HANDLING OF THE AIRPLANE. CONTRIBUTING TO THE ACCIDENT WAS THE SOFT TAKEOFF AREA.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. (F) TERRAIN CONDITION - SOFT

2. (C) AIRCRAFT HANDLING - IMPROPER - PILOT IN COMMAND

Occurrence #2: NOSE OVER Phase of Operation: TAXI - TO TAKEOFF

Page 2 of 5 ANC92LA009

Factual Information

Pilot Information

Certificate:	Private	Age:	45.Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	September 21, 1990
Occupational Pilot:	UNK Last Flight Review or Equivalent:		
Flight Time:	410 hours (Total, all aircraft), 286 hours (Total, this make and model), 317 hours (Pilot In Command, all aircraft), 27 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N4693B
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	31591
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	January 2, 2000 Annual	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:	24 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3094 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-470-J
Registered Owner:	MUELLER, JOSEPH R.	Rated Power:	225 Horsepower
Operator:	MUELLER, JOSEPH R.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC92LA009

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	25 knots / 30 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	120°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	10°C
Precipitation and Obscuration:	Light - None - Rain		
Departure Point:		Type of Flight Plan Filed:	None
Destination:	JUNEAU , AK (JUN)	Type of Clearance:	None
Departure Time:	17:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	58.580074,-134.769851(est)

Page 4 of 5 ANC92LA009

Administrative Information

Investigator In Charge (IIC): Daw, Roy

Additional Participating Persons:

Original Publish Date: April 23, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=5666

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC92LA009