

Aviation Investigation Final Report

Location:	Columbus, Ohio	Accident Number:	NYC03LA071
Date & Time:	March 23, 2003, 15:15 Local	Registration:	N2968Z
Aircraft:	Piper PA-22-150	Aircraft Damage:	Substantial
Defining Event:	Injuries: 3 None		
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

The certified flight instructor (CFI) was providing flight instruction to the private pilot/owner of the tail-wheeled airplane. The CFI stated that the private pilot began the takeoff roll from the 5,500-foot-long, 100-foot-wide, asphalt runway. The airplane was almost at takeoff speed when it began to veer to the right. The CFI took control of the airplane, and attempted to correct; however, the airplane departed the right side of the runway, and ground-looped. The left main landing gear collapsed and the left wing struck the ground. Examination of the runway revealed a tire mark began about 350 feet from the beginning of the runway. A second parallel tire mark began to the left of the first tire mark, about 675 feet from the beginning of the runway, and both tire marks continued to the accident site. The airplane came to rest in a grass area, approximately 1,132 feet from the beginning of the runway. Both pilots were unsure if the private pilot had his feet positioned on the rudder pedals in such a way that he inadvertently applied brakes during the takeoff. Winds at the time of the accident were calm.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot under instruction's failure to maintain directional control, and the flight instructor's delayed remedial action.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: TAKEOFF - ROLL/RUN Findings 1. (C) REMEDIAL ACTION - DELAYED - PILOT IN COMMAND(CFI) 2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - COPILOT/SECOND PILOT

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings

3. TERRAIN CONDITION - GRASS

Factual Information

On March 23, 2003, about 1515 eastern standard time, a Piper PA-22-150, N2968Z, was substantially damaged during takeoff from Bolton Field (TZR), Columbus, Ohio. The certificated flight instructor (CFI), a private pilot, and a passenger were not injured. Visual meteorological conditions prevailed and no flight plan had been filed for the flight destined for the Anderson Regional Airport (AND), Anderson, South Carolina. The instructional flight was conducted under 14 CFR Part 91.

According to the CFI, the tail-wheeled airplane was recently purchased by the private pilot, who was also his brother-in-law. The private pilot had not flown regularly since 1983, and the CFI provided the private pilot flight instruction in the airplane, the day before the accident.

During the accident flight, the CFI stated the private pilot began the takeoff roll from runway 22, a 5,500-foot-long, 100-foot-wide, asphalt runway. The airplane was almost at takeoff speed when it began to veer to the right. The CFI took control of the airplane, and attempted to correct; however, the airplane departed the right side of the runway, and ground-looped. The left main landing gear collapsed and the left wing struck the ground.

The CFI stated that they did not experience any mechanical malfunctions. He also said the takeoff was attempted with "very little wind." Winds reported at the airport, at 1525, were calm.

Examination of the runway by the Ohio State Highway Patrol revealed a tire mark began about 350 feet from the beginning of runway 22. A second parallel tire mark began to the left of the first tire mark, about 675 feet from the beginning of the runway, and both tire marks continued to the accident site. The airplane came to rest in a grass area, approximately 1,132 feet from the beginning of the runway.

During an interview with a Federal Aviation Administration inspector, both pilots were unsure if the private pilot had his feet positioned on the rudder pedals in such a way that he inadvertently applied brakes during the takeoff roll.

The CFI and private pilot reported 600 and 280 hours of flight experience in make and model; respectively.

Flight instructor Information

Certificate:	Airline transport; Flight instructor	Age:	61,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	November 12, 2002
Occupational Pilot:	No	Last Flight Review or Equivalent:	October 4, 2001
Flight Time:	27000 hours (Total, all aircraft), 600 hours (Total, this make and model), 15000 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Private	Age:	53,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	280 hours (Total, all aircraft), 280 hours (Total, this make and model), 1 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N2968Z
Model/Series:	PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-6943
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	November 10, 2002 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:	5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2618 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0320
Registered Owner:	Terry T. Kuebler	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	TZN,905 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	15:25 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 4300 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.93 inches Hg	Temperature/Dew Point:	15°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Columbus, OH (TZR)	Type of Flight Plan Filed:	None
Destination:	ANDERSON, SC (AND)	Type of Clearance:	VFR
Departure Time:	15:15 Local	Type of Airspace:	Class D

Airport Information

Airport:	Bolton Field Airport TZR	Runway Surface Type:	Asphalt
Airport Elevation:	905 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	5500 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	39.901111,-83.136665

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke	
Additional Participating Persons:	Gordon L Smith; FAA FSDO-07; Columbus, OH	
Original Publish Date:	February 5, 2004	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=56674	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.