

# **Aviation Investigation Final Report**

Location:	CHANDLER, Arizona	Accident Number:	LAX03LA153
Date & Time:	May 18, 2003, 07:00 Local	<b>Registration:</b>	N24006
Aircraft:	Beech B19	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

#### **Analysis**

The airplane collided with a taxiway sign following a loss of directional control while on the landing roll. During the landing roll, the airplane drifted to the left of the centerline. The pilot applied right rudder pressure in an effort to counteract the drift, and the airplane veered sharply to the right. He applied left rudder pressure to correct for the overcompensation, and the airplane veered sharply to the left. After repeating this sequence, the airplane departed the left side of the runway, and the right wing collided with a taxiway sign. The pilot thought that he might have inadvertently applied pressure to the toe brakes during his attempted corrections, rather than the rudder pedals. The pilot did not report any mechanical problems with the airplane prior to the accident.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's failure to maintain directional control on the landing roll due to his inadvertent use of brakes.

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings 1. (C) BRAKES(NORMAL) - INADVERTENT ACTIVATION - PILOT IN COMMAND 2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND 3. GROUND LOOP/SWERVE - ENCOUNTERED

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ROLL

Findings 4. OBJECT - SIGN

#### **Factual Information**

On May 18, 2003, about 0700 mountain standard time, a Beech B19, N24006, collided with a taxiway sign while on the landing roll at Chandler Municipal Airport (CHD), Chandler, Arizona. The co-owner/pilot was operating the airplane under the provisions of 14 CFR Part 91. The commercial pilot, the sole occupant, was not injured; the airplane sustained substantial damage. The personal local flight departed CHD at an undetermined time. Day visual meteorological conditions prevailed, and a flight plan had not been filed.

In a written statement, the pilot reported that he was performing practice touch-and-go takeoffs and landings on runway 04L. During the landing roll, the airplane drifted to the left of the centerline. The pilot applied right rudder pressure in an effort to counteract the drift. The airplane veered sharply to the right, and he applied left rudder pressure to correct. After repeating this sequence, the airplane departed the left side of the runway, and the right wing collided with a taxiway sign. The airplane sustained substantial damage to the right wing.

During his attempted corrections, the pilot thought that he might have inadvertently applied pressure to the toe brakes, located on the top end of the rudder pedals, rather than the bottom end of the rudder pedals. The pilot did not report any mechanical problems with the airplane prior to the accident.

Certificate:	Commercial	Age:	63,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 4, 2002
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 20, 2002
Flight Time:	485 hours (Total, all aircraft), 11 hours (Total, this make and model), 286 hours (Pilot In Command, all aircraft)		

#### **Pilot Information**

### Aircraft and Owner/Operator Information

		<b>D</b>	
Aircraft Make:	Beech	Registration:	N24006
Model/Series:	B19	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	MB835
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	June 22, 2002 Annual	Certified Max Gross Wt.:	2155 lbs
Time Since Last Inspection:	27 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1733 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320-E3D
Registered Owner:	John R. Elliott and David L. Keiper	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dawn
<b>Observation Facility, Elevation:</b>	CHD,1243 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	06:45 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	25 miles
Lowest Ceiling:	Overcast / 2000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	80°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.8 inches Hg	Temperature/Dew Point:	24°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	CHANDLER, AZ (KCHD)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class D

#### **Airport Information**

Airport:	Chandler Municipal Airport CHD	Runway Surface Type:	Asphalt
Airport Elevation:	1243 ft msl	Runway Surface Condition:	Dry
Runway Used:	04L	IFR Approach:	None
Runway Length/Width:	4850 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.26889,-111.811111

#### **Administrative Information**

Investigator In Charge (IIC):	Jones, Patrick
Additional Participating Persons:	Steve Hanes; Federal Aviation Administration; Scottsdale, AZ
Original Publish Date:	December 28, 2004
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=57015

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.