



Aviation Investigation Final Report

Location: Guymon, Oklahoma Accident Number: FTW03LA162

Date & Time: May 25, 2003, 17:45 Local Registration: N6578E

Aircraft: Cessna A185F Aircraft Damage: Substantial

Defining Event: 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The private pilot encountered a 10 knot crosswind while landing on runway 18. He was not able to maintain directional control after the airplane veered left and departed the runway. No mechanical defects or anomalies were reported or found with the airplane. He had reported over 1136 hours of total flight time which included 432 hours in make and model.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate compensation for the crosswind, and his failure to maintain directional control. A factor was the crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (C) COMPENSATION FOR WIND CONDITIONS - IMPROPER - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings
3. GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Page 2 of 6 FTW03LA162

Factual Information

On May 25, 2003, at 1745 central daylight time, a Cessna A185F tailwheel-equipped airplane, N6578E, was substantially damaged following a loss of directional control while landing at the Guymon Municipal Airport (GUY), near Guymon, Oklahoma. The non-instrument rated private pilot was not injured and his passenger sustained minor injuries. The airplane was registered to and operated by Hitch Enterprises, Inc., of Guymon, Oklahoma. Visual meteorological conditions prevailed, and a flight plan had not been filed for the 14 Code of Federal Regulations Part 91 personal flight. The local flight originated from GUY approximately 1630.

The pilot reported that he flew a visual approach to runway 18 at GUY. The airplane touched down on the main gear at 65 knots, rolled down the runway, and while at approximately 30 knots, the airplane veered to the left of centerline. The pilot added that the airplane "felt like the tail came around." The airplane traveled for an additional 15 feet before coming to rest 10 feet from the east edge of runway 18.

The 1,136-hour pilot reported to have accumulated a total of 432 hours in the same make and model of airplane.

Examination of the wreckage revealed structural damage to the right wing and the right main landing gear attaching point. No mechanical defects were reported by the pilot and no anomalies were found with the airplane that could have prevented normal flight operations.

The weather observation at GUY, at 1653, reported the winds from 120 degrees at 10 knots.

Pilot Information

Certificate:	Private	Age:	57,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 14, 2001
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	May 7, 2002
Flight Time:	1136 hours (Total, all aircraft), 432 hours (Total, this make and model), 1061 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 FTW03LA162

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N6578E
Model/Series:	A185F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18504055
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	June 17, 2002 Annual	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	46 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2581 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-520D30
Registered Owner:	Hitch Enterprises	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GUY,3100 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 2300 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	120°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.02 inches Hg	Temperature/Dew Point:	18°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Guymon (GUY)	Type of Flight Plan Filed:	None
Destination:	(GUY)	Type of Clearance:	None
Departure Time:	16:30 Local	Type of Airspace:	Class E

Page 4 of 6 FTW03LA162

Airport Information

Airport:	Guymon Municipal GUY	Runway Surface Type:	Asphalt
Airport Elevation:	3123 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	5900 ft / 100 ft	VFR Approach/Landing:	Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	36.685001,-101.507774

Page 5 of 6 FTW03LA162

Administrative Information

Investigator In Charge (IIC):	Casanova, Hector	
Additional Participating Persons:	Don M Cook; Federal Aviation Administration; Oklahoma City, OK	
Original Publish Date:	September 30, 2003	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=57074	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 FTW03LA162