



Aviation Investigation Final Report

Location: Montauk, New York Accident Number: NYC03LA130

Date & Time: June 6, 2003, 09:00 Local Registration: N1077V

Aircraft: Mooney M20J Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The airplane was landing on runway 24, a 3,258-foot-long, 85-foot-wide, asphalt runway. According to the pilot, during the landing flare, the airplane encountered a direct crosswind gust that he was unable to correct with right aileron. The pilot added full power and attempted to maneuver the airplane back towards the runway centerline, but the airplane continued to drift left towards brush. He then attempted to climb; however, the left wing made contact with the top of the brush and the airplane struck the ground. The pilot stated he did not experience any mechanical malfunctions. Winds reported at the airport about the time of the accident were from 280 degrees at 11 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control. A factor in this accident was the crosswind condition.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: LANDING

Findings
3. OBJECT - TREE(S)

Page 2 of 6 NYC03LA130

Factual Information

On June 6, 2003, about 0900 eastern daylight time, a Mooney M20J, N1077V, was substantially damaged while landing at Montauk Airport (MTP), Montauk, New York. The certificated private pilot and two passengers were not injured. Visual meteorological conditions prevailed, and no flight plan was filed for the flight that departed Sullivan County International Airport (MSV), Monticello, New York. The personal flight was conducted under 14 CFR Part 91.

The airplane was landing on runway 24, a 3,258-foot-long, 85-foot-wide, asphalt runway.

The pilot stated he applied right aileron and left rudder to keep the airplane straight during final approach due to a crosswind. During the landing flare, the pilot encountered a direct crosswind gust that he was unable to correct with right aileron. The pilot said he added full power and attempted to maneuver the airplane back towards the runway centerline, but the airplane continued to drift left toward brush. He then attempted to climb; however, the left wing made contact with the top of the brush and the airplane struck the ground.

The pilot stated he did not experience any mechanical malfunctions.

The reported wind at MTP, at 0854, was from 280 degrees at 11 knots.

Pilot Information

Certificate:	Private	Age:	42,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 31, 2001
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	January 14, 2003
Flight Time:	720 hours (Total, all aircraft), 36 hours (Total, this make and model), 720 hours (Pilot In Command, all aircraft), 21 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 NYC03LA130

Aircraft and Owner/Operator Information

Aircraft Make:	Mooney	Registration:	N1077V
Model/Series:	M20J	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-3160
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	December 22, 2002 Annual	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:	35 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1035 Hrs at time of accident	Engine Manufacturer:	Avco Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-360-A3B6D
Registered Owner:	Gary P. Gottlieb	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MTP,7 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	08:54 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	6 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.92 inches Hg	Temperature/Dew Point:	16°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	MONTICELLO, NY (MSV)	Type of Flight Plan Filed:	None
Destination:	Montauk, NY (MTP)	Type of Clearance:	None
Departure Time:	08:00 Local	Type of Airspace:	Class E

Page 4 of 6 NYC03LA130

Airport Information

Airport:	Montauk Airport MTP	Runway Surface Type:	Asphalt
Airport Elevation:	7 ft msl	Runway Surface Condition:	Unknown
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	3258 ft / 85 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	41.076667,-71.92028

Page 5 of 6 NYC03LA130

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke
Additional Participating Persons:	Nick Gregoriades; FAA FSDO-11; Farmingdale, NY
Original Publish Date:	March 2, 2004
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=57213

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 NYC03LA130