



# **Aviation Investigation Final Report**

Location:	West Branch, Michigan	Accident Number:	CHI03LA183
Date & Time:	June 15, 2003, 13:38 Local	<b>Registration:</b>	N5695D
Aircraft:	Enstrom 280C	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Serious, 1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

# Analysis

The helicopter impacted water during an autorotation following a loss of engine power. The pilot reported he lost engine power during initial climb and the helicopter landed upright about 75 feet off the shore in about 2-1/2 feet of water. An inspection of the helicopter confirmed flight control continuity. Both fuel tanks contained 25 gallons of fuel and the engine contained 8 quarts of oil. The main and tail rotors showed drivetrain continuity. A large hole was found in the crankcase, near the number one engine cylinder, and the number one connecting rod was protruding from the hole. Examination of the broken connecting rod cap revealed fracture features that were consistent with a fatigue-type failure. Additionally, the material encompassing the fatigue initiation point was galled along with several other areas of the bearing interface.

# **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of engine power due to the fatigue failure of the connecting rod cap. A related factor was the unsuitable terrain the pilot encountered.

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: TAKEOFF - INITIAL CLIMB Findings 1. (C) ENGINE ASSEMBLY, CONNECTING ROD - FAILURE 2. (C) ENGINE ASSEMBLY, CONNECTING ROD - FATIGUE

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY

Findings

3. AUTOROTATION - PERFORMED - PILOT IN COMMAND

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - EMERGENCY

Findings

4. UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - ENCOUNTERED - PILOT IN COMMAND 5. (F) TERRAIN CONDITION - WATER

### **Factual Information**

On June 15, 2003, at 1338 eastern daylight time, an Enstrom 280C, N5695D, owned and piloted by a commercial pilot, sustained substantial damage when it impacted water following a loss of engine power near West Branch, Michigan. Visual meteorological conditions prevailed at the time of the accident. The pilot reported serious injuries and his passenger reported no injuries. The 14 CFR Part 91 personal flight was not operating on a flight plan. The flight departed from a private helipad near West Branch, Michigan, at 1320 with an intended destination of Selkirk, Michigan.

The pilot reported he did not notice any anomalies with the engine gauges while in hover shortly after liftoff. The pilot noted he was in a climbing departure when he heard noises over his headset. The pilot stated he did not have enough engine power to continue flight, so he began an autorotation. The pilot reported he steered right during the autorotation and landed upright about 75 feet off the shore in about 2-1/2 feet of water.

A Federal Aviation Administration (FAA) airworthiness inspector conducted the on-scene inspection of the helicopter. The inspection of the helicopter confirmed flight control continuity. Both fuel tanks contained 25 gallons of fuel and the engine contained 8 quarts of oil. The main and tail rotors showed drivetrain continuity. A large hole was found in the crankcase, near the number one engine cylinder, and the number one connecting rod was protruding from the hole. Examination of the broken connecting rod cap revealed fracture features that were consistent with a fatigue-type failure. Additionally, the material encompassing the fatigue initiation point was galled along with several other areas of the bearing interface.

### **Pilot Information**

Certificate:	Commercial	Age:	52,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	January 28, 2002
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 29, 2003
Flight Time:	1311 hours (Total, all aircraft), 194 hours (Total, this make and model), 23 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	Enstrom	Registration:	N5695D
Model/Series:	280C	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1210
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	May 19, 2003 Annual	Certified Max Gross Wt.:	2350 lbs
Time Since Last Inspection:	12.1 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	768.7 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	HIO-360 SER
Registered Owner:	On file	Rated Power:	205 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dav
Observation Facility, Elevation:	HTL,1150 ft msl	Distance from Accident Site:	22 Nautical Miles
Observation Time:	14:55 Local	Direction from Accident Site:	270°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.14 inches Hg	Temperature/Dew Point:	25°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	West Branch, MI (PVT )	Type of Flight Plan Filed:	None
Destination:	Selkirk, MI (1MI7)	Type of Clearance:	None
Departure Time:	13:20 Local	Type of Airspace:	Class G

# Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 None	Latitude, Longitude:	44.294723,-84.17028

### **Administrative Information**

Investigator In Charge (IIC):	Fox, Andrew	
Additional Participating Persons:	John Miller; FAA- Grand Rapids FSDO; Grand Rapids, MI	
Original Publish Date:	July 29, 2004	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=57311	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.