



# Aviation Investigation Final Report

---

|                                |                                      |                         |             |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| <b>Location:</b>               | Driggs, Idaho                        | <b>Accident Number:</b> | SEA03LA117  |
| <b>Date &amp; Time:</b>        | June 22, 2003, 15:00 Local           | <b>Registration:</b>    | N86182      |
| <b>Aircraft:</b>               | Cessna T337D                         | <b>Aircraft Damage:</b> | Substantial |
| <b>Defining Event:</b>         |                                      | <b>Injuries:</b>        | 2 None      |
| <b>Flight Conducted Under:</b> | Part 91: General aviation - Personal |                         |             |

---

## Analysis

The pilot calculated the distance to his destination at 201 nautical miles and estimated that he had 2 hours of fuel in the main tanks at the time of takeoff. Twelve minutes into the flight and leveling off at 13,500 feet MSL, the Global Positioning System was indicating a groundspeed of 190 knots, with the destination airport 59 minutes away. The pilot assumed he had close to 1 3/4 hours of fuel remaining, and elected to proceed directly to his destination rather than to stop and refuel. 80 nautical miles from the destination airport the pilot began a descent out of 8,000 feet MSL, and 60 nautical miles northwest of the airport he mentioned to his passenger that the right main fuel gauge, which feeds the rear engine, seemed to be reading lower than usual. The pilot switched over to the right aux tank, but two to three minutes later the rear engine started to cough. The pilot then switched back to the right main tank. Approximately 20 nautical miles from the destination airport the front engine began to fail from lack of fuel. The pilot attempted to crossfeed the front engine to the right main tank as the engine was starting to quit. Unable to keep the front engine running, the pilot feathered the front propeller. As the pilot was about to make a radio call on the airport's Unicom frequency, the rear engine began to fail from lack of fuel. The pilot feathered the rear propeller, retracted the flaps, reduced airspeed, and began looking for a forced landing site. The right seat passenger began to manually pump the gear down, but deciding that there was no suitable road within gliding range, the pilot elected to make a wheels up landing in a field. Touching down fairly hard and fast, the airplane spun 90 degrees to the left and began sliding sideways before coming to a stop in an upright position. There was no post-impact fire and neither the pilot or passenger sustained injury.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate inflight decision by failing to refuel while en route, resulting in fuel exhaustion and the loss of power. A factor contributing to the accident was the unsuitable terrain for the forced landing.

### Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - NONMECHANICAL

Phase of Operation: DESCENT

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - INADEQUATE - PILOT IN COMMAND
2. (C) FLUID,FUEL - EXHAUSTION
3. (C) REFUELING - NOT PERFORMED - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY LANDING

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

4. (F) TERRAIN CONDITION - NONE SUITABLE

## Factual Information

On June 22, 2003, approximately 1500 mountain daylight time, a Cessna T337D, N86182, was substantially damaged during a forced landing following a total loss of engine power while descending near Driggs, Idaho. The airplane was registered to and operated by the pilot. The private pilot and his sole passenger were not injured. Visual meteorological conditions prevailed for the 14 CFR Part 91 personal cross-country flight, and a flight plan was not filed. The flight originated from the Johnson Creek Airport (3U2), Yellow Pine, Idaho, at 1400, and was en route to the Driggs-Reed Memorial Airport (U59), Driggs, Idaho.

According to the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2), the pilot reported that after departing 3U2 and climbing to 13,500 feet mean sea level (MSL), his intention was to check weather to the east and refuel in either Challis (LLJ) or Salmon (SMN), Idaho. The pilot stated that the distance to his destination, U59, was 201 nautical miles and estimated that he had 2 hours of fuel in the main tanks at the time of takeoff. After approximately .2 hours (12 minutes) the pilot related that the Global Positioning System (GPS) was indicating a groundspeed of 190 knots, with U59 only 59 minutes away. The pilot stated, "Assuming (incorrectly, as it turned out!) that we had near 1 3/4 hours of fuel remaining, I deleted LLJ from our GPS flight plan and decided to proceed direct to Driggs. We continued to achieve groundspeeds of 180 knots to 190 knots throughout the flight. Approximately 80 nautical miles from U59 the pilot began a slow descent to 8,000 feet MSL. Approximately 60 nautical miles northwest of U59, the pilot mentioned to his passenger that the right main fuel gauge seemed to be reading lower than usual. The pilot then switched the rear engine (normally feed off the right main and right aux tanks) over to the right aux tank. Two to three minutes later the engine [rear engine] started to "cough", prompting the pilot to switch it back over to the right main tank. The pilot reported that about 20 nautical miles from U59 the front engine began to fail from lack of fuel. "Knowing there was little fuel in the left aux tank, I tried to crossfeed the front engine to the right main tank while the engine was still coughing. I was unable to keep the engine running, so I feathered the front propeller and proceeded direct to U59 while maintaining 7,500 feet MSL." The pilot said he was about to make a radio call on the airport's Unicom frequency when the rear engine began to fail from lack of fuel. "I feathered the rear engine while there was still oil pressure, retracted the flaps I had put out for the descent, reduced airspeed to about 115 miles per hour, and began looking for a forced landing site. The pilot stated that at 7,000 feet MSL he turned toward the south, into the wind, looking for north/south roadways while the right seat passenger began to manually pump the gear down. With only the gear doors open and deciding that there was no suitable road within gliding range, the pilot elected to make a wheels up landing in a field. The pilot reported the airplane touched down "fairly hard and fast" due to having only 1/3 flaps on. After slowing, the airplane spun 90 degrees to the left and began sliding sideways before coming to a stop in an upright position. Both the pilot and his passenger exited the airplane uninjured. There was no post-impact fire.

An FAA inspector, who traveled to the aircraft recovery site, reported the aircraft had sustained substantial damage to the lower fuselage frame where both wing struts are attached, as well as to the bottom of the fuselage. The right wing tip and the forward wheel well area were also damaged.

In the Recommendation section of the NTSB Form 6120.1/2, the pilot reported, "Accident was caused by faulty fuel planning. Inadequate allowance for fuel consumed during startup, warm-up, taxi, and initial departure. Avoid by dipping tanks prior to every flight."

### Pilot Information

|                                  |  |  |               |
|----------------------------------|--|--|---------------|
| <b>Certificate:</b>              | Private  | <b>Age:</b>                              | 48, Male      |
| <b>Airplane Rating(s):</b>       | Single-engine land; Multi-engine land  | <b>Seat Occupied:</b>                    | Left          |
| <b>Other Aircraft Rating(s):</b> | None   | <b>Restraint Used:</b>                   |               |
| <b>Instrument Rating(s):</b>     | Airplane   | <b>Second Pilot Present:</b>             | No            |
| <b>Instructor Rating(s):</b>     | None   | <b>Toxicology Performed:</b>             | No            |
| <b>Medical Certification:</b>    | Class 2 Valid Medical--w/ waivers/lim  | <b>Last FAA Medical Exam:</b>            | June 9, 2003  |
| <b>Occupational Pilot:</b>       | No   | <b>Last Flight Review or Equivalent:</b> | June 11, 2001 |
| <b>Flight Time:</b>              | 1767 hours (Total, all aircraft), 1032 hours (Total, this make and model), 1590 hours (Pilot In Command, all aircraft), 84 hours (Last 90 days, all aircraft), 33 hours (Last 30 days, all aircraft) |  |               |

## Aircraft and Owner/Operator Information

|                                      |                                |                                       |                 |
|--------------------------------------|--------------------------------|---------------------------------------|-----------------|
| <b>Aircraft Make:</b>                | Cessna                         | <b>Registration:</b>                  | N86182          |
| <b>Model/Series:</b>                 | T337D                          | <b>Aircraft Category:</b>             | Airplane        |
| <b>Year of Manufacture:</b>          |                                | <b>Amateur Built:</b>                 |                 |
| <b>Airworthiness Certificate:</b>    | Normal                         | <b>Serial Number:</b>                 | 337-1105        |
| <b>Landing Gear Type:</b>            | Tricycle                       | <b>Seats:</b>                         | 4               |
| <b>Date/Type of Last Inspection:</b> | March 24, 2003 Annual          | <b>Certified Max Gross Wt.:</b>       | 4500 lbs        |
| <b>Time Since Last Inspection:</b>   | 87 Hrs                         | <b>Engines:</b>                       | 2 Reciprocating |
| <b>Airframe Total Time:</b>          | 4700 Hrs as of last inspection | <b>Engine Manufacturer:</b>           | Continental     |
| <b>ELT:</b>                          | Installed, not activated       | <b>Engine Model/Series:</b>           | TSIO-360        |
| <b>Registered Owner:</b>             | On file                        | <b>Rated Power:</b>                   | 210 Horsepower  |
| <b>Operator:</b>                     | On file                        | <b>Operating Certificate(s) Held:</b> | None            |

## Meteorological Information and Flight Plan

|   |                                  |   |                   |
|---|----------------------------------|---|-------------------|
| <b>Conditions at Accident Site:</b>     | Visual (VMC)                     | <b>Condition of Light:</b>                  | Day               |
| <b>Observation Facility, Elevation:</b> | RXE,4858 ft msl                  | <b>Distance from Accident Site:</b>         | 36 Nautical Miles |
| <b>Observation Time:</b>                | 14:53 Local                      | <b>Direction from Accident Site:</b>        | 280°              |
| <b>Lowest Cloud Condition:</b>          | Few                              | <b>Visibility</b>                           | 10 miles          |
| <b>Lowest Ceiling:</b>                  | None                             | <b>Visibility (RVR):</b>                    |                   |
| <b>Wind Speed/Gusts:</b>                | 21 knots / 26 knots              | <b>Turbulence Type Forecast/Actual:</b>     | /                 |
| <b>Wind Direction:</b>                  | 200°                             | <b>Turbulence Severity Forecast/Actual:</b> | /                 |
| <b>Altimeter Setting:</b>               | 29.85 inches Hg                  | <b>Temperature/Dew Point:</b>               | 16°C / -1°C       |
| <b>Precipitation and Obscuration:</b>   | No Obscuration; No Precipitation |   |                   |
| <b>Departure Point:</b>                 | Yellow Pine, ID (3U2)            | <b>Type of Flight Plan Filed:</b>           | None              |
| <b>Destination:</b>                     | Driggs, ID (U59)                 | <b>Type of Clearance:</b>                   |                   |
| <b>Departure Time:</b>                  | 14:00 Local                      | <b>Type of Airspace:</b>                    | Class G           |

## Wreckage and Impact Information

|                            |        |                             |                       |
|----------------------------|--------|-----------------------------|-----------------------|
| <b>Crew Injuries:</b>      | 1 None | <b>Aircraft Damage:</b>     | Substantial           |
| <b>Passenger Injuries:</b> | 1 None | <b>Aircraft Fire:</b>       | None                  |
| <b>Ground Injuries:</b>    | N/A    | <b>Aircraft Explosion:</b>  | None                  |
| <b>Total Injuries:</b>     | 2 None | <b>Latitude, Longitude:</b> | 43.808334,-111.216667 |

## Administrative Information

|  |   |
|--|---|
| <b>Investigator In Charge (IIC):</b>     | Little, Thomas  |
| <b>Additional Participating Persons:</b> | Lynn S Higgins; Salt Lake City, Utah; Salt Lake City, UT  |
| <b>Original Publish Date:</b>            | November 25, 2003   |
| <b>Last Revision Date:</b>               |   |
| <b>Investigation Class:</b>              | <a href="#">Class</a>   |
| <b>Note:</b>                             |   |
| <b>Investigation Docket:</b>             | <a href="https://data.ntsb.gov/Docket?ProjectID=57314">https://data.ntsb.gov/Docket?ProjectID=57314</a> |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).