



Aviation Investigation Final Report

Location: KLUTINA LAKE, Alaska Accident Number: ANC92LA087

Date & Time: June 7, 1992, 11:00 Local Registration: N4088M

Aircraft: PIPER PA-12 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT OF THE PIPER PA 12 WAS FLYING AT ABOUT 100 FEET AGL WHEN HE ENCOUNTERED A DOWNDRAFT WHILE HEADING DIRECTLY TOWARD A RIDGE. HE APPLIED FULL POWER, BUT THE AIRCRAFT WAS UNABLE TO OUTCLIMB THE RISING TERRAIN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILO'TS POOR INFLIGHT PLANNING. FACTORS INCLUDE DOWNDRAFTS, AND MOUNTAINOUS/ HILLY TERRAIN.

Findings

Occurrence #1: ALTITUDE DEVIATION, UNCONTROLLED

Phase of Operation: MANEUVERING

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - POOR - PILOT IN COMMAND

2. (F) WEATHER CONDITION - DOWNDRAFT

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings
3. (F) TERRAIN CONDITION - MOUNTAINOUS/HILLY

Page 2 of 5 ANC92LA087

Factual Information

Pilot Information

Certificate:	Private	Age:	30,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 23, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3050 hours (Total, all aircraft), 3000 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N4088M
Model/Series:	PA-12 PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12-3003S
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 14, 1992 100 hour	Certified Max Gross Wt.:	1894 lbs
Time Since Last Inspection:	70 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	O-320-A2A
Registered Owner:	LLOYD, KENT S.	Rated Power:	160 Horsepower
Operator:	MAYEUR, CLINT	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC92LA087

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	17°C
Precipitation and Obscuration:	No Obscuration; No Precipi	tation	
Departure Point:	GULKANA , AK (GKN)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	55.919296,-159.490005(est)

Page 4 of 5 ANC92LA087

Administrative Information

Investigator In Charge (IIC): Daw, Roy

Additional Participating
Persons:

Original Publish Date: May 26, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=5737

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC92LA087