



Aviation Investigation Final Report

Location: Sullivan, Wisconsin Accident Number: CHI03LA206

Date & Time: July 13, 2003, 14:30 Local Registration: N2180V

Aircraft: Cessna 140 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The airplane nosed over after veering off the runway during landing. The pilot reported he observed a 25 to 30 degree, 8 knot crosswind while on downwind. The pilot stated he corrected for the crosswind with left aileron, but the airplane began to drift to the left. The pilot noted that when he applied right rudder and aileron to correct for the drift the wheels began to squeal. The pilot reported the airplane turned to the left as it slowed down and the right wing tip struck the runway. The right main landing gear wheel dug into the sod and the airplane nosed over.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate compensation for wind conditions resulting in a loss of directional control. A factor contributing to the accident was the crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

- 1. (C) COMPENSATION FOR WIND CONDITIONS INADEQUATE PILOT IN COMMAND
- 2. (F) WEATHER CONDITION CROSSWIND
- 3. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND

Occurrence #2: NOSE OVER Phase of Operation: LANDING

Page 2 of 6 CHI03LA206

Factual Information

On July 13, 2003, at 1430 central daylight time, a Cessna 140, N2180V, sustained substantial damage when it nosed over during landing after it veered off runway 24 (4,548 feet by 50 feet, asphalt) at the McDermott Air Park (31WI), Sullivan, Wisconsin. The pilot was not injured. The 14 CFR Part 91 personal flight departed East Troy Municipal Airport, East Troy, Wisconsin, at 1330. Visual meteorological conditions prevailed and no flight plan was filed.

The pilot recalled that as he was on downwind there was about a 25 to 30 degree crosswind with an estimated wind speed of 8 knots. The pilot reported he used left aileron to keep the airplane on the centerline during approach, but the airplane began drifting to the left. The pilot stated he corrected for the drift with right aileron and right rudder during touch down. The pilot indicated he held the right aileron and rudder correction during the landing roll and the wheels started "squealing." The pilot reported the airplane began to turn to the left as it slowed down. The pilot stated the right wing tip struck the runway surface, the right main landing gear wheel dug into the sod, and the airplane subsequently nosed over.

The pilot reported no mechanical malfunctions or defects prior to the accident.

Pilot Information

Certificate:	Private	Age:	42,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	November 9, 2002
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	November 12, 2002
Flight Time:	343 hours (Total, all aircraft), 31 hours (Total, this make and model), 248 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 36 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CHI03LA206

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2180V
Model/Series:	140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	14409
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 8, 2002 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	35 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1945 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	C-85
Registered Owner:	On file	Rated Power:	85 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RYV,833 ft msl	Distance from Accident Site:	11 Nautical Miles
Observation Time:	14:37 Local	Direction from Accident Site:	333°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.07 inches Hg	Temperature/Dew Point:	28°C / 17°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	East Troy, WI (57C)	Type of Flight Plan Filed:	None
Destination:	Sullivan, WI (31WI)	Type of Clearance:	None
Departure Time:	13:30 Local	Type of Airspace:	Class G

Page 4 of 6 CHI03LA206

Airport Information

Airport:	McDermott Air Park 31WI	Runway Surface Type:	Asphalt
Airport Elevation:	875 ft msl	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	4548 ft / 50 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	43.007221,-88.601943

Page 5 of 6 CHI03LA206

Administrative Information

Investigator In Charge (IIC):	Silliman, James	
Additional Participating Persons:	Darrel McCullion; FAA Milwaukee FSDO; Milwaukee, WI	
Original Publish Date:	March 2, 2004	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=57471	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI03LA206