



Aviation Investigation Final Report

Location: SEWARD, Alaska Accident Number: ANC93LA008

Date & Time: October 17, 1992, 15:29 Local Registration: N1660A

Aircraft: PIPER PA-22 Aircraft Damage: Substantial

Defining Event: 1 Serious

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

A WITNESS TO THE ACCIDENT STATED THAT 'THE AIRPLANE TOOK OFF IN A VERY NOSE HIGH ATTITUDE, QUIT FLYING, AND FELL TO THE GROUND.' THEN THE AIRPLANE WENT OFF THE LEFT SIDE OF THE RUNWAY AND CRASHED INTO A LARGE DITCH. THE UNLICENSED PILOT SAID HE COULD NOT REMEMBER EXACTLY WHAT HAPPENED. THE PILOT SAID HE HAD NEVER HAD ANY OFFICIAL FLIGHT INSTRUCTION, BUT HAD FLOWN THREE TIMES WITH A FRIEND DURING THE PREVIOUS YEAR. THE PILOT ALSO SAID THIS WAS HIS SECOND SOLO FLIGHT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOTS FAILURE TO MAINTAIN DIRECTIONAL CONTROL ON THE GROUND. CONTRIBUTING TO THE ACCIDENT WAS THE PILOTS FAILURE TO MAINTAIN AIRSPEED DURING THE TAKEOFF CLIMB, HIS INADEQUATE TRAINING, HIS LACK OF TOTAL EXPERIENCE, AND THE DITCH.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: TAKEOFF

Findings

1. (F) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

2. (F) INADEQUATE TRAINING - PILOT IN COMMAND

3. (F) LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF

Findings

4. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: TAKEOFF

Findings

5. (F) TERRAIN CONDITION - DITCH

Page 2 of 5 ANC93LA008

Factual Information

Pilot Information

Certificate:	None	Age:	64,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N1660A
Model/Series:	PA-22 PA-22	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-429
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	November 30, 1980 Annual	Certified Max Gross Wt.:	1800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-290-D
Registered Owner:	BAILEY, OSCAR H.	Rated Power:	125 Horsepower
Operator:	BAILEY, OSCAR H.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC93LA008

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	SWD ,50 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	14:50 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Scattered / 6000 ft AGL	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	3°C / -2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(SWD)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:29 Local	Type of Airspace:	Class G

Airport Information

Airport:	SEWARD SWD	Runway Surface Type:	Asphalt
Airport Elevation:	50 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	60.049438,-149.330764(est)

Page 4 of 5 ANC93LA008

Administrative Information

Investigator In Charge (IIC): Daw, Roy Additional Participating PETER DULA; ANCHORAGE , AK **DEBBIE** Persons: BEU; ANCHORAGE , AK **Original Publish Date:** September 28, 1993 **Last Revision Date:** Class **Investigation Class:** Note: Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=5847

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC93LA008