



# Aviation Investigation Final Report

---

<b>Location:</b>	Fort Lauderdale, Florida	<b>Accident Number:</b>	MIA04LA062
<b>Date &amp; Time:</b>	March 13, 2004, 04:50 Local	<b>Registration:</b>	N11FL
<b>Aircraft:</b>	Beech BE90	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	7 None
<b>Flight Conducted Under:</b>	Part 135: Air taxi & commuter - Non-scheduled		

---

## Analysis

The pilot stated, during the approach to the airport he selected the landing gear to the down position. He observed two green lights and the light for the left landing gear was off on the landing gear indication. He informed the tower of the situation and cycled the gear with no change to the indication. He advised the tower he would like to perform a fly-by to have a visual check of the landing gear. The tower approved the low approach. The pilot cycled the landing gear one more time and got three green lights on the landing gear indication. The tower informed the pilot the gear appeared to be down and in place. The pilot requested and received clearance to land on runway 13. The accident airplane landed and rolled approximately 2,000 feet on the runway before the left main landing gear collapsed. The FAA inspector who responded to the accident site stated, the left main gear assembly was found retracted and up into the engine nacelle. The lock down assembly was unlocked and undamaged. The left main landing gear torque link was broken and the left landing gear actuator gearbox assembly was detached from its mount box. The investigating FAA inspector stated, at the time of the accident the accident airplane had accumulated about 148 hours since its last maintenance inspections, on January 3, 2004. That inspection included checking the actuator support brackets for visible damage, wear, cracks, loose or missing rivets. An examination of the fractured left gear actuator support box structure brackets revealed a crack that circumscribes the lower hi-shear rivet holes of the outboard bracket. The operator of the accident airplane stated, during damage assessment, a structural failure of the left main landing gear actuator support box structure was discovered. They suspected the structure had at least one existing crack which allowed the actuator to "float" within the support structure not allowing complete spring compression from the actuator to engage the left main landing gear drag leg hooks.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The inadequate inspection of the landing gear system by company maintenance personnel resulting in a crack in the left main landing actuator mount going undetected and collapse of the left landing gear during landing roll when the actuator attachment failed.

### Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: APPROACH

#### Findings

1. LANDING GEAR,MAIN GEAR ATTACHMENT - CRACKED
2. (C) MAINTENANCE,INSPECTION - INADEQUATE - COMPANY MAINTENANCE PERSONNEL
3. LANDING GEAR,MAIN GEAR ATTACHMENT - FAILURE

-----

Occurrence #2: GEAR COLLAPSED

Phase of Operation: LANDING - ROLL

## Factual Information

On March 13, 2004, about 0450 eastern daylight time, a Beech BE90, N11FL, registered to Core Investments Inc. and operated by Execstar Aviation, as a Title 14 CFR Part 135 on demand air taxi flight, experienced a collapse of the left main landing gear during the landing roll at Fort Lauderdale International Airport, Fort Lauderdale, Florida. Visual meteorological conditions prevailed and an instrument flight rule flight plan was filed. The commercial-rated pilot and the six passengers were not injured, and the airplane incurred substantial damage. The flight originated from Cancun International Airport, Cancun, Mexico, earlier that day, about 0100.

The pilot stated, during the approach to the airport he selected the landing gear handle to the down position. He observed two green lights and the light for the left landing gear was off on the landing gear indication. He reduced engine power and heard the landing gear warning horn and elected to abort the landing. He informed the tower of the situation and recycled the landing gear. The landing gear indication did not change. He advised the tower he would like to perform a fly-by to have a visual check of the gear. The tower advised the pilot to perform a low approach south of the tower to observe the landing gear position. The pilot cycled the landing gear one more time and got three green lights on the landing gear indication. The tower informed the pilot the gear appeared to be down and in place, and asked the pilot to state his intentions. The pilot then requested a landing clearance. At which time, the tower cleared the pilot to land on runway 13 and called Airport Rescue Fire Fighting to standby. The accident airplane landed on runway 13 and rolled approximately 2,000 feet on the runway before the left main landing gear collapsed.

The FAA inspector who responded to the accident site stated, the left main gear assembly was found retracted and up into the engine nacelle. The lock down assembly was unlocked and undamaged. The left main landing gear torque link was broken and the left landing gear actuator gearbox assembly was detached from its mount box. The left main landing gear gearbox drive shaft was disconnected from the universal joint and the connecting bolt was missing.

The investigating FAA inspector stated, at the time of the accident the accident airplane had accumulated about 148 hours since its last maintenance inspection, a Phase 3 of its Airplane Approved Inspection Program, on January 3, 2004. The Phase 3 inspection includes checking the actuator support brackets for visible damage, wear, cracks, and loose or missing rivets. An examination of the fractured left gear actuator support box structure brackets revealed a crack that circumscribes the lower hi-shear rivet holes of the outboard bracket.

The operator of the accident airplane discovered a structural failure of the left main landing gear actuator support box structure during assessment of the damage to the left wheel well area. They report that it is suspected the structure had at least one existing crack which

allowed the actuator to "float" within the support structure not allowing complete spring compression from the actuator to engage the left main landing gear drag leg hooks.

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	30, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	March 1, 2003
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	March 1, 2004
<b>Flight Time:</b>	3900 hours (Total, all aircraft), 1600 hours (Total, this make and model), 3000 hours (Pilot In Command, all aircraft), 44 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Beech	<b>Registration:</b>	N11FL
<b>Model/Series:</b>	BE90	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	LJ-301
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	10
<b>Date/Type of Last Inspection:</b>	January 1, 2004 AAIP	<b>Certified Max Gross Wt.:</b>	9300 lbs
<b>Time Since Last Inspection:</b>	164.1 Hrs	<b>Engines:</b>	2 Turbo prop
<b>Airframe Total Time:</b>	14744.3 Hrs at time of accident	<b>Engine Manufacturer:</b>	Pratt & Whitney
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	PT6A-20
<b>Registered Owner:</b>	Core Investments Inc.	<b>Rated Power:</b>	550 Horsepower
<b>Operator:</b>	EXECSTAR AVIATION INC	<b>Operating Certificate(s) Held:</b>	On-demand air taxi (135)
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	XVQA

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Dawn
<b>Observation Facility, Elevation:</b>	KFLL, 9 ft msl	<b>Distance from Accident Site:</b>	0 Nautical Miles
<b>Observation Time:</b>	04:53 Local	<b>Direction from Accident Site:</b>	0°
<b>Lowest Cloud Condition:</b>	Scattered / 3400 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 4500 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	8 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	60°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.14 inches Hg	<b>Temperature/Dew Point:</b>	21°C / 17°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Cancun (MMUN)	<b>Type of Flight Plan Filed:</b>	IFR
<b>Destination:</b>	Fort Lauderdale, FL (KFLL)	<b>Type of Clearance:</b>	IFR
<b>Departure Time:</b>	06:00 UTC	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Fort Lauderdale-Hollywood Intl FLL	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	9 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	13	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	6930 ft / 150 ft	<b>VFR Approach/Landing:</b>	Straight-in

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	6 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	7 None	<b>Latitude, Longitude:</b>	26.18943,-80.170845(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Yurman, Alan
<b>Additional Participating Persons:</b>	Carlton L Kitchen; FAA / Fort Lauderdale FSDO-17; Fort Lauderdale, FL
<b>Original Publish Date:</b>	September 13, 2005
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=58924">https://data.nts.gov/Docket?ProjectID=58924</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).