



Aviation Investigation Final Report

Location:	Norfolk, Virginia	Accident Number:	NYC04LA142
Date & Time:	June 15, 2004, 18:20 Local	Registration:	N2065T
Aircraft:	Schweizer 269C	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

The student pilot was conducting his third supervised solo flight, and had completed two takeoffs and landings. During his third landing attempt, after the helicopter contacted the ground, it began to vibrate violently. The student pilot was not able to stop the vibration, before the helicopter began to break apart. The accident was witnessed by the student pilot's flight instructor, who stated he utilized a hand-held radio to tell the student to pick up the helicopter, in order to recover. Examination of the landing skid dampers revealed that they were improperly charged. The helicopter had been operated for 371 hours since it's most recent annual inspection, which was performed about 6 months prior to the accident. The helicopter had been operated for 85 hours since it's most recent 100-hour inspection. The student pilot had accumulated 22 hours of total flight experience, all in the same make and model as the accident helicopter.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's failure to maintain control of the helicopter, which resulted ground resonance. Contributing to the accident was the improperly serviced landing gear dampers.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING

Findings

1. (F) LANDING GEAR,MAIN GEAR SHOCK ABSORBING STRUT - IMPROPERLY SERVICED
2. (C) GROUND RESONANCE - ENCOUNTERED
3. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

On June 15, 2004, about 1820 eastern daylight time, a Schweizer 269C, N2065T, was substantially damaged while landing at Hampton Roads Executive Airport, Norfolk, Virginia. The certificated student pilot was not injured. Visual meteorological conditions prevailed and no flight plan had been filed for the solo instructional flight conducted under 14 CFR Part 91.

According to a Federal Aviation Administration (FAA) inspector, the student pilot was conducting his third supervised solo flight, and had completed two takeoffs and landings. During his third landing attempt, after the helicopter contacted the ground, it began to vibrate violently. The student pilot was not able to stop the vibration, before the helicopter began to break apart.

The accident was witnessed by the student pilot's flight instructor, who stated he utilized a hand-held radio to tell the student to pick up the helicopter, in order to recover.

Examination of the landing skid dampers conducted by Schweizer Aircraft Corporation revealed that they were improperly charged. Three of the four dampers had maximum travel compression values in excess of that specified for their part number. According to a Schweizer representative, the improperly charged dampers would have effected their attenuation capability.

The helicopter had been operated for 371 hours since it's most recent annual inspection, which was performed on December 23, 2003. The helicopter had been operated for 85 hours since it's most recent 100-hour inspection.

The student pilot had accumulated 22 hours of total flight experience, all in the same make and model as the accident helicopter.

According to FAA publication FAA-H-8083-21, "Rotorcraft Flying Handbook:"

"Ground resonance is an aerodynamic phenomenon associated with fully-articulated rotor systems. It develops when rotor blades move out of phase with each other and cause the rotor disc to become unbalanced. This condition can cause a helicopter to self-destruct in a matter of seconds....If the rpm is low, the corrective action to stop ground resonance is to close the throttle immediately and fully lower the collective to place the blades in low pitch. If the rpm is in the normal range, you should fly the helicopter off the ground, and allow the blades to automatically realign themselves. You can then make a normal touchdown...."

Student pilot Information

Certificate:	None	Age:	31, Male
Airplane Rating(s):	None	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	April 8, 2004
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	22 hours (Total, all aircraft), 22 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Schweizer	Registration:	N2065T
Model/Series:	269C	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	146
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	December 23, 2003 Annual	Certified Max Gross Wt.:	1900 lbs
Time Since Last Inspection:	371 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1404 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	HIO-360-D1A
Registered Owner:	Aerial Resources LLC.	Rated Power:	190 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	NGU,15 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	18:55 Local	Direction from Accident Site:	45°
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	7 miles
Lowest Ceiling:	Broken / 12000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.07 inches Hg	Temperature/Dew Point:	30°C / 22°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Norfolk, VA (PVG)	Type of Flight Plan Filed:	None
Destination:	Norfolk, VA (PVG)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	Hampton Roads Executive PVG	Runway Surface Type:	Concrete
Airport Elevation:	23 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.781387,-76.448608

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke
Additional Participating Persons:	A.C. McClain; FAA Richmond FSDO; Richmond, VA
Original Publish Date:	April 28, 2005
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=59472

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).