



# **Aviation Investigation Final Report**

Location: Lordsberg, New Mexico Accident Number: DEN04LA146

Date & Time: September 21, 2004, 13:00 Local Registration: N11BE

Aircraft: Smith Aerostar 601P Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation

### **Analysis**

According to the pilot, during the take off roll from runway 12, the airplane "veered 30 degrees to the right, departed the runway, and came to rest a couple of hundred yards away in sagebrush," causing substantial damage. The pilot stated that prior to the take-off roll, he observed the wind sock "hanging down indicating a no-wind situation." The winds 33 miles northeast of the airport were reported as 250 degrees at 11 knots with gusts to 17 knots. According to a witness, the airplane got caught in a whirlwind. An examination of the airplane's systems revealed no anomalies.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: aircraft control not maintained by the pilot. Contributing to the accident was the dirt devil/whirlwind.

#### **Findings**

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH WEATHER

Phase of Operation: TAKEOFF - ROLL/RUN

**Findings** 

1. (F) WEATHER CONDITION - DUST DEVIL/WHIRLWIND

. . . . . . . . . .

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

**Findings** 

2. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

------

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

3. TERRAIN CONDITION - HIGH VEGETATION

Page 2 of 6 DEN04LA146

#### **Factual Information**

On September 21, 2004, at approximately 1300 mountain daylight time, a Smith Aerostar 601P, N11BE, operated by Campground Brokers Inc., was substantially damaged when it impacted terrain during takeoff roll at Lordsburg Municipal Airport, Lordsburg (LSB), New Mexico. Visual meteorological conditions prevailed at the time of the accident. The business flight was being conducted under the provisions of Title 14 CFR Part 91 without a flight plan. The private pilot reported no injuries. The cross-country flight was originating at the time of the accident and was en route to Phoenix, Arizona.

According to the accident report submitted by the pilot, during take off roll from runway 12, the airplane "veered 30 degrees to the right, departed the runway, and came to rest a couple of hundred yards away in sagebrush." Both landing gear folded, both propellers were damaged and the right wing spar was bent. The pilot stated that prior to the take-off roll, he observed the wind sock "hanging down indicating a no-wind situation." The winds at Grant County Airport, 33 miles northeast of LSB were reported as 250 degrees at 11 knots with gusts to 17 knots. According to a witness, the airplane got caught in a whirlwind. An examination of the airplane's systems revealed no anomalies.

#### **Pilot Information**

Certificate:	Private	Age:	56,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 2, 2003
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 2, 2004
Flight Time:	4062 hours (Total, all aircraft), 1058 hours (Total, this make and model), 4010 hours (Pilot In Command, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 DEN04LA146

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Smith	Registration:	N11BE
Model/Series:	Aerostar 601P	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	61P-0203-017
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	6000 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-540
Registered Owner:	On file	Rated Power:	350 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dawn
Observation Facility, Elevation:	SVC,4278 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	12:50 Local	Direction from Accident Site:	300°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots / 17 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.09 inches Hg	Temperature/Dew Point:	25°C / 5°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lordsberg, NM (LSB)	Type of Flight Plan Filed:	None
Destination:	PHOENIX, AZ (PHX )	Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	Class G

Page 4 of 6 DEN04LA146

## **Airport Information**

Airport:	LORDSBURG MUNI LSB	Runway Surface Type:	Asphalt
Airport Elevation:	4278 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	12	IFR Approach:	None
Runway Length/Width:	5011 ft / 75 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	32.332778,-108.683891

Page 5 of 6 DEN04LA146

#### **Administrative Information**

Investigator In Charge (IIC):	Bowling, David	
Additional Participating Persons:	Kenneth D Hand; FAA Flight Standards District Office; Albuquerque, NM	
Original Publish Date:	January 24, 2005	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=60173	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 DEN04LA146