



# Aviation Investigation Final Report

---

<b>Location:</b>	Hermiston, Oregon	<b>Accident Number:</b>	SEA05LA006
<b>Date &amp; Time:</b>	October 14, 2004, 09:00 Local	<b>Registration:</b>	N706C
<b>Aircraft:</b>	Caldwell Glasair II	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>		<b>Injuries:</b>	1 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

After performing a number of low-level aerobatic maneuvers to the east of the airport, the pilot made a low-level pass over the runway from east to west. He then executed a rapid pull-up, and climbed on a near-vertical line. As the aircraft climbed, its airspeed decreased to the point that when the pilot executed a wingover maneuver at the top of the climb, the aircraft entered a spin. It then spun two or three times to the left, before its rotation rate began to decrease. As the rotation rate decreased, the pilot attempted to pull out of the dive, but the aircraft impacted the terrain and immediately burst into flames. There was no indication of any problems with the flight controls, nor any evidence that there had been a malfunction associated with the engine.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain an airspeed above stall speed while executing a wingover maneuver at the top of a vertical climb, leading to an inadvertent spin, and the pilot's inadequate remedial action in attempting to recover from the spin. Factors include performing aerobatic maneuvers close to the terrain.

## Findings

---

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING

### Findings

1. (C) AIRSPEED(VS) - NOT MAINTAINED - PILOT IN COMMAND
2. STALL/SPIN - ENCOUNTERED - PILOT IN COMMAND
3. (C) REMEDIAL ACTION - INADEQUATE - PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: MANEUVERING

### Findings

4. AEROBATICS - PERFORMED - PILOT IN COMMAND
5. (F) LOW ALTITUDE FLIGHT/MANEUVER - INTENTIONAL - PILOT IN COMMAND
6. TERRAIN CONDITION - GROUND

## Factual Information

On October 14, 2004, approximately 0900 Pacific daylight time, an experimental Caldwell Glasair II, N706C, impacted the terrain while the pilot was performing low-level aerobatic maneuvers about one-half mile southwest of Hermiston Municipal Airport, Hermiston, Oregon. The private pilot, who was the sole occupant, received fatal injuries, and the aircraft, which was owned and operated by the pilot, was destroyed by the impact and post-crash fire. The 14 CFR Part 91 personal pleasure flight, which departed Hermiston about 15 minutes before the crash, was being operated in visual meteorological conditions. No flight plan had been filed. There was no report of an ELT activation.

According to witnesses, the pilot, who had been performing low-level aerobatic maneuvers to the east of the airport, made a low-level pass over the runway from east to west. The aircraft then pulled up rapidly and climbed on a near-vertical line. As the aircraft reached the top of its climb, its forward speed appeared to become very slow, and then it was witnessed doing a "wingover-like" maneuver to the left. As it completed the wingover maneuver, it appeared to enter a spin. The aircraft spun two or three times to the left, and then according to the witnesses, its rotation rate decreased. The witnesses reported that at the point where the rotation seemed to decrease, the nose of the aircraft started to rise, "as if the pilot was attempting to pull out of the dive." But soon after the rotation decreased and the nose started to rise, the aircraft impacted the terrain and immediately burst into flames.

All witnesses noted that the aircraft's aerobatic smoke system was producing a significant amount of smoke as it climbed, but there was disagreement as to the amount it produced on the way down. Some said that no smoke was produced on the way down, but others said that once the rotation rate slowed and the nose started to rise, that the smoke started being produced again. There was also some disagreement about whether the engine was producing power during the entire sequence. All witnesses said that the engine sounded as if it were at full power on the way up, but some thought that it was not producing much power on the way down. A number of witnesses stated that it appeared to them that the pilot may have pulled the power to idle after the wingover, and then about half way down, the engine went back to full power and the aerobatic smoke started being produced again.

According to the FAA Inspector who evaluated the aircraft wreckage at the scene, there was no evidence of any engine malfunction, or any indication that there had been a problem with the flight control system.

A toxicology examination was negative for all tested substances, and the autopsy identified the cause of death as accidental as the result of blunt impact forces.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	60, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	May 7, 2004
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	1350 hours (Total, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Caldwell	<b>Registration:</b>	N706C
<b>Model/Series:</b>	Glasair II	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	307
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>		<b>Certified Max Gross Wt.:</b>	1900 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	IO-360
<b>Registered Owner:</b>	Steven M. Caldwell	<b>Rated Power:</b>	200 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KHRI,644 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	08:53 Local	<b>Direction from Accident Site:</b>	40°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	130°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.2 inches Hg	<b>Temperature/Dew Point:</b>	11°C / 9°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Hermiston, OR (HRI )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	(HRI )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	08:45 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Hermiston Municipal Airport KHRI	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	644 ft msl	<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	On-ground
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Fatal	<b>Latitude, Longitude:</b>	45.823055,-119.277496

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Anderson, Orrin
<b>Additional Participating Persons:</b>	Robert Eccles; Portland FSDO; Hillsboro, OR
<b>Original Publish Date:</b>	September 13, 2005
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=60337">https://data.nts.gov/Docket?ProjectID=60337</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).