



Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| Location: | Bay St. Louis, Mississippi | Accident Number: | ANC05LA029 |
| Date & Time: | February 10, 2005, 17:30 Local | Registration: | N6742S |
| Aircraft: | Beech A36 | Aircraft Damage: | Substantial |
| Defining Event: | | Injuries: | 3 None |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

The pilot/owner of the airplane heard a low thumping noise during takeoff on several occasions, which he associated with the landing gear. He flew the airplane to an airport to have a mechanic familiar with his airplane troubleshoot the noise. After a visual inspection failed to reveal the problem, a test flight was initiated. The mechanic seated in the rear of the airplane heard the noise, and after flying around for a few minutes, requested a return to the airport. During extension of the landing gear, the 3 green (gear down/locked) lights failed to illuminate. The pilot cycled the gear, but the lights again failed to illuminate. He stated he thought he had heard all the appropriate sounds associated with proper landing gear extension, and elected to continue the landing, without attempting the manual extension of the gear as prescribed in the "Emergency Procedures" section of the pilot's operating handbook. During the landing roll the landing gear collapsed. Postaccident testing of the landing gear was conducted with the airplane on jacks. Tests revealed that the charge on the battery was insufficient to extend the electrically operated landing gear completely. The battery was found to be capable of taking a charge, but further tests revealed no output from the alternator. The alternator's rotor was found to be defective and the electrical brushes excessively worn.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to use the manual emergency landing gear extension mechanism during the approach to land, which resulted in the electrically actuated main landing gear collapsing during the landing roll. A factor associated with the accident is an inoperative alternator.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: APPROACH

Findings

1. (F) ELECTRICAL SYSTEM,ALTERNATOR - INOPERATIVE

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING - ROLL

Findings

2. TERRAIN CONDITION - RUNWAY

3. (C) EMERGENCY PROCEDURE - NOT PERFORMED - PILOT IN COMMAND

Factual Information

On February 10, 2005, about 1730 central standard time, a Beech A36 airplane, N6742S, sustained substantial damage when the landing gear collapsed during landing at the Stennis International Airport, Bay St. Louis, Mississippi. The airplane was being operated by the pilot as a visual flight rules (VFR) local personal flight under Title 14, CFR Part 91 when the accident occurred. The private pilot and two passengers were not injured. Visual meteorological conditions prevailed, and no flight plan was filed.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge (IIC) on February 11, the pilot said he had flown the accident airplane to Stennis International Airport to pickup an aircraft mechanic, and have him listen to a "low thumping" noise the airplane was making during takeoff. He said after returning from the flight, the landing gear down and locked indicator's three green lights failed to illuminate when he extended the landing gear. The pilot said none of the remedial actions he took resulted in a green, down and locked indication, but he felt the gear was down and locked. He said during the landing roll the nose gear collapsed, followed by the collapse of the right main gear. He said the right wing sustained structural damage when the landing gear collapsed.

In a subsequent written statement dated February 15, 2005, the pilot reported that he had contacted Beechcraft in reference to a low thumping noise he routinely heard during initial takeoff. Beechcraft suggested an inspection of the landing gear and associated mechanisms for security. After inspecting the airplane himself, and finding nothing unusual, the pilot flew the airplane to an airport where a mechanic familiar with his specific airplane could troubleshoot the problem. The mechanic visually inspected the airplane, and found no mechanical anomalies. They decided to fly the airplane with the mechanic in the rear seat, to facilitate listening to the gear during retraction. During takeoff-initial climb, the low thumping noise was heard prior to gear retraction. During gear retraction the pilot reported hearing all the normal sounds associated with the retraction process. They flew the airplane for a short time, and returned to the airport for landing. The pilot reported that prior to landing, he heard all the appropriate sounds associated with the extension of the landing gear, but the 3 green lights associated with the gear down and locked condition did not illuminate. The pilot cycled the landing gear, and heard what he believed were all the appropriate sounds associated with the retraction and re-extension of the landing gear. He reported the 3 green lights again did not illuminate. He elected to continue the landing without executing the emergency gear extension procedures. He reported that during the landing sequence he retarded the throttle specifically to see if the gear warning horn would activate. The warning horn did not activate, adding to his belief the landing gear was down and locked. The landing gear collapsed during the landing roll.

After recovery the airplane was placed on jacks for gear retraction tests. During the initial test

the 3 green gear down and locked lights did not illuminate, and it was found the nose gear light was burned out. After replacing the nose gear light the tests continued. The gear cycled normally on the first test, but the battery went dead. The airplane's gear retraction system is an electrically driven mechanical system. The tests were continued using auxiliary power, and proceeded without incident. The battery was tested, and found to be in good condition, but uncharged. The alternator was removed, and sent to a certified shop for inspection. The alternator was tested, and found to have zero output. During teardown and inspection, the alternator's rotor was found to be defective, and the electrical brushes worn excessively.

The airplane is equipped with a manual hand crank to extend the landing gear in the event of a landing gear system failure. The procedures for manual extension are contained in the pilot's operating handbook under "Emergency Procedures."

Pilot Information

| | | | |
|----------------------------------|---------------------------------------|------------------------------------------|----------------|
| Certificate: | Private | Age: | 59, Male |
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | August 1, 2003 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | March 1, 2004 |
| Flight Time: | 4500 hours (Total, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|--------------------------------|---------------------------------------|-----------------|
| Aircraft Make: | Beech | Registration: | N6742S |
| Model/Series: | A36 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | E1635 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 6 |
| Date/Type of Last Inspection: | November 1, 2004 Annual | Certified Max Gross Wt.: | 3000 lbs |
| Time Since Last Inspection: | 13 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 2166 Hrs as of last inspection | Engine Manufacturer: | Continental |
| ELT: | Installed, not activated | Engine Model/Series: | IO-520-BB |
| Registered Owner: | Free Sky LLC | Rated Power: | 285 Horsepower |
| Operator: | John Schwegmann | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|-----------------------------------------|----------------------------------|---------------------------------------------|------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | KHSA | Distance from Accident Site: | |
| Observation Time: | 16:40 Local | Direction from Accident Site: | |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 8 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 340° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.29 inches Hg | Temperature/Dew Point: | 9°C / -1°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Bay St. Louis, MS (HSA) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | |

Airport Information

| | | | |
|-----------------------------|--------------------|----------------------------------|-----------------|
| Airport: | Bay St. Louis KHSA | Runway Surface Type: | Asphalt |
| Airport Elevation: | | Runway Surface Condition: | Dry |
| Runway Used: | 18 | IFR Approach: | None |
| Runway Length/Width: | 8500 ft / 75 ft | VFR Approach/Landing: | Traffic pattern |

Wreckage and Impact Information

| | | | |
|----------------------------|--------|-----------------------------|----------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
| Passenger Injuries: | 2 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 3 None | Latitude, Longitude: | 30.367776,-89.454719 |

Administrative Information

| | |
|------------------------------------------|---------------------------------------------------------------------------------------------------------|
| Investigator In Charge (IIC): | Lewis, Lawrence |
| Additional Participating Persons: | Chuck Wittington; FAA FSDO ; Jackson, MS |
| Original Publish Date: | December 20, 2005 |
| Last Revision Date: | |
| Investigation Class: | Class |
| Note: | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=61003 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).