



Aviation Investigation Final Report

Location: Bloomingburg, New York Accident Number: IAD05CA081

Date & Time: June 20, 2005, 16:24 Local Registration: N341PW

Aircraft: PZL Swidnik PW-5 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot was participating in a competition between regional glider pilots. After approximately 2.5 hours of gliding, while heading towards Middletown, New York, the pilot stated that thermal lift began to decrease, so he decided to divert to a closer airport. About 4.1 nautical miles from the airport, his glide computer indicated an estimated arrival altitude of 350 feet agl. Over the next mile, lift continued to be lost and the glider descended about 300 feet, which forced the pilot to find an off airport location to land. The pilot set up a right hand traffic pattern to a hay field and when he made a right turn from the base leg of the traffic pattern to the final leg, the glider's "airspeed was low" and it subsequently "stalled and nosed down."

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain airspeed, which resulted in an inadvertent stall, and subsequent impact with terrain.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: APPROACH - VFR PATTERN - BASE LEG/BASE TO FINAL

Findings

1. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

2. STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

3. TERRAIN CONDITION - GROUND

Page 2 of 6 IAD05CA081

Factual Information

On June 20, 2005, about 1624 eastern daylight time, a PZL-Swidnik PW-5 glider, N341PW, was substantially damaged when it impacted terrain while maneuvering for an off airport landing near Bloomingburg, New York. The certificated private pilot received minor injuries. Visual meteorological conditions prevailed and no flight plan was filed for the local personal flight conducted under 14 CFR Part 91 which departed the Blairstown Airport (1N7), Blairstown, New Jersey.

According to the pilot, the purpose of the flight was to fly the "governor's cup north course" as part of a competition between regional glider pilots.

After approximately 2.5 hours of gliding, while heading towards Middletown, New York, the pilot stated that thermal lift began to decrease, and he decided to divert to the Wurtsboro-Sullivan County Airport (N82), Wurtsboro, New York. About 4.1 nautical miles from the airport, his glide computer indicated an estimated arrival altitude of 350 feet agl. However, over the next mile, lift continued to be lost, and the glider descended about 300 feet, which forced the pilot to find a off airport location to land.

The pilot chose to land in a hay field bordered by trees. He set up a right hand traffic pattern, and when he made a right turn from the base leg of his traffic pattern to the final leg, his "airspeed was low" and the glider "stalled and nosed down."

A post accident examination of the glider by a Federal Aviation Administration inspector, revealed that the glider had sustained substantial damage, and that the fuselage, was bent 90 degrees and exhibited multiple cracks and tears in the composite material.

The pilot reported no mechanical deficiencies with the glider.

A weather observation taken at the Orange County Airport (MGJ), Montgomery, New York, approximately 10 miles from the accident site, at 1654, recorded the winds as variable at 3 knots, 10 statute miles visibility, and clear skies below 12,000 feet.

Page 3 of 6 IAD05CA081

Pilot Information

Certificate:	Private	Age:	61,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	February 1, 2005
Flight Time:	1166 hours (Total, all aircraft), 326 hours (Total, this make and model), 1131 hours (Pilot In Command, all aircraft), 51 hours (Last 90 days, all aircraft), 21 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

PZL Swidnik	Registration:	N341PW
PW-5	Aircraft Category:	Glider
	Amateur Built:	
Utility	Serial Number:	1712023
Unknown	Seats:	1
May 1, 2005 Annual	Certified Max Gross Wt.:	660 lbs
80 Hrs	Engines:	0
360 Hrs as of last inspection	Engine Manufacturer:	
Installed, activated, did not aid in locating accident	Engine Model/Series:	
On file	Rated Power:	
On file	Operating Certificate(s) Held:	None
	PW-5 Utility Unknown May 1, 2005 Annual 80 Hrs 360 Hrs as of last inspection Installed, activated, did not aid in locating accident On file	PW-5 Aircraft Category: Amateur Built: Utility Serial Number: Unknown Seats: May 1, 2005 Annual Certified Max Gross Wt.: 80 Hrs Bengines: 360 Hrs as of last inspection Installed, activated, did not aid in locating accident On file Rated Power: On file Operating Certificate(s)

Page 4 of 6 IAD05CA081

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MGJ,365 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	16:54 Local	Direction from Accident Site:	135°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots / 0 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.14 inches Hg	Temperature/Dew Point:	24°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Blairstown, NJ (1N7)	Type of Flight Plan Filed:	None
Destination:	(1N7)	Type of Clearance:	None
Departure Time:	13:47 Local	Type of Airspace:	

Airport Information

Airport:	Wurtsboro County Airport N82	Runway Surface Type:	Grass/turf
Airport Elevation:	560 ft msl	Runway Surface Condition:	Dry
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	1100 ft / 110 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	41.52639,-74.478889

Page 5 of 6 IAD05CA081

Administrative Information

Investigator In Charge (IIC):	Gunther, Todd
Additional Participating Persons:	Mike Mahan; Albany, NY
Original Publish Date:	October 27, 2005
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=61766

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 IAD05CA081