



Aviation Investigation Final Report

Location: San Andreas, California Accident Number: LAX05CA287

Date & Time: September 1, 2005, 16:15 Local Registration: N1644M

Aircraft: Cessna A185E Aircraft Damage: Substantial

Defining Event: 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The airplane encountered a dust devil during the takeoff ground roll, then it veered off the runway, and collided with a berm. About 600 feet into the takeoff ground roll the airplane veered to the left and continued in that direction even with the pilot's counteractive control input. During the event, the pilot reduced the power, the right main landing gear sheared off, and the airplane came to rest on the right wing and horizontal stabilizer. Witnesses informed the pilot that they observed a dust devil approach the airplane during takeoff roll. The pilot reported experiencing no anomalies with the airframe or engine prior to the event.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's failure to maintain directional control of the airplane upon encountering a dust devil during the takeoff roll.

Findings

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH WEATHER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. WEATHER CONDITION - DUST DEVIL/WHIRLWIND

.

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

3. TERRAIN CONDITION - BERM

Page 2 of 6 LAX05CA287

Factual Information

On September 1, 2005 at 1615 Pacific daylight time, a Cessna A185E airplane, N1644M, was substantially damaged when it impacted terrain during the takeoff roll at the Calaveras County Airport, San Andreas, California. The private pilot and three passengers were not injured. The pilot operated the airplane under the provisions of 14 CFR Part 91 as a personal flight. Visual meteorological conditions prevailed and a flight plan had not been filed for the local flight. The flight was departing at the time of the accident.

According to the pilot's written statement, the airplane was 600 feet down the 3,603-foot-runway (runway 31) when the airplane encountered a dust devil. The airplane veered to the left, and the pilot added full right rudder to counteract the left movement. The airplane was thrust left and upward onto the left wing. The pilot reduced power and then the right main landing gear impacted an earthen berm and sheared the landing gear. The airplane came to rest on the right wing, engine cowling, and right horizontal stabilizer (all of which were structurally damage).

Witnesses approached the pilot following the accident and informed him they observed a dust devil approach the airplane during the takeoff roll. The pilot indicated that there were no anomalies with the airframe or the engine prior to the event.

The pilot reported accumulating a total of 1,200 hours of flight time, of which 300 hours were accumulated in the same make and model as the accident airplane.

Pilot Information

Certificate:	Private	Age:	39,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3	Last FAA Medical Exam:	September 1, 2003
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1200 hours (Total, all aircraft), 300 hours (Total, this make and model), 5 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Page 3 of 6 LAX05CA287

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N1644M
Model/Series:	A185E	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18501847
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:		Engine Model/Series:	IO-520D
Registered Owner:	Skyline Holdings, Inc.	Rated Power:	
Operator:	Casey M. Long	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	SCK	Distance from Accident Site:	
Observation Time:	16:55 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	33°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	San Andreas, CA (CPU)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	16:15 Local	Type of Airspace:	

Page 4 of 6 LAX05CA287

Airport Information

Airport:	Calaveras County CPU	Runway Surface Type:	Asphalt
Airport Elevation:	1320 ft msl	Runway Surface Condition:	Dry
Runway Used:	31	IFR Approach:	None
Runway Length/Width:	3603 ft / 60 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	4 None	Latitude, Longitude:	38.14611,-120.648056

Page 5 of 6 LAX05CA287

Administrative Information

Investigator In Charge (IIC):	Charnon, Nicole
Additional Participating Persons:	Federal Aviation Administration; Oakland, CA
Original Publish Date:	December 20, 2005
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=62397

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX05CA287