



# Aviation Investigation Final Report

---

|                                |   |                         |             |
|--------------------------------|---|-------------------------|-------------|
| <b>Location:</b>               | Newberg, Oregon                           | <b>Accident Number:</b> | SEA06LA005  |
| <b>Date &amp; Time:</b>        | October 15, 2005, 12:37 Local             | <b>Registration:</b>    | N23887      |
| <b>Aircraft:</b>               | Piper PA-38-112                           | <b>Aircraft Damage:</b> | Substantial |
| <b>Defining Event:</b>         |   | <b>Injuries:</b>        | 2 Serious   |
| <b>Flight Conducted Under:</b> | Part 91: General aviation - Instructional |                         |             |

---

## Analysis

The flight instructor reported that he and the student picked the day to practice crosswind landings. The flight instructor recalled a successful run up and departure. The next thing the flight instructor recalled was the student telling him to "take the airplane." The instructor does not recall anything after that. The student pilot reported that the flight stayed in the traffic pattern. One successful touch-and-go was accomplished followed by a go-around. The student pilot stated that during the climb out after the go-around, he turned the aircraft to cross-wind. During the turn toward downwind, the engine lost power. The student stated that he kept control of the airplane while the instructor went through a trouble shoot/restart sequence. The student then turned the airplane over to the flight instructor. The student does not recall anything after that point. Witnesses reported that the aircraft had been doing touch-and-go landings on runway 17. The aircraft was observed to pass over a building near the runway, pitch up and make a hard banking turn to the left before stalling and colliding with the building's parking lot. Another witness stated that after the accident, he heard the right seat occupant state, "sorry I just lost it." The aircraft collided with several objects before coming to rest about 55 yards from the initial ground impact. The nearest weather reporting facility was reporting a wind from 150 degrees at 19 knots at the time of the accident. No mechanical failure or malfunction was noted during the post-accident airframe and engine examination. Damage signatures found on the airplane's propeller were consistent with the engine producing power at the time of impact.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight instructor's failure to maintain airspeed while on approach for landing resulting in an inadvertent stall. Wind gusts, trees and an undetermined loss of engine power were factors.

## Findings

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: APPROACH - VFR PATTERN - DOWNWIND

Findings

1. (F) REASON FOR OCCURRENCE UNDETERMINED

-----

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

2. (F) WEATHER CONDITION - GUSTS

3. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND(CFI)

4. STALL - INADVERTENT - PILOT IN COMMAND

-----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

5. TERRAIN CONDITION - GROUND

-----

Occurrence #4: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING

Findings

6. (F) OBJECT - TREE(S)

## Factual Information

On October 15, 2005, about 1237 Pacific daylight time, a Piper PA-38-112, N23887, registered to and operated by Sportsman Airpark Inc., as a 14 CFR Part 91 instructional flight, collided with the terrain while maneuvering for landing at Sportsman Airpark, Newberg, Oregon. Visual meteorological conditions prevailed at the time and no flight plan was filed for the local flight. The aircraft was substantially damaged and the flight instructor and student pilot were seriously injured.

In a written statement, the flight instructor reported that he and the student picked the day to practice landings in the wind. The flight instructor recalls a successful run up and departure. The next thing the flight instructor recalls is the student telling him to "take the airplane." The instructor does not recall anything after this.

In a written statement, the student pilot reported that the purpose of the flight was to practice crosswind landings. The flight stayed in the traffic pattern. One successful touch-and-go was accomplished followed by a go-around. The student pilot stated that during the climb out after the go-around, he turned the aircraft to cross-wind. During the turn toward downwind, the engine quit. The student stated that he kept control of the airplane while the instructor went through a trouble shoot/restart sequence. The student then turned the airplane over to the flight instructor. The student does not recall anything after this point.

Witnesses reported that the aircraft had been doing touch-and-go landings to runway 17. The aircraft was observed to pass over a building near the runway, pitch up and appeared to make a hard banking turn to the left before stalling and colliding with the building's parking lot. The aircraft collided with several objects before coming to rest about 55 yards from the initial ground impact. The witnesses reported that the wind was from the south at approximately 15 knots plus, with gusts. Another witness stated that it appeared that the "aircraft was fighting the wind by yawing hard back and forth combined with a hard roll to starboard as it disappeared below the building..." This witness went to the accident site and stated that he heard the right seat occupant state, "Sorry, I just lost it."

The nearest weather reporting facility located in McMinnville, Oregon, approximately 10 nautical miles to the south was reporting a wind from 150 degrees at 19 knots at the time of the accident.

An airframe and engine inspection/teardown was accomplished on October 17, 2005, by the Federal Aviation Administration and investigators from The New Piper Aircraft and Textron Lycoming.

During the airframe inspection, it was noted that the left wing skins were separated from the

main spar. The inboard rear wing walk section remained in-place. About three and-a-half feet inboard of the wing tip, the leading edge displayed a circular impact deformation. The fuel tank was destroyed. The aileron was attached, but displayed impact damage. The balance weight remained attached. The bell crank separated and both aileron cables remained attached to the bell crank. Control continuity was established to the aileron torque tube assembly. The flap remained attached to the hinges. The flap rod was bent and separated at the flap attachment point and displayed impact damage.

The right wing skins separated from the main spar. The inboard rear walk section remained in-place. About three and-a-half feet inboard from the wing tip the leading edge displayed a circular impact deformation. The fuel tank was destroyed. The aileron was attached to the outboard section of the wing and was separated from the inboard wing at the inboard hinge. The bell crank was separated from its attachment point and one cable remained attached. Control continuity was established to the aileron torque tube assembly. The flap remained attached at the hinges. The flap rod was bent and separated at the flap attachment point and displayed impact damage.

The empennage remained attached to the fuselage. The rudder, vertical fin and stabilator remained attached. Rudder continuity was established from the rudder to the rudder pedals. The right tip of the stabilator displayed impact damage. Stabilator continuity was established from the stabilator forward to the control column.

The engine remained attached to the airframe at the firewall and displayed impact damage. The firewall and engine mounts were damaged. The carburetor heat cable was separated by impact damage. The carburetor was removed and disassembled. Blue colored fuel remained in the fuel bowl. The carburetor floats remained intact. The carburetor inlet screen was clear of contaminants. The engine driven fuel pump was disassembled and the diaphragm was intact. Manual crankshaft rotation was obtained and accessory gearing and valve train continuity was established. Suction and compression was noted to all cylinders. The spark plugs displayed normal operating signatures. Both magnetos produced a spark during rotation.

The propeller separated from the crankshaft flange and the flange was bent aft on one side. The blades displayed chord wise scratches and impact damage from about mid-span to the tip. One blade remained straight, while the other blade's outboard section displayed a tight 360 degree twist.

## Flight instructor Information

|                                  |  |  |                 |
|----------------------------------|--|--|-----------------|
| <b>Certificate:</b>              | Commercial; Flight instructor  | <b>Age:</b>                              | 46, Male        |
| <b>Airplane Rating(s):</b>       | Single-engine land; Multi-engine land  | <b>Seat Occupied:</b>                    | Right           |
| <b>Other Aircraft Rating(s):</b> | None   | <b>Restraint Used:</b>                   |                 |
| <b>Instrument Rating(s):</b>     | Airplane   | <b>Second Pilot Present:</b>             | Yes             |
| <b>Instructor Rating(s):</b>     | Airplane multi-engine; Airplane single-engine  | <b>Toxicology Performed:</b>             | No              |
| <b>Medical Certification:</b>    | Class 2  | <b>Last FAA Medical Exam:</b>            | April 1, 2005   |
| <b>Occupational Pilot:</b>       | No   | <b>Last Flight Review or Equivalent:</b> | October 1, 2003 |
| <b>Flight Time:</b>              | 1280 hours (Total, all aircraft), 56 hours (Total, this make and model), 1086 hours (Pilot In Command, all aircraft), 89 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft) |  |                 |

## Student pilot Information

|                                  |  |  |     |
|----------------------------------|--|--|-----|
| <b>Certificate:</b>              |  | <b>Age:</b>                              |     |
| <b>Airplane Rating(s):</b>       |  | <b>Seat Occupied:</b>                    |     |
| <b>Other Aircraft Rating(s):</b> |  | <b>Restraint Used:</b>                   |     |
| <b>Instrument Rating(s):</b>     |  | <b>Second Pilot Present:</b>             | Yes |
| <b>Instructor Rating(s):</b>     |  | <b>Toxicology Performed:</b>             | No  |
| <b>Medical Certification:</b>    |  | <b>Last FAA Medical Exam:</b>            |     |
| <b>Occupational Pilot:</b>       |  | <b>Last Flight Review or Equivalent:</b> |     |
| <b>Flight Time:</b>              |  |  |     |

## Aircraft and Owner/Operator Information

|                                      |  |                                       |                 |
|--------------------------------------|--|---------------------------------------|-----------------|
| <b>Aircraft Make:</b>                | Piper  | <b>Registration:</b>                  | N23887          |
| <b>Model/Series:</b>                 | PA-38-112  | <b>Aircraft Category:</b>             | Airplane        |
| <b>Year of Manufacture:</b>          |  | <b>Amateur Built:</b>                 |                 |
| <b>Airworthiness Certificate:</b>    | Normal   | <b>Serial Number:</b>                 | 38-79A1062      |
| <b>Landing Gear Type:</b>            | Tricycle   | <b>Seats:</b>                         | 2               |
| <b>Date/Type of Last Inspection:</b> | September 1, 2005 Annual                               | <b>Certified Max Gross Wt.:</b>       | 1670 lbs        |
| <b>Time Since Last Inspection:</b>   | 7 Hrs  | <b>Engines:</b>                       | 1 Reciprocating |
| <b>Airframe Total Time:</b>          | 5216 Hrs at time of accident                           | <b>Engine Manufacturer:</b>           | Lycoming        |
| <b>ELT:</b>                          | Installed, activated, did not aid in locating accident | <b>Engine Model/Series:</b>           | O-235-L2        |
| <b>Registered Owner:</b>             | Sportsman Airpark                                      | <b>Rated Power:</b>                   | 112 Horsepower  |
| <b>Operator:</b>                     |  | <b>Operating Certificate(s) Held:</b> | None            |

## Meteorological Information and Flight Plan

|   |                                  |   |                   |
|---|----------------------------------|---|-------------------|
| <b>Conditions at Accident Site:</b>     | Visual (VMC)                     | <b>Condition of Light:</b>                  | Day               |
| <b>Observation Facility, Elevation:</b> | MMV,214 ft msl                   | <b>Distance from Accident Site:</b>         | 22 Nautical Miles |
| <b>Observation Time:</b>                | 11:53 Local                      | <b>Direction from Accident Site:</b>        | 180°              |
| <b>Lowest Cloud Condition:</b>          |                                  | <b>Visibility</b>                           | 10 miles          |
| <b>Lowest Ceiling:</b>                  | Overcast / 2100 ft AGL           | <b>Visibility (RVR):</b>                    |                   |
| <b>Wind Speed/Gusts:</b>                | 19 knots /                       | <b>Turbulence Type Forecast/Actual:</b>     | /                 |
| <b>Wind Direction:</b>                  | 150°                             | <b>Turbulence Severity Forecast/Actual:</b> | /                 |
| <b>Altimeter Setting:</b>               | 29.81 inches Hg                  | <b>Temperature/Dew Point:</b>               | 16°C / 11°C       |
| <b>Precipitation and Obscuration:</b>   | No Obscuration; No Precipitation |   |                   |
| <b>Departure Point:</b>                 | Newberg, OR (2S6 )               | <b>Type of Flight Plan Filed:</b>           | None              |
| <b>Destination:</b>                     |                                  | <b>Type of Clearance:</b>                   | None              |
| <b>Departure Time:</b>                  |                                  | <b>Type of Airspace:</b>                    |                   |

## Airport Information

|                             |                       |                                  |                 |
|-----------------------------|-----------------------|----------------------------------|-----------------|
| <b>Airport:</b>             | Sportsman Airpark 2S6 | <b>Runway Surface Type:</b>      | Asphalt         |
| <b>Airport Elevation:</b>   | 178 ft msl            | <b>Runway Surface Condition:</b> | Dry             |
| <b>Runway Used:</b>         | 17                    | <b>IFR Approach:</b>             | None            |
| <b>Runway Length/Width:</b> | 2745 ft / 50 ft       | <b>VFR Approach/Landing:</b>     | Traffic pattern |

## Wreckage and Impact Information

|                            |           |                             |                       |
|----------------------------|-----------|-----------------------------|-----------------------|
| <b>Crew Injuries:</b>      | 2 Serious | <b>Aircraft Damage:</b>     | Substantial           |
| <b>Passenger Injuries:</b> |           | <b>Aircraft Fire:</b>       | None                  |
| <b>Ground Injuries:</b>    | N/A       | <b>Aircraft Explosion:</b>  | None                  |
| <b>Total Injuries:</b>     | 2 Serious | <b>Latitude, Longitude:</b> | 45.283332,-122.951942 |

## Administrative Information

|  |   |
|--|---|
| <b>Investigator In Charge (IIC):</b>     | Eckrote, Debra  |
| <b>Additional Participating Persons:</b> | Erik Ramseyer; FAA/FSDO; Hillsboro, OR<br>Gregory Erikson; Textron Lycoming; Wayne, IL<br>Charles R Little; New Piper Aircraft; Chino Hills, CA |
| <b>Original Publish Date:</b>            | May 30, 2006  |
| <b>Last Revision Date:</b>               |   |
| <b>Investigation Class:</b>              | <a href="#">Class</a>   |
| <b>Note:</b>                             |   |
| <b>Investigation Docket:</b>             | <a href="https://data.nts.gov/Docket?ProjectID=62669">https://data.nts.gov/Docket?ProjectID=62669</a>   |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).