



# **Aviation Investigation Final Report**

Location:	Jasper, Alabama	Accident Number:	ATL06CA026
Date & Time:	December 22, 2005, 13:19 Local	<b>Registration:</b>	N350ET
Aircraft:	Eurocopter France AS-350-B2	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Serious, 1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

# Analysis

The pilot was in cruise flight at 400 feet AGL looking for a bridge that crossed a river. The pilot stated that he did not maintain a visual look out and was not familiar with the area. Examination of the accident site revealed the helicopter collided with an overhead ground wire near Black Water Creek in-between Alabama Power Structure 51 and 52. The pilot stated that he maintained control of the helicopter, and flew the helicopter to his house and landed. Examination of the helicopter revealed it received structural damage to the nose, windscreen, lower chin bubble, overhead window, left door post and cabin roof. The pilot called an employee on a cell phone. The employee met him at his house after landing the helicopter and transported the pilot to a local area hospital. The pilot's right middle finger was amputated due to injuries sustained during the wire strike. The passenger was not injured. The pilot stated the helicopter did not have any mechanical problems before the in-flight collision with the power lines.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain a visual look out, and proper altitude clearance during a low level flight, resulting in an in-flight collision with a power line.

### **Findings**

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: CRUISE

Findings

- 1. OBJECT WIRE, TRANSMISSION
- 2. (C) ALTITUDE/CLEARANCE NOT MAINTAINED PILOT IN COMMAND 3. (C) VISUAL LOOKOUT NOT MAINTAINED PILOT IN COMMAND

### **Factual Information**

The pilot was in cruise flight at 400 feet AGL looking for a bridge that crossed a river. The pilot stated he did not maintain a visual look out and was not familiar with the area. Examination of the accident site revealed the helicopter collided with an overhead ground wire near Black Water Creek in-between Alabama Power Structure 51 and 52. Title 14 CFR Part 91.119, Section (b) and (c) states, over sparsely populated areas, no aircraft may be operated closer than 500 feet to any structure. Helicopters may be operated at less than the minimums prescribed if the operation is conducted without hazards to persons or property on the surface. The pilot stated he maintained control of the helicopter, and flew the helicopter to his house and landed. Examination of the helicopter revealed it received structural damage to the nose, windscreen, lower chin bubble, overhead window, left door post and cabin roof. The pilot called an employee on a cell phone. The employee met him at his house after landing the helicopter and transported the pilot to a local area hospital. The pilot's right middle finger was amputated due to injuries sustained during the wire strike. The passenger was not injured. The pilot stated the helicopter did not have any mechanical problems before the in-flight collision with the power lines.

Certificate:	Private	Age:	55,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	August 1, 2005
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 1, 2004
Flight Time:	5600 hours (Total, all aircraft), 500 hours (Total, this make and model)		

#### **Pilot Information**

### Aircraft and Owner/Operator Information

Aircraft Make:	Eurocopter France	Registration:	N350ET
Model/Series:	AS-350-B2	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3068
Landing Gear Type:	Skid	Seats:	6
Date/Type of Last Inspection:	January 1, 2005 Annual	Certified Max Gross Wt.:	49600 lbs
Time Since Last Inspection:		Engines:	1 Turbo shaft
Airframe Total Time:	1360 Hrs at time of accident	Engine Manufacturer:	Turbomeca
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	ARREL 1SER
Registered Owner:	Sunshine Air Inc.	Rated Power:	
Operator:	Robert L. Banks	Operating Certificate(s) Held:	None

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	BHM,644 ft msl	Distance from Accident Site:	45 Nautical Miles
Observation Time:	13:53 Local	Direction from Accident Site:	140°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.29 inches Hg	Temperature/Dew Point:	8°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Double Springs, AL (3M2 )	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:51 Local	Type of Airspace:	

### Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 None	Latitude, Longitude:	33.884998,-87.197219

### **Administrative Information**

Investigator In Charge (IIC):	Smith, Carrol
Additional Participating Persons:	David W Hargett; Birmingham FSDO-09; Birmingham, AL
Original Publish Date:	March 28, 2006
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=62982

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.