



Aviation Investigation Final Report

Location:	Haines, Alaska	Accident Number:	ANC06LA044
Date & Time:	April 6, 2006, 15:50 Local	Registration:	N209CH
Aircraft:	Aerospatiale AS-350BA	Aircraft Damage:	Substantial
Defining Event:		Injuries:	3 None
Flight Conducted Under:	Part 135: Air taxi & commuter - Non-scheduled		

Analysis

The airline transport certificated pilot was landing a helicopter in an area of grass near the beach of an island on a CFR Part 135 air taxi flight. The pilot indicated that he was focused on a log as a reference point, when just before touchdown, the main rotor blades struck a tree. The operator's director of operations indicated that the rotor blades could not be repaired at his facility, and were being sent to the blade manufacturer's repair facility.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain adequate clearance from an object while landing a helicopter at a remote site, which resulted in the main rotor blades striking a tree.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT
Phase of Operation: LANDING

Findings

1. OBJECT - TREE(S)
2. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

On April 6, 2006, about 1550 Alaska daylight time, an Aerospatiale AS-350BA helicopter, N209CH, sustained substantial damage when its main rotor blades struck trees during landing on Talsani Island, located in the Lynn Canal, about 13 miles east-southeast of Haines, Alaska. The helicopter was being operated as a visual flight rules (VFR) local area on-demand air taxi flight under Title 14, CFR Part 135, when the accident occurred. The helicopter was operated by Coastal Helicopters Inc., Juneau, Alaska. The airline transport certificated pilot, and the two passengers, were not injured. Visual meteorological conditions prevailed, and VFR company flight following procedures were in effect. The flight originated from a nearby landing area about 1545.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge (IIC), on April 7, the director of operations for the operator reported that the pilot was landing in an area of grass near the beach. According to the director of operations, the pilot indicated he was focused on a log he was using as a reference point, when just before touchdown, the main rotor blades struck a tree. The director of operations indicated that the rotor blades could not be repaired at his facility, and were being sent to the blade manufacturer's repair facility.

Pilot Information

Certificate:	Airline transport; Commercial; Flight engineer	Age:	59, Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	December 1, 2005
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	May 1, 2005
Flight Time:	18227 hours (Total, all aircraft), 396 hours (Total, this make and model), 4860 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Aerospatiale	Registration:	N209CH
Model/Series:	AS-350BA	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2494
Landing Gear Type:	Emergency float; High skid	Seats:	7
Date/Type of Last Inspection:	February 1, 2006 AAIP	Certified Max Gross Wt.:	4630 lbs
Time Since Last Inspection:	21 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	16927 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	75-101-600A3
Registered Owner:	Coastal Helicopters Inc.	Rated Power:	650 Horsepower
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	XCHA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Thin Overcast / 1500 ft AGL	Visibility	5 miles
Lowest Ceiling:	Overcast / 2000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	7°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Haines, AK	Type of Flight Plan Filed:	Company VFR
Destination:		Type of Clearance:	None
Departure Time:	15:45 Local	Type of Airspace:	

Airport Information

Airport:	Runway Surface Type:
Airport Elevation:	Runway Surface Condition:
Runway Used:	IFR Approach: None
Runway Length/Width:	VFR Approach/Landing: Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	59.074443,-135.273605

Administrative Information

Investigator In Charge (IIC):	Erickson, Scott
Additional Participating Persons:	Larry West; FAA-AL-JNU FSDO 05; Juneau, AK
Original Publish Date:	October 31, 2006
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=63465

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).