



Aviation Investigation Final Report

Location:	Modesto, California	Accident Number:	LAX06LA229
Date & Time:	July 11, 2006, 11:33 Local	Registration:	N992PC
Aircraft:	Velocity 173/RG-XL	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The landing gear collapsed during a touch-and-go landing. The pilot/builder explained that the airplane ballooned after initial touchdown due to too much elevator trim. The airplane then landed "very hard" farther down the runway. The landing gear collapsed, and the rudders sustained substantial damage after contacting the runway. The pilot/builder conducted maintenance on his airplane, and believed that he had set the landing gear extension/retraction cables too tight. Coupled with the hard landing, this caused the main gear over-center linkage to release from the over-center position.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's misjudged flare and improper recovery from a bounced landing, which resulted in a hard landing and landing gear collapse. A contributing factor was the pilot/builder's inadequate adjustment of the landing gear cable tension.

Findings

Occurrence #1: HARD LANDING
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) FLARE - MISJUDGED - PILOT IN COMMAND
2. (C) RECOVERY FROM BOUNCED LANDING - INADEQUATE - PILOT IN COMMAND

Occurrence #2: COMPLETE GEAR COLLAPSED
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. (F) LANDING GEAR, GEAR LOCKING MECHANISM - UNLOCKED
4. (F) MAINTENANCE, SERVICE OF AIRCRAFT/EQUIPMENT - INADEQUATE - OWNER/PILOT MECHANIC
5. LANDING GEAR - COLLAPSED

Factual Information

On July 11, 2006, about 1133 Pacific daylight time, an experimental Velocity 173/RG-XL, N992PC, had a landing gear collapse during a hard landing at Modesto City Airport, Modesto, California. The pilot/owner/builder was operating the airplane under the provisions of 14 CFR Part 91. The private pilot, the sole occupant, was not injured; the airplane sustained substantial damage. The local personal flight departed Modesto about 1125. Visual meteorological conditions prevailed, and no flight plan had been filed.

The pilot planned to do a touch-and-go landing on 28L. He stated that the airplane ballooned after initial touchdown due to too much elevator trim. It began to fly again at approximately 57 miles per hour, which was under the stall speed of 63 miles per hour. The airplane then landed "very hard" farther down the runway. The gear collapsed; the rudders contacted the runway, and sustained substantial damage.

The pilot reported that the airplane had a total airframe time of 89 hours. It had an annual inspection on November 15, 2005, 9 hours prior to the accident. He said that a hydraulic actuator drives a set of cables, which move the landing gear extension/retraction mechanism. The cables attach to the main gear struts. The cables provide the force to extend the locking mechanism to the over-center position. The pilot/builder does the maintenance on the airplane, and had adjusted the cable tension several times. He surmised that he had the landing gear cables set too tight. Coupled with the hard landing, he felt that this caused the main gear over-center linkage to release from the over-center position.

Pilot Information

Certificate:	Private	Age:	67, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 1, 2005
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1140 hours (Total, all aircraft), 89 hours (Total, this make and model), 1039 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Velocity	Registration:	N992PC
Model/Series:	173/RG-XL	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	3RX045
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	November 1, 2005 Annual	Certified Max Gross Wt.:	2700 lbs
Time Since Last Inspection:	9 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	89 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-540-C
Registered Owner:	On file	Rated Power:	260 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MOD,97 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	10:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	320°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	31°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Modesto, CA (MOD)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	11:25 Local	Type of Airspace:	

Airport Information

Airport:	Modesto City MOD	Runway Surface Type:	Asphalt
Airport Elevation:	97 ft msl	Runway Surface Condition:	Dry
Runway Used:	28L	IFR Approach:	None
Runway Length/Width:	3459 ft / 100 ft	VFR Approach/Landing:	Touch and go

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.631942,-120.957496

Administrative Information

Investigator In Charge (IIC):	Plagens, Howard
Additional Participating Persons:	Jim Henry; Federal Aviation Administration ; Fresno, CA
Original Publish Date:	November 29, 2007
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=64118

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).