



Aviation Investigation Final Report

Location: MARION, South Carolina Accident Number: ATL84LA094

Date & Time: February 10, 1984, 11:50 Local Registration: N34CN

Aircraft: BEECH F33A Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE PLT STATED HE WAS INVOLVED IN A DISCUSSION WITH THE COMPANY PRESIDENT, WHO WAS ON BOARD, DURING THE LANDING APCH AND HE FAILED TO USE THE CHECKLIST. THE ACFT WAS LANDED GEAR UP. IT WAS LATER DETERMINED THE GEAR UP WARNING HORN WAS INOP.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) CHECKLIST - NOT USED - PILOT IN COMMAND

2. (F) DIVERTED ATTENTION - PILOT IN COMMAND

3. (C) GEAR EXTENSION - NOT PERFORMED - PILOT IN COMMAND

4. LANDING GEAR, GEAR WARNING SYSTEM - INOPERATIVE

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	43,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 15, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	13060 hours (Total, all aircraft), 1202 hours (Total, this make and model), 12700 hours (Pilot In Command, all aircraft), 400 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ATL84LA094

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N34CN
Model/Series:	F33A F33A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	CE-743
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:	6 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1630 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	10-520
Registered Owner:	EASTERN AGRI BROKERS, INC.	Rated Power:	300 Horsepower
Operator:	STEVE MATTHEWS	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FLO ,147 ft msl	Distance from Accident Site:	16 Nautical Miles
Observation Time:	11:55 Local	Direction from Accident Site:	275°
Lowest Cloud Condition:	Scattered / 8000 ft AGL	Visibility	5 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	18°C / 7°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	WILSON , NC (WD3	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Page 3 of 5 ATL84LA094

Airport Information

Airport:	MARION COUNTY MAO	Runway Surface Type:	Asphalt
Airport Elevation:	93 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	4500 ft / 100 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	34.169029,-79.400756(est)

Page 4 of 5 ATL84LA094

Administrative Information

Investigator In Charge (IIC): Drake, John

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=6412

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ATL84LA094