



# Aviation Investigation Final Report

---

<b>Location:</b>	Lincoln, Nebraska	<b>Accident Number:</b>	CHI06CA169
<b>Date &amp; Time:</b>	June 26, 2006, 16:12 Local	<b>Registration:</b>	N983T
<b>Aircraft:</b>	Beech 35-33	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Serious, 1 Minor, 2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Instructional		

---

## Analysis

The airplane was substantially damaged during a forced landing following a loss of engine power on final approach. The pilot and one passenger were uninjured. The flight instructor sustained minor injuries. A second passenger sustained serious injuries. The instrument instructional flight departed about 1300. The accident occurred at 1612 while the airplane was on final approach to intended destination airport. The pilot stated that the flight proceeded normally with a deviation due to an active Military Operations Area (MOA) en route. He noted that winds aloft were about 10 knots from 9 to 10 o'clock relative to the direct flight route. The winds were estimated to add 10 to 15 minutes to the flight time. On final approach, about 1-1/2 miles from the runway, the "engine died with no warning." The pilot noted that the fuel selector was set to the right main tank at the time of the loss of power. The crew subsequently switched to the left tank and activated the auxiliary fuel pump in an unsuccessful effort to restore engine power. A post accident inspection recovered one quart of fuel from the right main fuel tank and 3-1/2 gallons from the left main fuel tank. The fuel tanks did not appear to have been compromised during the accident sequence. The pilot stated that the flight departed with the main tanks topped off, 44 gallons useable, and the auxiliary fuel tanks empty. The flight plan filed with the Federal Aviation Administration showed an estimated time en route of 3 hours and total fuel on-board of 4 hours and 30 minutes. The flight prior to the accident flight was over the same course, except in the opposite direction. According to information provided by the pilot and the fixed base operator at the departure airport, the prior flight lasted approximately 2 hours and 40 minutes. The airplane was fueled with 41 gallons. Performance data provided by the manufacturer indicated that the expected fuel burn at 7,000 feet pressure altitude was: 12.9 gallons-per-hour (gph) at 75-percent power; 11.5 gph at 65-percent power, and 9.8 gph at 55-percent power. The prior owner of the accident aircraft stated he normally planned a fuel burn of 14 gph when he flew the airplane.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A loss of engine power due to fuel exhaustion as a result of inaccurate fuel consumption calculations and inadequate monitoring of the remaining fuel quantity en route. A contributing factor was the inadequate supervision of the instructional flight by the flight instructor.

### Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: APPROACH

#### Findings

1. (C) FLUID,FUEL - EXHAUSTION
2. (C) FUEL CONSUMPTION CALCULATIONS - INACCURATE - FLIGHTCREW
3. (C) IN-FLIGHT PLANNING/DECISION - INADEQUATE - FLIGHTCREW
4. (F) SUPERVISION - INADEQUATE - PILOT IN COMMAND(CFI)

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

-----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: EMERGENCY LANDING

#### Findings

5. TERRAIN CONDITION - GROUND

## Factual Information

The airplane was substantially damaged during a forced landing following a loss of engine power on final approach. The pilot and one passenger were uninjured. The flight instructor sustained minor injuries. A second passenger sustained serious injuries. The instrument instructional flight departed Tradewind Airport (TDW), Amarillo, Texas, about 1300. The accident occurred at 1612 while the airplane was on final approach to Lincoln Municipal Airport (LNK), Lincoln, Nebraska.

The pilot stated that the flight proceeded normally direct to LNK with a deviation due to an active Military Operations Area (MOA) en route. He noted that winds aloft were about 10 knots, from 9 to 10 o'clock relative to the direct flight route. The winds were estimated to add 10 to 15 minutes to the flight time. On final approach at LNK, about 1-1/2 miles from the runway, the "engine died with no warning." The pilot noted that the fuel selector was set to the right main tank at the time of the loss of power. The crew subsequently switched to the left tank and activated the auxiliary fuel pump in an unsuccessful effort to restore engine power.

A post accident inspection recovered one quart of fuel from the right main fuel tank and 3-1/2 gallons from the left main fuel tank. The fuel tanks did not appear to have been compromised during the accident sequence.

The pilot stated that the flight departed with the main tanks topped off and the auxiliary fuel tanks empty. Fuel capacity of both main tanks was 50 gallons total, of which 44 gallons were useable. The flight plan filed with the Federal Aviation Administration showed an estimated time en route of 3 hours and total fuel on-board of 4 hours and 30 minutes.

The flight prior to the accident flight was from LNK to TDW. The accident flight was the return flight. According to information provided by the pilot and the fixed base operator at TDW, the flight from LNK to TDW lasted approximately 2 hours and 40 minutes. The airplane was fueled with 41 gallons at TDW.

Performance data provided by the manufacturer indicated that the expected fuel burn at 7,000 feet pressure altitude was: 12.9 gallons-per-hour (gph) at 75-percent power; 11.5 gph at 65-percent power, and 9.8 gph at 55-percent power. The prior owner of the accident aircraft stated he normally planned a fuel burn of 14 gph when he flew the airplane.

## Flight instructor Information

<b>Certificate:</b>	Commercial; Flight instructor	<b>Age:</b>	71, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	January 1, 2006
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	March 1, 2005
<b>Flight Time:</b>	3333 hours (Total, all aircraft), 374 hours (Total, this make and model), 2964 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	41, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	December 1, 2005
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	December 1, 2005
<b>Flight Time:</b>	82 hours (Total, all aircraft), 10 hours (Total, this make and model), 30 hours (Pilot In Command, all aircraft), 16 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Beech	<b>Registration:</b>	N983T
<b>Model/Series:</b>	35-33	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	CD-190
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	August 1, 2005 Annual	<b>Certified Max Gross Wt.:</b>	2900 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	5177 Hrs at time of accident	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	IO-470-J
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	225 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	LNK,1201 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	15:54 Local	<b>Direction from Accident Site:</b>	360°
<b>Lowest Cloud Condition:</b>	Few / 7000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	12 knots / 20 knots	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	10°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.12 inches Hg	<b>Temperature/Dew Point:</b>	27°C / 9°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Amarillo, TX (TDW )	<b>Type of Flight Plan Filed:</b>	IFR
<b>Destination:</b>	Lincoln, NE (LNK )	<b>Type of Clearance:</b>	IFR
<b>Departure Time:</b>	13:00 Local	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Lincoln Muni LNK	<b>Runway Surface Type:</b>	Asphalt;Concrete
<b>Airport Elevation:</b>	1219 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	35	<b>IFR Approach:</b>	Visual
<b>Runway Length/Width:</b>	5400 ft / 100 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor, 1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Serious, 1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious, 1 Minor, 2 None	<b>Latitude, Longitude:</b>	40.851112,-96.759445

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Sorensen, Timothy
<b>Additional Participating Persons:</b>	Russell Timmerman; FAA-Lincoln FSDO
<b>Original Publish Date:</b>	October 3, 2006
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	This accident report documents the factual circumstances of this accident as described to the NTSB.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=64206">https://data.nts.gov/Docket?ProjectID=64206</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).