



Aviation Investigation Final Report

Location: ROCKINGHAM, North Carolina Accident Number: ATL84LA113

Date & Time: March 4, 1984, 16:30 Local Registration: N92792

Aircraft: PIPER PA-12 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

N92792 WAS BEING TAXIED FROM A TIE DOWN AREA WHEN THE PROP STRUCK THE RIGHT WING ON AN UNOCCUPIED B-35, N8813A. THE PLT STATED THE BRAKES FAILED AS HE WAS ATTEMPTING TO TAXI BETWEEN TWO ROWS OF PARKED ACFT AND DIRECTIONAL CONTROL WAS LOST.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. LANDING GEAR, NORMAL BRAKE SYSTEM - FAILURE, TOTAL

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI - TO TAKEOFF

Findings
3. OBJECT - AIRCRAFT PARKED/STANDING

Page 2 of 5 ATL84LA113

Factual Information

Pilot Information

Certificate:	Private	Age:	56,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 4, 1978
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1170 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N92792
Model/Series:	PA-12 PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12-238
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	March 12, 1984 Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:	70 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	11 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-235-C
Registered Owner:	A. C. FARMER	Rated Power:	100 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ATL84LA113

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	15 miles
Lowest Ceiling:	Broken / 3000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	26 inches Hg	Temperature/Dew Point:	11°C / -4°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	16:30 Local	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:
Airport Elevation:		Runway Surface Condition:
Runway Used:	0	IFR Approach:
Runway Length/Width:		VFR Approach/Landing:

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.929878,-79.759956(est)

Page 4 of 5 ATL84LA113

Administrative Information

Investigator In Charge (IIC):	Golden, Jay
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=6421

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ATL84LA113