



Aviation Investigation Final Report

Location: CHARLESTON, South Carolina Accident Number: ATL84LA152

Date & Time: April 25, 1984, 14:37 Local Registration: N85052

Aircraft: BEECH E55 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

AFTER THE LANDING THE ACFT LANDING GEAR RETRACTED DURING A PERIOD OF MAXIMUM BRAKING TO AVOID AN ARRESTING CABLE. DURING THE EXAMINATION OF THE LANDING GEAR DOOR DAMAGE IT WAS DETERMINED THAT THE LANDING GEAR WAS RETRACTED DURING THE LANDING ROLL.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: COMPLETE GEAR COLLAPSED

Phase of Operation: LANDING - ROLL

Findings

1. (C) GEAR RETRACTION - INADVERTENT - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	68,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	November 14, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	18560 hours (Total, all aircraft), 100 hours (Total, this make and model), 18560 hours (Pilot In Command, all aircraft), 35 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N85052
Model/Series:	E55 E55	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	TE-1095
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	October 12, 1983 Annual	Certified Max Gross Wt.:	5300 lbs
Time Since Last Inspection:	60 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	736 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	IO-520-C
Registered Owner:	JOHN E. BLACKWELL	Rated Power:	285 Horsepower
Operator:	HENRY J. WURSTER	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 ATL84LA152

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CHS,45 ft msl	Distance from Accident Site:	
Observation Time:	14:51 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	29°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	JOHN ISLAND , SC (JZI)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	00:00 Local	Type of Airspace:	Class E

Airport Information

Airport:	CHARLESTON AFB CHS	Runway Surface Type:	Concrete
Airport Elevation:	45 ft msl	Runway Surface Condition:	Dry
Runway Used:	33	IFR Approach:	None
Runway Length/Width:	9001 ft / 200 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	32.899295,-80.060066(est)

Page 3 of 4 ATL84LA152

Administrative Information

Investigator In Charge (IIC):	Drake, John
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=6443

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ATL84LA152