



Aviation Investigation Final Report

Location:	Annapolis, Maryland	Accident Number:	NYC07CA004
Date & Time:	October 6, 2006, 15:45 Local	Registration:	N600U
Aircraft:	Beech BE-58	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot of the Beech BE-58 was attempting to land on runway 12, a 2,500-foot-long, 48-foot-wide, asphalt runway. The pilot reported that the airplane touched down with about 2,000 feet of runway remaining; however, he was not able to stop the airplane before it departed the end of the runway, and struck a pole. A witness reported that heavy rain was falling at the time of the accident, and he could see the airplane hydroplaning along the runway surface. Winds reported about 5 miles northeast of the accident site, about the time of the accident, were from 40 degrees at 11 knots, with 29 knot gusts. Review of an airport facility directory for the airport revealed that runway 12 was noted as "extremely slippery when wet."

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's improper in-flight decision to attempt to land on the wet runway, which resulted in an overrun. Factors in the accident were rain, and the gusty wind conditions.

Findings

Occurrence #1: OVERRUN
Phase of Operation: LANDING

Findings

1. (F) WEATHER CONDITION - RAIN
2. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

3. (F) WEATHER CONDITION - GUSTS

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING

Findings

4. OBJECT - POLE

Factual Information

The pilot of the Beech BE-58 was attempting to land on runway 12, a 2,500-foot-long, 48-foot-wide, asphalt runway. The pilot reported that the airplane touched down with about 2,000 feet of runway remaining; however, he was not able to stop the airplane before it departed the end of the runway, and struck a pole. A witness reported that heavy rain was falling at the time of the accident, and he could see the airplane hydroplaning along the runway surface. Winds reported about 5 miles northeast of the accident site, about the time of the accident, were from 40 degrees at 11 knots, with 29 knot gusts. Review of an airport facility directory for the airport revealed that runway 12 was noted as "extremely slippery when wet."

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	37, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	September 1, 2006
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	December 1, 2005
Flight Time:	1754 hours (Total, all aircraft), 53 hours (Total, this make and model), 1636 hours (Pilot In Command, all aircraft), 70 hours (Last 90 days, all aircraft), 38 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N600U
Model/Series:	BE-58	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	TH-1524
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	5500 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	5113 Hrs at time of accident	Engine Manufacturer:	Teledyne Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-550
Registered Owner:	Epps Air Service, Inc.	Rated Power:	300 Horsepower
Operator:	EPPS AIR SERVICE INC	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	ESMA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	NAK	Distance from Accident Site:	5 Nautical Miles
Observation Time:	15:54 Local	Direction from Accident Site:	45°
Lowest Cloud Condition:		Visibility	8 miles
Lowest Ceiling:	Broken / 1900 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	11 knots / 18 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	40°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.27 inches Hg	Temperature/Dew Point:	12°C / 12°C
Precipitation and Obscuration:	N/A - None - Rain		
Departure Point:	Atlanta, GA (PDK)	Type of Flight Plan Filed:	IFR
Destination:	Annapolis, MD (ANP)	Type of Clearance:	IFR
Departure Time:	12:30 Local	Type of Airspace:	

Airport Information

Airport:	LEE ANP	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Wet
Runway Used:	12	IFR Approach:	None
Runway Length/Width:	2500 ft / 48 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	38.942779,-76.568336

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke
Additional Participating Persons:	John Cumberpatch; FAA Baltimore FSDO ; Baltimore, MD
Original Publish Date:	January 31, 2007
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=64667

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).