



Aviation Investigation Final Report

Location:	New Braunfels, Texas	Accident Number:	DFW07CA015
Date & Time:	October 26, 2006, 17:00 Local	Registration:	N32CX
Aircraft:	Maule M5	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The private pilot was returning to the airport in the tail-wheeled airplane. He reported that he executed a normal approach to runway 17 for a full-stop landing. He stated that the wind at the time of the landing was reported as 250 degrees at 8 knots. During the landing roll, the airplane drifted to the left side of the runway. He stated that he made a "slight correction with right rudder," but the airplane's right wing "continued down and the aircraft [began] to turn hard right." He attempted to regain directional control by adding power, but the right main landing gear collapsed, and the right wing and the propeller contacted the ground. The airplane ground looped which, resulted in structural damage to the right wing. Examination of the landing gear by an aircraft mechanic revealed that the right landing gear strut attachment point was corroded and cracked.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the right main landing gear attachment during the landing roll, which resulted in a ground loop. A contributing factor was a crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR,MAIN GEAR ATTACHMENT - CORRODED
2. (C) LANDING GEAR,MAIN GEAR ATTACHMENT - DETERIORATED
3. (F) WEATHER CONDITION - CROSSWIND
4. DIRECTIONAL CONTROL - NOT POSSIBLE - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: LANDING - ROLL

Findings

5. TERRAIN CONDITION - GROUND

Factual Information

The 512-hour private pilot had just completed a practice flight consisting of slow flight, stalls, and steep turns, and was returning to the airport in the tail-wheeled airplane. The pilot reported that he executed a normal approach to runway 17, (a dry asphalt 5,354-foot long by 100-foot wide runway), which consisted of a 65-mph approach with the flaps extended to the 20-degree position for a planned full-stop landing. Additionally, the pilot reported that the wind at the time of the landing was being reported from 250 degrees at 8 knots. During the landing roll, the airplane drifted to the left side of the runway. The pilot stated that he made a "slight correction with right rudder," but the airplane's right wing "continued down and the aircraft [began] to turn hard right." The pilot attempted to regain directional control by adding power; however, the right main landing gear collapsed and the right wing and the propeller contacted the ground. The airplane ground looped which resulted in structural damage to the right wing. The pilot, who was uninjured, reported that he had accumulated a total of 4-hours in this make and model. Examination of the landing gear by an aircraft mechanic revealed that the right landing gear strut attachment point was corroded and cracked. A search of the SDR database, failed to return another report of a failed attachment point.

Pilot Information

Certificate:	Private	Age:	49, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	December 1, 2004
Occupational Pilot:	No	Last Flight Review or Equivalent:	October 1, 2006
Flight Time:	512 hours (Total, all aircraft), 4 hours (Total, this make and model), 453 hours (Pilot In Command, all aircraft), 26 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Maule	Registration:	N32CX
Model/Series:	M5	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7034C
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:	November 1, 2005 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1904 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-540
Registered Owner:	On file	Rated Power:	235 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KBAZ	Distance from Accident Site:	
Observation Time:	16:51 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 8000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.73 inches Hg	Temperature/Dew Point:	31°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	New Braunfels, TX (3R5)	Type of Flight Plan Filed:	None
Destination:	New Braunfels, TX	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	NEW BRAUNFELS MUNI 3R5	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	5364 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Hatch, Craig
Additional Participating Persons:	Jessie Sanchez; San Antonio, Texas
Original Publish Date:	March 26, 2007
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=64779

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).