



Aviation Investigation Final Report

Location:	Mineral Wells, Texas	Accident Number:	DFW07CA050
Date & Time:	December 30, 2006, 12:30 Local	Registration:	N9655F
Aircraft:	Hughes 269C	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

The 22-hour helicopter student pilot lost control of the single-engine helicopter while performing a hovering maneuver during a solo training flight. The pilot added that while hovering at a skid height of 10-feet above the ground, the helicopter encountered a phenomena known as loss of tail rotor effectiveness (LTE). The helicopter entered an uncontrolled hard spin to the right. The pilot responded by lowering the collective and the helicopter landed hard. The helicopter sustained structural damage to the right strut, the tail rotor drive shafts, and the right horizontal stabilizer. The pilot egressed from the helicopter normally and sustained no injuries. The winds at the time of the mishap were reported from 210 degrees at 6 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of control as result of loss of tail rotor effectiveness.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: HOVER - OUT OF GROUND EFFECT

Findings

1. (C) LOSS OF TAIL ROTOR EFFECTIVENESS - ENCOUNTERED - PILOT IN COMMAND

Occurrence #2: HARD LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

2. TERRAIN CONDITION - GROUND

Factual Information

The 22-hour helicopter student pilot lost control of the single-engine helicopter while performing a hovering maneuver during a solo training flight. The pilot added that while hovering at a skid height of 10-feet above the ground, the helicopter encountered a phenomena known as loss of tail rotor effectiveness (LTE). The helicopter entered an uncontrolled hard spin to the right. The pilot responded by lowering the collective and the helicopter landed hard. The helicopter sustained structural damage to the right strut, the tail rotor drive shafts, and the right horizontal stabilizer. The pilot egressed from the helicopter normally and sustained no injuries. The winds at the time of the mishap were reported from 210 degrees at 6 knots.

Pilot Information

Certificate:	Private	Age:	53, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	March 1, 2006
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	180 hours (Total, all aircraft), 22 hours (Total, this make and model), 22 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hughes	Registration:	N9655F
Model/Series:	269C	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	Unknown
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	100 hour	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	8500 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	H10 360A
Registered Owner:	Mark and Connie Taylor	Rated Power:	
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMWL	Distance from Accident Site:	
Observation Time:	12:30 Local	Direction from Accident Site:	
Lowest Cloud Condition:	2800 ft AGL	Visibility	10 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	6 knots / 0 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.95 inches Hg	Temperature/Dew Point:	16°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Mineral Wells, TX (KMWL)	Type of Flight Plan Filed:	None
Destination:	Mineral Wells, TX (KMWL)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Mineral Wells KMWL	Runway Surface Type:	
Airport Elevation:	972 ft msl	Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Gamble, William
Additional Participating Persons:	Peter W Kwaak; FTW
Original Publish Date:	March 26, 2007
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=65100

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).