

Aviation Investigation Final Report

Location: Cheyboygan, Michigan Accident Number: CHI07CA044

Date & Time: December 20, 2006, 10:15 Local Registration: N5811D

Aircraft: Piper PA-22-150 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The airplane encountered soft terrain during an off airport forced landing following a loss of engine power. The pilot reported that while climbing, shortly after takeoff, he switched from the left fuel tank to the right fuel tank. He stated that approximately three minutes later the engine lost power. The pilot stated he switched back to the left fuel tank, checked the magnetos, and switched on the carburetor heat, but was unable to regain power. He reported he made a turn back toward the airport to land. The airplane touched down in soft terrain approximately 300 feet short of the approach end of runway. The airport manager stated the airplane bounced, weathervaned and landed sideways which resulted in the right main gear collapsing and the nose gear buckling. The right wing and propeller contacted the ground as the airplane slid. Post accident inspection of the airplane and engine failed to reveal any mechanical failure/malfunction which would have resulted in the loss of engine power.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A loss of engine power for undetermined reasons. A factor was the soft terrain encountered during the lanidng.

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: CRUISE - NORMAL

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

2. TERRAIN CONDITION - GROUND

3. (F) TERRAIN CONDITION - SOFT

Page 2 of 6 CHI07CA044

Factual Information

The airplane encountered soft terrain during an off airport forced landing following a loss of engine power. The pilot reported that while climbing, shortly after takeoff, he switched from the left fuel tank to the right fuel tank. He stated that approximately three minutes later the engine lost power. The pilot stated he switched back to the left fuel tank, checked the magnetos, and switched on the carburetor heat, but was unable to regain power. He reported he made a turn back toward the airport to land. The airplane touched down in soft terrain approximately 300 feet short of the approach end of runway. The airport manager stated the airplane bounced, weathervaned and landed sideways which resulted in the right main gear collapsing and the nose gear buckling. The right wing and propeller contacted the ground as the airplane slid. Post accident inspection of the airplane and engine by inspectors from the Federal Aviation Administration, Grand Rapids, Michigan Flight Standards District Office failed to reveal any mechanical failure/malfunction which would have resulted in the loss of engine power.

Pilot Information

Certificate:	Commercial	Age:	58,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3	Last FAA Medical Exam:	April 1, 2006
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1306 hours (Total, all aircraft), 34 hours (Total, this make and model), 6 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft)		

Page 3 of 6 CHI07CA044

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N5811D
Model/Series:	PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	252-4486
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	0-320
Registered Owner:	Gregg H. Dickerson	Rated Power:	
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Cheboygan, MI (SLH)	Type of Flight Plan Filed:	None
Destination:	Pointe Aux Pins, MI (6YI)	Type of Clearance:	None
Departure Time:	10:05 Local	Type of Airspace:	

Page 4 of 6 CHI07CA044

Airport Information

Airport:	Cheboygan County SLH	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	09	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	2 None	Latitude, Longitude:	45.531944,-84.308052

Page 5 of 6 CHI07CA044

Administrative Information

Investigator In Charge (IIC):	Sullivan, Pamela
Additional Participating Persons:	John Parrish; Grand Rapids, MI FSDO
Original Publish Date:	March 26, 2007
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=65165

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.

Page 6 of 6 CHI07CA044