



# Aviation Investigation Final Report

---

<b>Location:</b>	Clinton, Oklahoma	<b>Accident Number:</b>	DFW07LA108
<b>Date &amp; Time:</b>	May 11, 2007, 12:50 Local	<b>Registration:</b>	N4413Q
<b>Aircraft:</b>	Cessna A188A	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Serious
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

---

## Analysis

As the agricultural pilot was pulling up from a low level pass, he smelled something "like wires burning" and observed the engine's fuel pressure drop. The pilot selected the auxiliary fuel pump's "EMERGENCY" position and five to ten seconds later the engine lost partial power. Not able to maintain altitude, the pilot elected to land the airplane to a rolling wheat field. During landing, the airplane nosed over and came to rest in an inverted position. An examination of the airplane revealed that, prior to impact, the engine exhaust stack had separated from the muffler. Hot exhaust gasses, that are normally vented overboard, were directed to the airplanes firewall, resulting in thermal damaged to electrical wiring and a vapor condition in the fuel gascolator. The pilot attempted to purge the vapor to no avail. No other pre impact anomalies were noted with the engine or the fuel system that would have prevented normal operating power.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Separation of the exhaust stack and resulting vapor lock. A contributing factor was the none suitable terrain for the forced landing.

## Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION  
Phase of Operation: MANEUVERING - AERIAL APPLICATION

### Findings

1. (C) EXHAUST SYSTEM,STACK - FAILURE  
-----

Occurrence #2: LOSS OF ENGINE POWER(PARTIAL) - NONMECHANICAL  
Phase of Operation: MANEUVERING

### Findings

2. (C) FLUID,FUEL - VAPOR LOCK  
-----

Occurrence #3: FORCED LANDING  
Phase of Operation: EMERGENCY DESCENT/LANDING  
-----

Occurrence #4: NOSE OVER  
Phase of Operation: EMERGENCY DESCENT/LANDING

### Findings

3. (F) TERRAIN CONDITION - NONE SUITABLE

## Factual Information

On May 11, 2007, about 1250 central daylight time, a single-engine Cessna A188A airplane, N4413Q, was substantially damaged during a forced landing following a partial loss of engine power near Clinton, Oklahoma. The airline transport pilot, the sole occupant, sustained serious injuries. The airplane was registered to and operated by the pilot. Visual meteorological conditions prevailed and a flight plan was not filed for the 14 Code of Federal Regulations part 137 aerial application flight. The local flight originated from Clinton Regional Airport (CLK), Clinton, Oklahoma at 1157.

According to the pilot, age 35, as he was pulling up from a low level pass, he smelled something "like wires burning" and observed the engine's fuel pressure drop to approximately six gallons per hour (GPH). The pilot selected the auxiliary fuel pump's "EMERGENCY" position which resulted in an increase in fuel pressure to about 22 GPH. Approximately five to ten seconds later the engine's fuel pressure again dropped to approximately six gallons per hour. Not able to maintain altitude, the pilot elected to land the airplane to a rolling wheat field. Prior to landing, the pilot shut off the engine magnetos and master switch. During landing, the airplane nosed over and came to rest in an inverted position. A post impact fire did not occur.

A Federal Aviation Administration (FAA) inspector responded to the accident site. According to the inspector, the airplane sustained substantial damage to the vertical stabilizer and both wings. The inspector further reported that aviation fuel was found in the airplane's main fuel tanks and in the engine's fuel manifold.

The NTSB investigator-in-charge (IIC) and a representative from Teledyne Continental Motors examined the airplane following its recovery. The examination revealed that prior to impact, the engine exhaust stack had separated from the muffler. The electrical wiring attached to the firewall in the area behind the muffler was found thermally damaged. The fuel gascolator was also attached to the firewall in this area. No other pre impact anomalies were noted with the engine or the fuel system that would have prevented normal operating power.

According to the Cessna Agwagon Owners Manual dated 1970/71, page 2-12, "...if fuel vapor is affecting engine operation, the vapor may be purged by placing the switch in the "EMERGENCY" position while leaning the mixture as required to prevent excessively rich mixture. Successful vapor purging is evidenced by smooth engine operation and steady and normal fuel flow indications with the auxiliary fuel pump switch "OFF.""

## Pilot Information

<b>Certificate:</b>	Airline transport; Flight instructor	<b>Age:</b>	35, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Single
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	March 1, 2007
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	September 1, 2006
<b>Flight Time:</b>	7230 hours (Total, all aircraft), 650 hours (Total, this make and model), 6050 hours (Pilot In Command, all aircraft), 105 hours (Last 90 days, all aircraft), 73 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N4413Q
<b>Model/Series:</b>	A188A	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Restricted (Special)	<b>Serial Number:</b>	18800813
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	1
<b>Date/Type of Last Inspection:</b>	March 1, 2007 Annual	<b>Certified Max Gross Wt.:</b>	4000 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	5678 Hrs at time of accident	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	IO-520-D
<b>Registered Owner:</b>	Chad Wright	<b>Rated Power:</b>	300 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>	Wright Air, Inc.	<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	CLK,1615 ft msl	<b>Distance from Accident Site:</b>	3 Nautical Miles
<b>Observation Time:</b>	11:55 Local	<b>Direction from Accident Site:</b>	350°
<b>Lowest Cloud Condition:</b>	Scattered / 3900 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 7000 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	20°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.11 inches Hg	<b>Temperature/Dew Point:</b>	23°C / 18°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Clinton , OK (CLK )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	11:57 Local	<b>Type of Airspace:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious	<b>Latitude, Longitude:</b>	35.536666,-98.913887

## Administrative Information

**Investigator In Charge (IIC):** LeBaron, Timothy

**Additional Participating Persons:** Mike Boler; Federal Aviation Administration; Oklahoma City, OK  
John Kent; Teledyne Continental Motors; Mobile, AL

**Original Publish Date:** April 30, 2008

**Last Revision Date:**

**Investigation Class:** [Class](#)

**Note:**

**Investigation Docket:** <https://data.ntsb.gov/Docket?ProjectID=65762>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).