





Aviation Investigation Final Report

Location: Spartanburg, South Carolina Accident Number: SEA07CA136

Date & Time: May 26, 2007, 19:45 Local Registration: N613KF

Aircraft: Lidgard 4-1200 Aircraft Damage: Substantial

Defining Event: 2 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot stated that during takeoff, approximately 500 feet down the runway surface, the tailwheel-equipped airplane veered right. Although the pilot attempted to stop the airplane, it continued 250 feet until impacting a fence. The pilot stated that the majority of his time was in tricycle gear airplanes and he had about 3 hours in the accident airplane. He said that there were no mechanical malfunctions with the airplane.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot lost directional control of the airplane during takeoff. A contributing factor was the pilot's lack of experience in the accident airplane make/model.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

2. (F) LACK OF FAMILIARITY WITH AIRCRAFT - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAKEOFF - ROLL/RUN

Findings
3. OBJECT - FENCE

Page 2 of 6 SEA07CA136

Factual Information

The pilot stated that during takeoff, approximately 500 feet down the runway surface, the tailwheel-equipped airplane veered right. Although the pilot attempted to stop the airplane, it continued 250 feet until impacting a fence. The pilot stated that the majority of his time was in tricycle gear airplanes and he had about 3 hours in the accident airplane. He said that there were no mechanical malfunctions with the airplane.

Pilot Information

| Certificate: | Private | Age: | 50,Male |
|---------------------------|---|-----------------------------------|--------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | |
| Instructor Rating(s): | | Toxicology Performed: | No |
| Medical Certification: | Class 3 | Last FAA Medical Exam: | June 1, 2006 |
| Occupational Pilot: | | Last Flight Review or Equivalent: | |
| Flight Time: | 340 hours (Total, all aircraft), 3 hours (Total, this make and model), 5 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft) | | |

Page 3 of 6 SEA07CA136

Aircraft and Owner/Operator Information

| Aircraft Make: | Lidgard | Registration: | N613KF |
|----------------------------------|------------------------|-----------------------------------|-----------------|
| Model/Series: | 4-1200 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | Yes |
| Airworthiness Certificate: | Experimental (Special) | Serial Number: | 1764 |
| Landing Gear Type: | Tailwheel | Seats: | |
| Date/Type of Last Inspection: | | Certified Max Gross Wt.: | |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | Subaru |
| ELT: | | Engine Model/Series: | EA-81 |
| Registered Owner: | On File | Rated Power: | |
| Operator: | On File | Operating Certificate(s) Held: | None |
| | | | |

Meteorological Information and Flight Plan

| | orrana riigite ritati | | |
|----------------------------------|------------------------------|--------------------------------------|-------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | GSP,964 ft msl | Distance from Accident Site: | 13 Nautical Miles |
| Observation Time: | 19:53 Local | Direction from Accident Site: | 270° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 4 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 160° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | | Temperature/Dew Point: | 38°C / 26°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | SPA Downtown Me, SC (SPA) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | VFR |
| Departure Time: | | Type of Airspace: | |

Page 4 of 6 SEA07CA136

Airport Information

| Airport: | Spartanburg Downtown Memorial SPA | Runway Surface Type: | Asphalt |
|----------------------|-----------------------------------|---------------------------|---------|
| Airport Elevation: | 801 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 23 | IFR Approach: | None |
| Runway Length/Width: | 5202 ft / 100 ft | VFR Approach/Landing: | None |

Wreckage and Impact Information

| Crew Injuries: | 1 Minor | Aircraft Damage: | Substantial |
|------------------------|---------|-------------------------|---------------------|
| Passenger Injuries: | 1 Minor | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 Minor | Latitude, Longitude: | 34.915554,-81.95639 |

Page 5 of 6 SEA07CA136

Administrative Information

| Investigator In Charge (IIC): | Dunks, Kristi |
|-----------------------------------|---|
| Additional Participating Persons: | Lewis Blackwell; Federal Aviation Administration; Columbia, SC |
| Original Publish Date: | July 25, 2007 |
| Last Revision Date: | |
| Investigation Class: | <u>Class</u> |
| Note: | This accident report documents the factual circumstances of this accident as described to the NTSB. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=65864 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA07CA136