



Aviation Investigation Final Report

Location: Mesa, Arizona Accident Number: LAX08CA011

Date & Time: October 14, 2007, 17:35 Local Registration: N5644N

Aircraft: Maule M-5-235-C Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot stated that he lost control of the airplane on the landing roll when the airplane veered to the left. He attempted to gain control by correcting the left turn with right rudder. The airplane then made an abrupt right turn and the left gear collapsed. After the propeller impacted the runway surface, the airplane came to rest perpendicular to the runway. The pilot said there were no preimpact mechanical malfunctions or failures.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control of the airplane during landing.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

2. (C) GROUND LOOP/SWERVE - NOT CORRECTED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings
3. TERRAIN CONDITION - RUNWAY

Page 2 of 6 LAX08CA011

Factual Information

On October 14, 2007, about 1735 mountain standard time, a Maule, M-5-235-C, N5644N, ground looped during landing at Falcon Field Airport, Mesa, Arizona. Terrane Exploration & Reconnaissance Company LLC was operating the airplane under the provisions of 14 CFR Part 91. The private pilot and a passenger were not injured. The airplane sustained substantial damage. The cross-country flight departed Santa Teresa, New Mexico, about 1510, with a planned destination of Falcon Field. Visual meteorological conditions prevailed, and a VFR flight plan had been filed.

In a written report to the National Transporation Safety Board, the pilot stated he lost control of the airplane on the landing roll when the airplane veered to the left. He attempted to gain control by correcting the left turn with right rudder. The airplane made an abrupt right turn and the left gear collapsed. After the propeller impacted the runway surface, the airplane came to rest perpendicular to the runway. The aircraft also sustained damage to the left wing, left horizontal stabilizer, left window, and muffler. The pilot reported no preimpact mechanical malfunctions or failures with the airframe or engine.

Pilot Information

Certificate:	Private	Age:	53,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	October 1, 2007
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 1, 2006
Flight Time:	411 hours (Total, all aircraft), 346 hours (Total, this make and model), 35 hours (Last 90 days, all aircraft), 34 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

Page 3 of 6 LAX08CA011

Aircraft and Owner/Operator Information

Aircraft Make:	Maule	Registration:	N5644N
Model/Series:	M-5-235-C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7347C
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	June 1, 2007 Annual	Certified Max Gross Wt.:	2500 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1197 Hrs at time of accident	Engine Manufacturer:	Textron Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-540-J1A5D
Registered Owner:	Terrane Exploration & Reconnaissance Co. LLC	Rated Power:	235 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site: Visual (VMC) Condition of Light: Day Observation Facility, Elevation: FFZ,1394 ft msl Distance from Accident Site: 0 Nautical Miles Observation Time: 15:48 Local Direction from Accident Site: Lowest Cloud Condition: Few / 8000 ft AGL Visibility 40 miles Lowest Ceiling: None Visibility (RVR):
Observation Time: 15:48 Local Direction from Accident Site: Lowest Cloud Condition: Few / 8000 ft AGL Visibility 40 miles Lowest Ceiling: None Visibility (RVR):
Lowest Cloud Condition: Few / 8000 ft AGL Visibility 40 miles Lowest Ceiling: None Visibility (RVR):
Lowest Ceiling: None Visibility (RVR):
Wind One of Country
Wind Speed/Gusts: 7 knots / Turbulence Type / Forecast/Actual:
Wind Direction: 250° Turbulence Severity / Forecast/Actual:
Altimeter Setting: 29.84 inches Hg Temperature/Dew Point: 27°C / 2°C
Precipitation and Obscuration: No Obscuration; No Precipitation
Departure Point: Santa Teresa, NM (5T6) Type of Flight Plan Filed: VFR
Destination: Mesa, AZ (FFZ) Type of Clearance: VFR
Departure Time: 15:10 Local Type of Airspace:

Page 4 of 6 LAX08CA011

Airport Information

Airport:	Falcon Field Airport FFZ	Runway Surface Type:	Asphalt
Airport Elevation:	1394 ft msl	Runway Surface Condition:	Dry;Rubber deposits
Runway Used:	22L	IFR Approach:	None
Runway Length/Width:	5101 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 5 of 6 LAX08CA011

Administrative Information

Investigator In Charge (IIC):	Jones, Patrick
Additional Participating Persons:	Michael G Moyer; Federal Aviation Administration; Scottsdale, AZ
Original Publish Date:	December 20, 2007
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=66896

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX08CA011