

Aviation Investigation Final Report

..

MARINE

PAIL POAD

PIPELINE

Location:	Windham, New York	Accident Number:	NYC08CA025
Date & Time:	November 4, 2007, 13:45 Local	Registration:	N46009
Aircraft:	Burkhart Grob G 103 Twin II	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Serious, 1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

Both pilots were alternating flying duties in a Burkhart Grob G 103 Twin II glider. They had been soaring along a ridge for approximately 1 hour in non-turbulent wind. The rear seat pilot was flying on the upwind side of the ridge, about 500 feet above the summit, when a gust of wind suddenly forced the glider to the downwind side of the ridge, about 25 feet below the summit. The glider then impacted trees, sustained substantial damage, and both pilots were seriously injured. The reported wind at an airport about 25 miles northeast of the accident site, about the time of the accident, was 270 degrees at 6 knots. Examination of the glider did not reveal any preimpact mechanical malfunctions, nor did the pilots report any.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: An inadvertent encounter with a wind gust while maneuvering.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: MANEUVERING

Findings 1. WEATHER CONDITION - GUSTS 2. (C) FLIGHT INTO ADVERSE WEATHER - INADVERTENT - PILOT IN COMMAND 3. (C) FLIGHT INTO ADVERSE WEATHER - INADVERTENT - PILOT PASSENGER Occurrence #2: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: DESCENT - UNCONTROLLED

Findings 4. OBJECT - TREE(S)

Factual Information

Both pilots were alternating flying duties in a Burkhart Grob G 103 Twin II glider. They had been soaring along a ridge for approximately 1 hour in non-turbulent wind. The rear seat pilot was flying on the upwind side of the ridge, about 500 feet above the summit, when a gust of wind suddenly forced the glider to the downwind side of the ridge, about 25 feet below the summit. The glider then impacted trees, sustained substantial damage, and both pilots were seriously injured. The reported wind at an airport about 25 miles northeast of the accident site, about the time of the accident, was 270 degrees at 6 knots. Examination of the glider by a Federal Aviation Administration inspector did not reveal any preimpact mechanical malfunctions, nor did the pilots report any.

Pilot Information

Certificate:	Private	Age:	72,Male
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 1, 2007
Flight Time:	1433 hours (Total, all aircraft), 44 hours (Total, this make and model), 70 hours (Pilot In Command, all aircraft), 28 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Co-pilot Information

Certificate: P	Private	Age:	58,Male
Airplane Rating(s): N	None	Seat Occupied:	Rear
Other Aircraft Rating(s): G	Glider	Restraint Used:	
Instrument Rating(s): N	None	Second Pilot Present:	Yes
Instructor Rating(s): N	None	Toxicology Performed:	No
Medical Certification: C	Class 2 With waivers/limitations	Last FAA Medical Exam:	May 1, 2007
Occupational Pilot: U	JNK	Last Flight Review or Equivalent:	
Flight Time: 3	308 hours (Total, all aircraft), 50 hour	s (Total, this make and model)	

Aircraft and Owner/Operator Information

Aircraft Make:	Burkhart Grob	Registration:	N46009
Model/Series:	G 103 Twin II	Aircraft Category:	Glider
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3830
Landing Gear Type:	Ski/wheel	Seats:	2
Date/Type of Last Inspection:		Certified Max Gross Wt.:	1279 lbs
Time Since Last Inspection:		Engines:	0
Airframe Total Time:		Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	Nutmeg Soaring Association	Rated Power:	
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ALB,285 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	13:51 Local	Direction from Accident Site:	30°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	12°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Freehold, NY (115)	Type of Flight Plan Filed:	None
Destination:	(115)	Type of Clearance:	None
Departure Time:	12:30 Local	Type of Airspace:	

Airport Information

Airport:	Freehold Airport 115	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Serious, 1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor	Latitude, Longitude:	42.299999,-74.25

Administrative Information

Investigator In Charge (IIC):	Gretz, Robert
Additional Participating Persons:	Chad Gilbert; FAA/FSDO; Albany, NY
Original Publish Date:	December 20, 2007
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67010

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.