

Aviation Investigation Final Report

Location: Jacksonville, Florida Accident Number: MIA08CA019

Date & Time: November 25, 2007, 16:00 Local Registration: N1055L

Aircraft: Lake LA-4-200 Aircraft Damage: Substantial

Defining Event: 2 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

According to the pilot, the "flight departed VFR from KVQQ at 15:55 for flight to KCRG. After departing Class D airspace to [the] southeast the pilot descended over the St. Johns River approximately 1/2 na[utical] mile offshore to practice reading wind direction from [the] water surface. The winds were very light and [the] water surface [was] mostly glassy. [The] pilot descended from about 2,500 ft. to approximately 100 ft. above [the] water and made several circles to [the] right to view [the] water. [The] pilot then leveled [the] wings and the [air]plane then bounced unexpectedly on the water and made about two more bounces before spinning to the left. [The] aircraft came to a stop and [the] pilot and passenger exited [the] cockpit onto [the] wing and were picked up by a passing motor boat. The plane sank after about 3 minutes." The pilot further stated that "this accident was caused by a glassy water condition and the pilot loosing depth perception. [The] pilot had no intention of landing and was practicing reading water for wind direction where wind was very light or none at all. [The] pilot had been endorsed on September 11, 2007 for SES [Single Engine Sea] practical testing but had not taken [the] check ride."

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain altitude while maneuvering over water. Contributing to the accident was glassy water conditions.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING

Findings

1. (C) TERRAIN CONDITION - WATER, GLASSY
2. (C) ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

Page 2 of 6 MIA08CA019

Factual Information

According to the pilot, the "flight departed VFR from KVQQ at 15:55 for flight to KCRG. After departing Class D airspace to [the] southeast the pilot descended over the St. Johns River approximately 1/2 na[utical] mile offshore to practice reading wind direction from [the] water surface. The winds were very light and [the] water surface [was] mostly glassy. [The] pilot descended from about 2,500 ft. to approximately 100 ft. above [the] water and made several circles to [the] right to view [the] water. [The] pilot then leveled [the] wings and the [air]plane then bounced unexpectedly on the water and made about two more bounces before spinning to the left. [The] aircraft came to a stop and [the] pilot and passenger exited [the] cockpit onto [the] wing and were picked up by a passing motor boat. The plane sank after about 3 minutes." The pilot further stated that "this accident was caused by a glassy water condition and the pilot loosing depth perception. [The] pilot had no intention of landing and was practicing reading water for wind direction where wind was very light or none at all. [The] pilot had been endorsed on September 11, 2007 for SES [Single Engine Sea] practical testing but had not taken [the] check ride."

Pilot Information

Certificate:	Private	Age:	36,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 1, 2006
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 1, 2007
Flight Time:	325 hours (Total, all aircraft), 320 hours (Total, this make and model), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 MIA08CA019

Aircraft and Owner/Operator Information

Aircraft Make:	Lake	Registration:	N1055L
Model/Series:	LA-4-200	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	648
Landing Gear Type:	Tricycle; Amphibian	Seats:	4
Date/Type of Last Inspection:	June 1, 2007 Annual	Certified Max Gross Wt.:	2690 lbs
Time Since Last Inspection:	4.96 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1435.04 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-360-A1B
Registered Owner:	Pavel Budnik	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCRG	Distance from Accident Site:	
Observation Time:	16:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	50°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	21°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	Jacksonville, FL (KVQQ)	Type of Flight Plan Filed:	None
Destination:	Jacksonville, FL (KCRG)	Type of Clearance:	None
Departure Time:	15:55 Local	Type of Airspace:	

Page 4 of 6 MIA08CA019

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	On-ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	30.334999,-81.508613

Page 5 of 6 MIA08CA019

Administrative Information

Investigator In Charge (IIC):	Wilson, Ralph
Additional Participating Persons:	Steve Weaver; Orlando FSDO; Orlando, FL
Original Publish Date:	February 28, 2008
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67152

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 MIA08CA019