



Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-----------------|
| Location: | Oklahoma City, Oklahoma | Accident Number: | DFW08LA055 |
| Date & Time: | January 3, 2008, 02:25 Local | Registration: | N398J |
| Aircraft: | Pilatus PC-12/45 | Aircraft Damage: | None |
| Defining Event: | AC/prop/rotor contact w person | Injuries: | 1 Fatal, 8 None |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

After an uneventful landing at night, the commercial rated pilot taxied the single-engine turbo propeller equipped airplane to a FBO based at the airport. Upon reaching the FBO's dimly lit ramp, a line technician, who was employed by the FBO, used lighted wands to marshal the airplane to a parking spot. When the airplane came to a complete stop, the pilot set the parking brake. As the pilot was initiating the engine shut down procedures, he heard a loud "thud" and felt the engine, propeller, and airplane begin to vibrate. He looked up and saw the line technician rolling on the ramp toward the airplane's left wing tip. Upon exiting the airplane, the pilot and one of the passengers, who was a physician, noted that the line technician was critically wounded and immediately initiated first aid. It was also noted that a set of wheel chocks and the severed sections of the two lighted wands were near the propeller at the front of the airplane. The line technician had received a written warning from his employer approximately three months before the accident for attempting to chock the nose wheel of another airplane while the engines were operating.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The line technician's failure to remain clear of the propeller. A factor was the night lighting conditions.

Findings

Environmental issues

Dark - Not specified

Personnel issues

Identification/recognition - Ground crew

Factual Information

History of Flight

Standing-engine(s) operating AC/prop/rotor contact w person (Defining event)

On January 3, 2008, approximately 0225 central standard time, a Pilatus PC-12/45, N398J, a single-engine turbo-prop airplane, was not damaged when a line technician was struck and killed by its moving propeller while parked at the ramp at Wiley Post Airport, Oklahoma City (PWA), Oklahoma. The commercial pilot and the 7 passengers were not injured. The airplane was operated by and registered to Oklahoma Cardiovascular Associates, Oklahoma City, Oklahoma. An instrument flight rules flight plan was filed for the flight that had departed the Phoenix Sky Harbor International Airport (PHX), Phoenix, Arizona, about 2200. Night visual meteorological conditions prevailed for the cross country flight that was conducted under 14 Code of Federal Regulations Part 91.

According to the Oklahoma City Police Department report, the pilot stated that after landing, he taxied to the fixed base operator (FBO) located at the airport. When he reached the FBO's dimly lit ramp, the line technician used lighted wands to guide the airplane to a parking spot. Once the line technician gave the pilot the "stop" hand signal, the pilot stopped the airplane, set the brake, and began shutting down the engine. The pilot said that when he was about to move the throttle to the fuel-cut-off position, he heard a loud "thud" and the engine, airplane and propeller began to "vibrate badly." He looked up and saw a "rapid movement" out of the corner of his eye to the left of the airplane and realized it was the line attendant tumbling along the ramp surface. The pilot immediately engaged the fuel-cut-off switch, and waited for the propeller to stop turning. At that point, the pilot and a passenger, who was a physician, exited the aircraft and immediately administered first aid to the technician until emergency response personnel arrived.

The police report also reported that a set of wheel chocks, a shoe, and broken pieces of the lighted wands were found near the propeller.

The FBO's third shift supervisor was on the ramp when the accident occurred, but he did not witness the line technician being struck by the propeller. According to the supervisor, he was operating an airplane tug and had last observed the line technician marshalling the airplane. The supervisor had turned away from the airplane when he heard a loud "thud." When he turned around, he saw that the line technician was critically injured and was rolling on the ground toward the airplane's left wing tip.

Although there were seven passengers on board the airplane, none of them witnessed the accident.

A review of training records provided by the FBO revealed that the line technician had successfully completed Professional Line Service Training (PLST) on September 4, 2007. This training included the dangers associated when working around propellers. According to the PLST Training Manual, Section 2.2.5, titled Propeller Danger, it stated, "The propeller blades spin at a high rpm and may present a significant hazard to ramp workers. Line service personnel have been killed by spinning propellers. Because propellers can become invisible when spinning at high revolution, it is easy to become distracted and forget that the aircraft's engine is, indeed, running." In addition, section 2.5 of the manual, titled Aircraft Marshaling and Hand Signals, stated, "...Some additional rules which must be followed when marshaling and parking of all types of aircraft...Propellers and rotors must be completely stopped before positioning the chocks."

Further review of the line technician's training file revealed that he received a Disciplinary Action from his employer on October 11, 2007. The reason for the action was defined as, "[Line technician] chocked the nose wheel of [registration number] (King Air) while the engines were still running. This violates previous training he has received." The Disciplinary Action was signed by the Line Technician, his supervisor, the General Manager of the FBO, and a witness.

As a result of this accident, The FBO issued training Bulletin #08-001, titled Aircraft Propeller Safety, to its 2,600 employees. This purpose of the bulletin was to "Ensure all personnel, who work, provide service or transition near aircraft, recognize the potential danger which exists with aircraft propellers, whether moving or stationary, and always observe propeller safety operating procedures."

Weather reported at Wiley Post Airport at 0253 included wind from 170 degrees at 16 knots, visibility 10 miles, clear skies, and a barometric pressure setting of 30.65 inches of Mercury.

Pilot Information

| | | | |
|----------------------------------|--|--|------------------|
| Certificate: | Commercial | Age: | 59, Male |
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 | Last FAA Medical Exam: | June 1, 2007 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | February 1, 2007 |
| Flight Time: | 10571 hours (Total, all aircraft), 475 hours (Total, this make and model), 17 hours (Last 90 days, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|---------------------------------------|---------------------------------------|------------------------|
| Aircraft Make: | Pilatus | Registration: | N398J |
| Model/Series: | PC-12/45 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 398 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 9 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 9920 lbs |
| Time Since Last Inspection: | | Engines: | 1 Turbo prop |
| Airframe Total Time: | 1871 Hrs | Engine Manufacturer: | Pratt & Whitney Canada |
| ELT: | Installed, not activated | Engine Model/Series: | PT6A-67A |
| Registered Owner: | Oklahoma cardiovascular Associates PC | Rated Power: | 1200 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Night |
| Observation Facility, Elevation: | PWA, 1299 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 02:53 Local | Direction from Accident Site: | 0° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 16 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 170° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.64 inches Hg | Temperature/Dew Point: | |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Phoenix, CA (PHX) | Type of Flight Plan Filed: | IFR |
| Destination: | Oklahoma City, OK (PWA) | Type of Clearance: | None |
| Departure Time: | 22:00 Local | Type of Airspace: | |

Airport Information

| | | | |
|-----------------------------|----------------|----------------------------------|------|
| Airport: | Wiley Post PWA | Runway Surface Type: | |
| Airport Elevation: | 1299 ft msl | Runway Surface Condition: | |
| Runway Used: | | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | None |

Wreckage and Impact Information

| | | | |
|----------------------------|-----------------|-----------------------------|----------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | None |
| Passenger Injuries: | 7 None | Aircraft Fire: | None |
| Ground Injuries: | 1 Fatal | Aircraft Explosion: | None |
| Total Injuries: | 1 Fatal, 8 None | Latitude, Longitude: | 35.533611,-97.641387 |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Yeager, Leah |
| Additional Participating Persons: | Don Cook; FAA/FSDO; Oklahoma City , OK |
| Original Publish Date: | March 31, 2008 |
| Last Revision Date: | |
| Investigation Class: | Class |
| Note: | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=67331 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).