



Aviation Investigation Final Report

Location:	La Porte, Texas	Accident Number:	DEN08LA071
Date & Time:	April 4, 2008, 15:03 Local	Registration:	N40289
Aircraft:	Hiller UH-12E	Aircraft Damage:	Substantial
Defining Event:	Loss of control in flight	Injuries:	1 Minor, 1 None
Flight Conducted Under:	Part 91: General aviation - Flight test		

Analysis

The pilot was test flying the helicopter after maintenance. He did two "quick stop" maneuvers into the wind. After completing the quick stop maneuver, and while in a 5-foot hover, he initiated a slow pedal turn to the left to return to the hangar. As he began the turn, he noticed "a loss of control effectiveness" and he attempted to set the helicopter down. Before he could regain control, the helicopter "slammed" into the ground. The pilot said it had begun to rain, and after he exited the helicopter, he noticed the wind sock had shifted 180 degrees. The tail boom was severed and the main rotor blades were destroyed.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of tail rotor effectiveness. Contributing factors were the sudden windshift to a tailwind, and the pilot initiating a hovering turn in ground effect.

Findings

Environmental issues	Sudden wind shift - Not specified
Environmental issues	Tailwind - Not specified
Personnel issues	Incorrect action performance - Pilot
Environmental issues	Glassy surface - Not specified

Factual Information

History of Flight	
Maneuvering	Other weather encounter
Maneuvering-hover	Loss of control in flight (Defining event)
Uncontrolled descent	Collision with terr/obj (non-CFIT)

On April 4, 2008, at 1503 central daylight time, a Hiller UH-12E, N40289, registered to and operated by Ascent Aviation, was substantially damaged when it struck the ground while maneuvering and rolled over at La Porte Municipal Airport (T14), La Porte, Texas. Visual meteorological conditions prevailed at the time of the accident. The test flight was being conducted under the provisions of Title 14 Code of Federal Regulations (CFR) Part 91 without a flight plan. The airline transport certificated pilot received minor injuries, and his pilot certificated passenger was not injured. The local flight originated at T41 approximately 10 minutes before the accident.

According to the pilot's accident report, he was test flying the helicopter after performing some maintenance that had been requested by its new owner. He performed two "quick stop" maneuvers into the wind. After completing the quick stop maneuver and while in a 5-foot hover, he initiated a slow pedal turn to the left to return to the hangar. As he began the turn, he noticed "a loss of control effectiveness" and he attempted to set the helicopter down. Before he could regain control, the helicopter "slammed" into the ground. The pilot said it had begun to rain and after he exited the helicopter, he noticed the wind sock had shifted 180 degrees. The tail boom was severed and the main rotor blades were destroyed.

Flight instructor Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	52,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Helicopter; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	December 1, 2007
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	May 1, 2007
Flight Time:	20000 hours (Total, all aircraft), 700 hours (Total, this make and model)		

Information

Information			
Certificate:	Private	Age:	49,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2	Last FAA Medical Exam:	December 1, 2007
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 1, 2007
Flight Time:	1200 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hiller	Registration:	N40289
Model/Series:	UH-12E	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	5096
Landing Gear Type:	High skid	Seats:	3
Date/Type of Last Inspection:	January 1, 2008 Annual	Certified Max Gross Wt.:	3 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2216 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	VO-540-C2A
Registered Owner:	Ascent Aviation	Rated Power:	305 Horsepower
Operator:	Paul Legris	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 800 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	13 knots / 21 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	330°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.81 inches Hg	Temperature/Dew Point:	18°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	La Porte, TX (T41)	Type of Flight Plan Filed:	None
Destination:	La Porte, TX (T41)	Type of Clearance:	None
Departure Time:	14:50 Local	Type of Airspace:	

Airport Information

Airport:	La Porte Municipal T41	Runway Surface Type:	Grass/turf
Airport Elevation:	25 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	29.671388,-95.073608

Administrative Information

Investigator In Charge (IIC):	Scott, Arnold
Additional Participating Persons:	David Richardson; Houston, Texas
Original Publish Date:	August 28, 2008
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67780

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.