



# Aviation Investigation Final Report

<b>Location:</b>	Denio, Nevada	<b>Accident Number:</b>	LAX08LA097
<b>Date &amp; Time:</b>	April 11, 2008, 09:00 Local	<b>Registration:</b>	N24SD
<b>Aircraft:</b>	Bell 47G-3B-1	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Miscellaneous/other	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Aerial observation		

## Analysis

After the passenger shot a coyote during the predator control flight, the helicopter pilot circled the injured coyote. While maneuvering at 15 miles per hour and about 20 feet above the hilly terrain, the pilot heard a grinding noise, which he opined originated from the transmission. The pilot believed the helicopter was losing power, and he opted to immediately land on sloping terrain. The helicopter touched down hard, the main rotors severed the tail boom, and the helicopter rolled over. During the subsequent examination of the airframe, transmission, and engine, no evidence of a mechanical malfunction was found. One of the two cooling fan drive belts was not found seated, and may have rolled over on its pulley, producing the noise that the pilot may have misinterpreted as relating to a loss of power.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadvertent hard landing induced by a perceived loss of power and a main transmission anomaly while maneuvering at low altitude.

## Findings

<b>Aircraft</b>	(general) - Not specified
<b>Personnel issues</b>	(general) - Flight crew
<b>Environmental issues</b>	Sloped/uneven terrain - Effect on operation



## Factual Information

### History of Flight

<b>Maneuvering-low-alt flying</b>	Miscellaneous/other (Defining event)
<b>Landing-flare/touchdown</b>	Hard landing
<b>Landing-flare/touchdown</b>	Roll over

On April 11, 2008, about 0900 Pacific daylight time, a Bell 47G-3B-1, N24SD, made a hard landing on hilly terrain about 25 miles south of Denio, Nevada. Following impact, the helicopter's skids collapsed, the main rotor blades severed the tail boom, and the substantially damaged helicopter rolled over. Neither the commercial pilot nor the passenger was injured during the aerial observation flight. The helicopter was operated by Helicopter Roundup Service, LLC, Nephi, Utah. Visual meteorological conditions prevailed at the time, and no flight plan was filed. The flight was performed under the provisions of 14 Code of Federal Regulations Part 91, and it originated from a private ranch near Denio, about 0700.

The pilot reported to the National Transportation Safety Board investigator that the purpose of the flight was predator control, and the passenger-gunman had just shot a coyote. The pilot opined that a mechanical malfunction occurred as he was circling the injured coyote about 20 feet above ground level, and while nearly in a hover.

According to the pilot, while maneuvering he heard a grinding noise emanating from the transmission, which was immediately followed by a loss of power to the main rotors. Prior to hearing the noise, there had not been any problem with the helicopter. The pilot stated that, at the time, the helicopter's airspeed was about 15 miles per hour, and he was unable to perform a successful autorotative descent.

The helicopter was recovered from the accident site and examined by Federal Aviation Administration (FAA) and Bell Helicopter personnel. In pertinent part, the swashplate and centrifugal clutch for the main rotor system showed no indication of failure, the engine and turbocharger rotated freely, the tail rotor drive shaft and tail rotor gear box rotated freely, and no signs of abnormal wear or failure were found. No evidence of any abnormal wear, failure, or anomalies with the transmission was found.

The FAA noted that the only discrepancy that was possibly pertinent to the pilot's report of hearing unusual noise may have related to the fact that one of the helicopter's two cooling fan drive belts was not found seated; although it was found at the accident site. The FAA reported that the belt may have rolled over on its pulley and made a noise that the pilot heard just before it broke.

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	45, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	July 13, 2007
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	August 10, 2007
<b>Flight Time:</b>	4153 hours (Total, all aircraft), 2746 hours (Total, this make and model), 4081 hours (Pilot In Command, all aircraft), 67 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Bell	<b>Registration:</b>	N24SD
<b>Model/Series:</b>	47G-3B-1	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	3671
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	3
<b>Date/Type of Last Inspection:</b>	February 27, 2008 100 hour	<b>Certified Max Gross Wt.:</b>	2950 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	9476 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	TVO-435-B1A
<b>Registered Owner:</b>	Helicopter Roundup Service, LLC	<b>Rated Power:</b>	270 Horsepower
<b>Operator:</b>	Helicopter Roundup Service, LLC	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>		<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>		<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	30 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>		<b>Temperature/Dew Point:</b>	8°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Denio, NV (NONE)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	07:00 Local	<b>Type of Airspace:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	41.049999,-118.333335(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Pollack, Wayne
<b>Additional Participating Persons:</b>	David Butler; Federal Aviation Administration; Reno, NV
<b>Original Publish Date:</b>	May 6, 2009
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=67806">https://data.ntsb.gov/Docket?ProjectID=67806</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).