



Aviation Investigation Final Report

Location:	Kingman, Arizona	Accident Number:	LAX08LA098
Date & Time:	April 11, 2008, 07:30 Local	Registration:	N9022N
Aircraft:	North American T-28C	Aircraft Damage:	Substantial
Defining Event:	Powerplant sys/comp malf/fail	Injuries:	1 Minor, 1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

About 15 minutes after takeoff, during cruise flight, the pilot observed the engine oil pressure drop and the temperature increase, followed by a total loss of engine power. The pilot made an intentional gear-up forced landing on rough terrain. A partial teardown examination of the engine revealed ferrous and non-ferrous metal in the oil screens. The number 3 connecting rod was found bent, and the number 4 and number 5 cylinders were damaged. Numerous pieces of metal were observed in the crankcase that were associated with the number 4 and number 5 cylinders and pistons. The internal engine component that initially broke at the beginning of the sequence was not identified.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A total loss of engine power during cruise flight due to an undetermined catastrophic internal engine failure.

Findings

Aircraft	(general) - Failure
Environmental issues	Rough terrain - Contributed to outcome

Factual Information

History of Flight

Enroute-cruise	Powerplant sys/comp malf/fail (Defining event)
Enroute-cruise	Loss of engine power (total)
Emergency descent	Off-field or emergency landing

On April 11, 2008, about 0730 mountain standard time, an experimental North American T-28C, N9022N, experienced a total loss of engine power while cruising about 5 miles east-southeast of the Kingman Airport, Kingman, Arizona. The pilot made a forced landing on open, rocky, desert terrain, and the airplane was substantially damaged. The private pilot was not injured, and the passenger sustained minor injuries. The airplane was owned and operated by the pilot. Visual meteorological conditions prevailed at the time of the personal flight, and no flight plan was filed. The flight was performed under the provisions of 14 Code of Federal Regulations Part 91, and it originated from Kingman about 0715.

The pilot reported to the National Transportation Safety Board investigator that the engine started running rough while cruising about 5,000 feet mean sea level (about 2,000 feet above ground level). The pilot checked the engine gauges and observed that the oil pressure was decreasing and the oil temperature was "maxing out." According to the pilot, the engine then lost all power and he made an intentional gear up landing because the tricycle gear airplane likely would have nosed over during rollout on the soft terrain. The propeller continued to rotate throughout the mishap. The pilot stated that his airplane's Curtis Wright model 1820-86B engine had been operated about 175 hours since receiving an overhaul.

At the direction of the Safety Board investigator, a Federal Aviation Administration (FAA) airworthiness inspector oversaw an examination of the accident engine. In pertinent part, the FAA inspector reported finding "an excessive amount of ferrous and non-ferrous" material in the oil screens. The number 3 cylinder was removed from the crank case and exhibited a bent connecting rod, along with "major damage to its piston and cylinder skirt." Also, numerous pieces of metal were observed in the crankcase that was associated with the number 4 and number 5 cylinders. The internal engine component that initially broke was not identified.

Pilot Information

Certificate:	Private	Age:	44, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	November 1, 2007
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 26, 2006
Flight Time:	2800 hours (Total, all aircraft), 700 hours (Total, this make and model), 2650 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	North American	Registration:	N9022N
Model/Series:	T-28C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Experimental (Special)	Serial Number:	140666
Landing Gear Type:	Retractable - Tricycle	Seats:	2
Date/Type of Last Inspection:	October 1, 2007 Condition	Certified Max Gross Wt.:	8000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	7000 Hrs as of last inspection	Engine Manufacturer:	Curtis Wright
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	R-1820-86B
Registered Owner:	On file	Rated Power:	1425 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	IGM,3449 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	07:15 Local	Direction from Accident Site:	298°
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Kingman, AZ (IGM)	Type of Flight Plan Filed:	None
Destination:	Kingman, AZ	Type of Clearance:	None
Departure Time:	07:00 Local	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	35.210556,-113.875556(est)

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne
Additional Participating Persons:	Kevin Bender; Federal Aviation Administration; Las Vegas, NV
Original Publish Date:	May 6, 2009
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67807

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).