

Aviation Investigation Final Report

Location: Dansville, New York Accident Number: NYC08LA168

Date & Time: April 19, 2008, 16:00 Local Registration: N90870

Aircraft: LET Blanik L-13 Aircraft Damage: Substantial

Defining Event: Landing area undershoot **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor was conducting a glider familiarization flight with the private pilot, who had not flown in a glider for about 3 years. The private pilot entered the traffic pattern for the grass landing area adjacent to runway 14. The flight instructor stated that the private pilot was "a little reluctant" to remove the dive brakes and that the instructor removed them while on final approach at 600 feet above ground level. He further stated that the glider encountered a wind gradient that substantially reduced the glider's glide ratio. The glider subsequently landed short of the desired touchdown point and the left wing struck a tree. The glider came to rest about 100 feet before the runway. The private pilot stated that she felt the glider was "too high" until she turned onto the final approach path and realized it was actually "too low." Winds reported at the airport about the time of the accident were from 140 degrees at 15 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to attain the proper glide path and the flight instructor's delayed remedial action. Contributing to the accident was the encountered headwind.

Findings

Aircraft Descent/approach/glide path - Not attained/maintained

Personnel issues Aircraft control - Pilot

Personnel issues Delayed action - Instructor/check pilot

Environmental issues (general) - Effect on operation

Page 2 of 7 NYC08LA168

Factual Information

History of Flight

Landing	Landing area undershoot (Defining event)
Landing	Collision during takeoff/land

On April 19, 2008, about 1600 eastern daylight time, a Let Blanik L-13 glider, N90870, was substantially damaged when it impacted terrain while landing at the Dansville Municipal Airport (DSV), Dansville, New York. The certificated flight instructor (CFI) and the certificated private pilot were not injured. Visual meteorological conditions prevailed and no flight plan had been filed for the local instructional flight conducted under 14 Code of Federal Regulations Part 91.

The flight instructor was conducting a familiarization flight with the private pilot, who had not flown in a glider for about 3 years.

According to the CFI, the glider was towed to an altitude of the 2,000 feet and released. The private pilot was flying and subsequently entered the traffic pattern for the grass landing area adjacent to runway 14, a 3,500-foot-long, by 100-foot-wide, asphalt runway. The turn from the base leg to the final approach course was performed at an altitude of approximately 700 feet above ground level (agl). The CFI stated that the private pilot was "a little reluctant" to remove the dive brakes and he removed them at 600 feet agl. He further stated:

"At this point in the flight the runway touchdown point appeared ok, so we continued. As we approached approximately 200 [feet] agl we began to sink, so I was forced to take over the controls. We encountered a wind gradient which substantially reduced the glide ratio of the aircraft, which resulted in landing short of the desired touchdown point. The left-hand wind struck a tree which ground-looped the aircraft and we came to a full stop facing the opposite direction of landing...."

The glider came to rest about 100 feet prior to the runway and sustained substantial damage to its left wing and fuselage.

The private pilot stated that she felt the glider was "too high" until she turned onto the final approach path and realized it was "too low."

The CFI reported 7,679 hours of total flight experience which included 145 hours in gliders. The private pilot reported 300 hours of total flight experience, all in gliders. Neither pilot reported any mechanical malfunctions of the glider during the accident flight.

A weather observation taken at DSV, at 1554, reported: wind from 140 degrees at 15 knots,

Page 3 of 7 NYC08LA168

visibility 10 statute miles, clear skies, temperature 29 degrees Celsius (C), dew point 2 degrees C, altimeter 29.82 inches of mercury.

Flight instructor Information

Certificate:	Airline transport; Commercial	Age:	56,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Glider; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	June 25, 2007
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 10, 2007
Flight Time:	7679 hours (Total, all aircraft), 100 hours (Total, this make and model), 3493 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Private	Age:	61,Female
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	300 hours (Total, all aircraft)		

Page 4 of 7 NYC08LA168

Aircraft and Owner/Operator Information

Aircraft Make:	LET	Registration:	N90870
Model/Series:	Blanik L-13	Aircraft Category:	Glider
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	025801
Landing Gear Type:	Ski/wheel	Seats:	2
Date/Type of Last Inspection:	April 17, 2008 Annual	Certified Max Gross Wt.:	1100 lbs
Time Since Last Inspection:		Engines:	
Airframe Total Time:	2299 Hrs as of last inspection	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	Finger Lakes Soaring Club	Rated Power:	
Operator:	Finger Lakes Soaring Club	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DSV,662 ft msl	Distance from Accident Site:	
Observation Time:	15:54 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.81 inches Hg	Temperature/Dew Point:	29°C / 2°C
Precipitation and Obscuration:			
Departure Point:	Dansville, NY (DSV)	Type of Flight Plan Filed:	None
Destination:	Dansville, NY	Type of Clearance:	None
Departure Time:	15:45 Local	Type of Airspace:	

Page 5 of 7 NYC08LA168

Airport Information

Airport:	Dansville Municipal DSV	Runway Surface Type:	Grass/turf
Airport Elevation:	662 ft msl	Runway Surface Condition:	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	3500 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.570835,-77.712776

Page 6 of 7 NYC08LA168

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke
Additional Participating Persons:	Gustav R Neubauer; FAA/FSDO; Albany, NY
Original Publish Date:	March 5, 2009
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67880

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 7 of 7 NYC08LA168