



# Aviation Investigation Final Report

<b>Location:</b>	Council, Idaho	<b>Accident Number:</b>	SEA08LA114
<b>Date &amp; Time:</b>	April 26, 2008, 16:45 Local	<b>Registration:</b>	N706BC
<b>Aircraft:</b>	Canup Titan Tornado S	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Sys/Comp malf/fail (non-power)	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

While climbing to cruise altitude about five minutes after departure, the outboard four inches of the tip of one propeller blade separated. The pilot was able to reduce power and return to the airport for a successful full-stop landing. Inspection of the experimental-use-only wood pusher propeller revealed that the blade had failed at a point where it had been damaged by a foreign object.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the tip of the wood propeller due to damage caused by a foreign object.

## Findings

<b>Aircraft</b>	Propeller blade section - Damaged/degraded
<b>Environmental issues</b>	Debris/dirt/foreign object - Not specified

## Factual Information

### History of Flight

<b>Enroute-cruise</b>	Sys/Comp malf/fail (non-power) (Defining event)
-----------------------	---

On April 26, 2008, about 1645 mountain daylight time, an experimental Canup Titan Tornado S, N706BC, experienced the separation of a portion of its wood propeller while climbing to cruise altitude about five miles north of Council, Idaho. The private pilot, who was the sole occupant, was not injured, but the airplane sustained substantial damage to the propeller. The 14 CFR Part 91 personal pleasure flight, which departed Council, Idaho, about five minutes prior to the propeller failure, was en route to McCall, Idaho. The airplane was being operated in visual meteorological conditions. No flight plan had been filed.

According to the pilot, while climbing through about 5,500 feet mean sea level (MSL), she heard a loud bang, followed by a severe vibration of the airplane. She immediately turned back toward Council Airport, and after she was sure she had the runway made, reduced power and continued the descent to a successful full-stop landing. After shutting down and inspecting the airplane, the pilot discovered that about four inches of the tip of one propeller blade was missing, and that the other blade was cracked along almost its entire span.

Inspection of the Sensenich experimental-use-only W58DJL-50 wood pusher propeller by a Federal Aviation Administration Airworthiness Inspector revealed that the blade had failed at a point where it had been damaged by a foreign object. Further inspection revealed that at the point of failure there was a sharp-edged indentation about one-half inch long and about one-sixteenth to one-eighth inch deep.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	43, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Front
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	September 1, 2007
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	December 1, 2006
<b>Flight Time:</b>	164 hours (Total, all aircraft), 34 hours (Total, this make and model), 60 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Canup	<b>Registration:</b>	N706BC
<b>Model/Series:</b>	Titan Tornado S	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	SO3J22COHK0453
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	November 1, 2007 Condition	<b>Certified Max Gross Wt.:</b>	1200 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	250 Hrs at time of accident	<b>Engine Manufacturer:</b>	Jabiru
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	2200A
<b>Registered Owner:</b>	Claudia A. Delaney	<b>Rated Power:</b>	85 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>		<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>		<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>		<b>Temperature/Dew Point:</b>	16°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Council, ID (U82 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	McCall, ID (MYL )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	16:40 Local	<b>Type of Airspace:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	44.749721,-116.446945

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Anderson, Orrin
<b>Additional Participating Persons:</b>	Robert Martinez; Federal Aviation Administration; Boise, ID
<b>Original Publish Date:</b>	May 28, 2008
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=67909">https://data.ntsb.gov/Docket?ProjectID=67909</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).