



# Aviation Investigation Final Report

<b>Location:</b>	Flushing, Michigan	<b>Accident Number:</b>	CHI08LA191
<b>Date &amp; Time:</b>	July 15, 2008, 10:08 Local	<b>Registration:</b>	N621CD
<b>Aircraft:</b>	Drochak Aventura II	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	1 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The amateur-built, experimental amphibian airplane had just departed the grass airstrip. About 100 feet above ground level just beyond the departure end of the airstrip, the engine lost power. Seconds later, the airplane impacted a tree and the ground in a left wing down, nose low attitude. Inspection of the propeller revealed no evidence of rotation at the time of impact. The fuel tank contained about 8 gallons of fuel. Flight control continuity was established. The engine rotated and an engine run was conducted and it operated. The inspection of the airframe and fuselage revealed no preexisting anomalies. The reason for the loss of engine power was not determined.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A loss of engine power for undetermined reasons.

## Findings

<b>Not determined</b>	(general) - Unknown/Not determined
<b>Environmental issues</b>	Tree(s) - Contributed to outcome

## Factual Information

### History of Flight

<b>Initial climb</b>	Loss of engine power (total) (Defining event)
<b>Uncontrolled descent</b>	Collision with terr/obj (non-CFIT)

On July 15, 2008, at 1008 eastern daylight time, an amateur-built, experimental Drochak Aventura II amphibian airplane, N621CD, was destroyed when it impacted trees and terrain after a loss of engine power during takeoff climb from Dalton Airport (3DA), Flushing, Michigan. The pilot received fatal injuries. The 14 Code of Federal Regulations Part 91 personal flight was departing from runway 27 on a local flight. Visual meteorological conditions prevailed at the time of the accident. No flight plan was filed.

A witness reported that he saw the airplane heading westbound from the airport at about 100 feet above ground level (agl), and then it entered a left turn to the south. The airplane made another left bank, and then it made a sudden nose dive into the ground. Other witnesses interviewed made similar statements.

One of the hangars located at 3DA was equipped with a security system that consisted of four video cameras and an area microphone. The cameras were aimed at the side of the ramp and taxiway adjacent to the grass runway. The cameras captured four different views of the accident flight. The security system captured the following information:

1. At 10:07:46, takeoff power was applied. The airplane was not in sight.
2. At 10:08:00 to 10:08:07, camera 4 showed the airplane after liftoff as it flew over the runway and then went out of view. The engine noise could be heard.
3. At 10:08:06, cameras 1 and 3 showed a shadow of the airplane as it flew over the runway. The engine noise could be heard.
4. At 10:08:08 to 10:08:18, camera 2 showed the shadow of the airplane as it appeared over the runway, and then was seen departing the end of the runway. The shadow of the airplane was seen turning left over the trees. The engine noise could be heard.
5. At 10:08:19, the engine sound quit.
6. At 10:08:23, the airplane was heard crashing into trees.

The 60-year-old pilot held a private pilot's certificate. He was operating as a sport pilot, and was not required to possess a current Federal Aviation Administration (FAA) medical

certificate. He had a total of about 209 flight hours with about 41 hours in the make and model of the accident airplane.

The airplane was a two seat amateur-built, experimental Drochak Aventura II amphibian airplane with a 100-horsepower Rotax 912 ULS engine. The last conditional maintenance inspection was in July 2007, and it had flown 47 hours since the inspection. The stall speed in the clean configuration was about 42 mph and about 30 mph in the landing configuration. The airplane had two throttle control handles. The throttle handle for the left seat pilot was located on the left side of the cockpit. The throttle handle for the right seat pilot was located on the right side of the cockpit. The distance from the center of the cockpit to the throttle located on the right side of the cockpit was about 20.5 inches. The throttles on the carburetors were spring loaded to the full open position if the throttle linkage was disconnected.

The airplane collided with a tree and impacted the front lawn of a house just west of the road that bordered the west side of the airport. The wreckage of the entire airplane was confined to the initial impact site. The nose of the amphibian's fuselage was crushed aft and was broken at the cockpit's instrument panel. The engine was mounted aft of the airplane's high wing. The engine, engine mounts, and wing spars and struts exhibited forward buckling, and had compromised the cockpit space. The leading edge of the left wing was crushed aft and the left wing spar was broken. The right wing remained intact with no leading edge damage. The empennage exhibited no impact damage. The flight control cables exhibited continuity from the flight controls to the flight control surfaces.

The three bladed composite propeller remained attached to the engine. One blade was straight and appeared undamaged. The second blade was straight but had received impact damage about mid-span. The third blade was broken 12-15 inches from the propeller hub. None of the propeller blades exhibited leading edge gouges or chordwise scratching.

The engine was separated from the fuselage during recovery of the wreckage to a hangar facility. The engine was rotated by hand and no internal damage was noted. An engine run was conducted and it operated.

There was an 18-gallon fuel tank located behind the pilots' seats. The fuel tank was not ruptured and about 8 gallons of fuel remained. Both switches for the dual electronic ignition were found in the OFF position. It was not determined if a first responder had turned the switches to OFF. None of the first responders remembered setting the switches to OFF.

The pilot's throttle handle, handle strap, throttle control tube, and a portion of the left wing spar were sent to the National Transportation Safety Board's Materials Laboratory for examination. The inspection of the wing spar revealed that the fracture occurred in an area of the wing spar containing a hole with a smooth bore. The region around the fracture had evidence of plastic deformation, and the fracture surfaces had a 45-degree angle shear lip. The plastic deformation and 45-degree shear lip are consistent with a ductile fracture due to tension and bending overstress. There was no indication of preexisting damage that initiated the fracture.

The throttle control assembly was manufactured by pressing steel inserts into each end of an aluminum tube. The end of the throttle control tube that had been connected to the throttle hand strap was found with the insert separated from the tube. The steel inserts had a crosswise hole drilled through them so that once pressed into the tube, they could be secured in place by pressing a dimple into the tube, from the exterior, in alignment with the crosswise hole in the insert.

A tension test, to evaluate the pull out strength of the insert, was conducted on the intact end of the throttle control tube. The maximum force recorded during the tensile test was 1,191 pounds, after which the force gradually decreased until the entire insert had been extracted from the tube.

After the tensile test, it was observed that the insert from the intact end of the control tube was slightly different than the one that was found separated from the tube. Both inserts had the same diameter but the one from the intact side was slightly shorter. The insert that was pulled out during the test had a square shoulder around the crosswise hole while the insert that was found separated from the tube had a chamfer around the circumference of the crosswise hole. The location of the crosswise hole with respect to the outboard end of the insert was slightly different (0.02 inch).

The inspection of the throttle hand strap revealed that it exhibited plastic deformation, which was consistent with multiple applied forces from various directions as exhibited by the compound angle bends.

First responders reported that the pilot initially survived the accident, but was not responsive. The time of death was 1118.

An autopsy was conducted on July 16, 2008, by the Genesee County Medical Examiner, Flint, Michigan. The stated cause of death was "Blunt Force Injuries Due to an Airplane Crash." The toxicology report was negative for all substances tested.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	60, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Sport pilot	<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	209 hours (Total, all aircraft), 41 hours (Total, this make and model)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Drochak	<b>Registration:</b>	N621CD
<b>Model/Series:</b>	Aventura II	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	AA2A0130
<b>Landing Gear Type:</b>	Tricycle; Amphibian	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	July 21, 2007 Condition	<b>Certified Max Gross Wt.:</b>	1430 lbs
<b>Time Since Last Inspection:</b>	47 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	47 Hrs at time of accident	<b>Engine Manufacturer:</b>	Rotax
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	912ULS
<b>Registered Owner:</b>	Clifford Drochak	<b>Rated Power:</b>	100 Horsepower
<b>Operator:</b>	Clifford Drochak	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	FNT,782 ft msl	<b>Distance from Accident Site:</b>	6 Nautical Miles
<b>Observation Time:</b>	09:53 Local	<b>Direction from Accident Site:</b>	135°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	8 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	210°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.09 inches Hg	<b>Temperature/Dew Point:</b>	23°C / 12°C
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Flushing, MI (3DA )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	10:15 Local	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Dalton Airport 3DA	<b>Runway Surface Type:</b>	Grass/turf
<b>Airport Elevation:</b>	733 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	09	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	1633 ft / 150 ft	<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Fatal	<b>Latitude, Longitude:</b>	43.052501,-83.804725(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Silliman, James
<b>Additional Participating Persons:</b>	Phil Bolyard; FAA Detroit FSDO; Belleville, MI
<b>Original Publish Date:</b>	December 29, 2009
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=68748">https://data.nts.gov/Docket?ProjectID=68748</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).