



Aviation Investigation Final Report

Location:	King Salmon, Alaska	Accident Number:	ANC08CA091
Date & Time:	July 27, 2008, 18:30 Local	Registration:	N3501L
Aircraft:	Cessna T206H	Aircraft Damage:	Substantial
Defining Event:	Collision with terr/obj (non-CFIT)	Injuries:	3 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The private pilot was ferrying friends to a lakeside lodge in his float-equipped airplane, under Title 14, CFR Part 91. He said he landed too close to the beach, and was unable to stop before the airplane impacted the beach. According to the pilot, the airplane traveled up the beach 20-30 feet, and the left float structure collapsed. He said the left wing and left horizontal stabilizer struck the ground, damaging both. The pilot said there were no known mechanical problem with the airplane prior to the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's misjudged speed and distance during a water landing.

Findings

Aircraft

Descent/approach/glide path - Not attained/maintained

Factual Information

History of Flight

Landing-landing roll

Collision with terr/obj (non-CFIT) (Defining event)

Pilot Information

Certificate:	Private	Age:	54,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 1, 2008
Occupational Pilot:	No	Last Flight Review or Equivalent:	March 1, 2008
Flight Time:	1792 hours (Total, all aircraft), 510 hours (Total, this make and model), 37 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N3501L
Model/Series:	Т206Н	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	T20608304
Landing Gear Type:	Float	Seats:	6
Date/Type of Last Inspection:	July 1, 2008 Annual	Certified Max Gross Wt.:	3800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	509 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	TIO-540-AJ1A
Registered Owner:	Rooney Consulting & Aviation LLC	Rated Power:	310 Horsepower
Operator:	William Rooney	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	5 miles
Lowest Ceiling:	Overcast / 1800 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	0 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	16°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	King Salmon, AK	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	56.959636,-158.579925(est)

Administrative Information

Investigator In Charge (IIC):	Lewis, Lawrence
Additional Participating Persons:	
Original Publish Date:	September 26, 2008
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=68848

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.