



Aviation Investigation Final Report

Location:	Duncan, Oklahoma	Accident Number:	DEN08LA163
Date & Time:	September 28, 2008, 15:25 Local	Registration:	N6714E
Aircraft:	Beech C23	Aircraft Damage:	Substantial
Defining Event:	Powerplant sys/comp malf/fail	Injuries:	2 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

During the local flight, the airplane's engine began to violently shake and the pilot elected to shut down the engine and perform an emergency landing to a field. The airplane impacted a fence and terrain, which resulted in a bent firewall and left wing. A review of the maintenance records showed that, approximately 23 hours prior, the engine had experienced a loss of engine oil due to faulty maintenance during an annual inspection. The engine underwent maintenance and the airplane was returned to service. Examination and disassembly of the engine revealed that the crankshaft had fractured into 3 sections and that improper maintenance had been performed on several engine components. Metallurgical examination of the crankshaft revealed that the crankshaft had been improperly reworked which resulted in fatigue and crankshaft failure. The crankshaft rework and engine reassembly did not follow the manufacturer's overhaul manual.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A total loss of engine power due to the fatigue failure of the engine crankshaft. Contributing to the accident were the improper maintenance to the engine crankshaft, improper reassembly of the engine, and failure to follow the engine manufacturer's overhaul manual.

Findings

Aircraft	Recip engine power section - Failure
Aircraft	Recip engine power section - Fatigue/wear/corrosion
Personnel issues	Repair - Maintenance personnel
Aircraft	Recip engine power section - Incorrect service/maintenance
Personnel issues	Use of manual - Maintenance personnel

Factual Information

History of Flight

Maneuvering	Powerplant sys/comp malf/fail (Defining event)
Emergency descent	Loss of engine power (total)

On September 28, 2008, at 1525 central daylight time, a Beech C23 single-engine airplane, N6714E, sustained substantial damage when it impacted terrain following a loss of engine power while maneuvering near Duncan, Oklahoma. The private pilot, who was the registered owner, and passenger sustained minor injuries. Visual meteorological conditions prevailed for the Title 14 Code of Federal Regulations Part 91 personal flight. The local flight departed Duncan approximately 1500.

The pilot, who purchased the airplane in February 2008, flew the airplane from Guthrie, Oklahoma, to Duncan on a 1.3 hour flight with no problems noted. The passenger boarded the airplane in Duncan, and the pilot performed a run-up prior to the local flight. At an altitude of 2,500 mean sea level (msl), the engine RPM dropped, and the engine "shook violently." The pilot attempted to troubleshoot the engine problem; however, the engine vibration continued. The pilot elected to shut down the engine and execute a forced landing to a field. During the forced landing, the airplane impacted a fence and terrain. Examination of the airplane revealed the firewall and left wing were bent and buckled. The tachometer showed 1,688 hours at the time of the accident.

A review of the Lycoming O-360-A4K (s/n: L26749-36A) engine maintenance records revealed the engine underwent its most recent "annual" inspection on December 20, 2007, at a tachometer time of 1,661.8 hours. During the inspection, the engine oil cooler lines were replaced and no additional anomalies were noted. On January 21, 2008, at a tachometer time of 1,664.8 hours, the engine underwent maintenance due to an engine oil leak caused by a crack oil cooler elbow fitting. Included in that maintenance was the disassembly of the engine and replacement of the rod bearings, main crankshaft bearings, and piston rings. The engine was test run and leak checked with no anomalies noted. The engine maintenance records stated that the maintenance was done in accordance with the Lycoming Overhaul Manual.

On October 21, 2008, the engine was examined and disassembled at the facilities of Air Salvage of Dallas, Lancaster, Texas, under the supervision of a NTSB investigator, and three Federal Aviation Administration (FAA) inspectors. According to a FAA inspector's report, examination of the engine revealed the wrong gasket was installed on the oil filter adapter assembly, the oil filter contained metal debris, the piston rings were worn and did not exhibit etched part numbers, and the oil rings were different between the 4 pistons. Internal examination of the engine revealed the crankshaft was fractured into 3 sections, 2 of the 8 tappets exhibited pitting, the aft main bearings and rod bearing part numbers matched the

January 2008 engine maintenance record entry, however, the front main bearings did not match the part number indicated in the record. The fractured crankshaft was retained for metallurgical examination.

The fractured crankshaft was examined by the NTSB materials laboratory. Examination of the crankshaft revealed the crankshaft was fractured in two places; one fracture occurred forward of the number 2 crankshaft journal and one fracture occurred aft of the number 3 crankshaft journal. The features on both fracture surfaces were consistent with fatigue crack propagation with crack initiation at the journal radii. Circumferential crack arrest lines were observed on both fracture surfaces and ratchet marks were visible on the forward fracture surface, consistent with fatigue crack growth. The crack arrest lines and ratchet marks pointed towards the journal radius as the initiation site for both fatigue cracks.

Size measurements of the crankshaft journals were consistent with material removal from some of the journals. Three of the four crankshaft journals were undersized. Journal numbers 2 and 4 were undersized by 0.003 inch, and number 3 was undersized by 0.005 inch. According to the Lycoming Overhaul Manual, the crankshaft journal diameters may be reduced by 0.003 inch by polishing without renitriding the crankshaft. In that event, it is advised that all journals be polished to the same size. Grinding is not advised as it may penetrate the nitride layer at the journal radius leaving the crankshaft prone to fatigue failure. If a journal is polished to undersize, the code "M03P" should be stamped as a suffix to the part number on the flange. There was no code suffix found on the flange. If a journal is reduced by more than 0.003 inch, the journals should be ground to undersize, the shaft renitrided and the code "RN" stamped as a suffix to the serial number on the flange. There was no code suffix found on the flange. In addition, there was no documentation noted in the maintenance records that the shaft had been renitrided.

Pilot Information

Certificate:	Private	Age:	53, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	September 12, 2007
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 4, 2007
Flight Time:	113 hours (Total, all aircraft), 27 hours (Total, this make and model), 52 hours (Pilot In Command, all aircraft), 11 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N6714E
Model/Series:	C23	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	M-2200
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	December 20, 2007 Annual	Certified Max Gross Wt.:	2450 lbs
Time Since Last Inspection:	26 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1688 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-360-A4K
Registered Owner:	Donald G. Holloway	Rated Power:	180 Horsepower
Operator:	Donald G. Holloway	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DUC	Distance from Accident Site:	
Observation Time:	15:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	100°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	27°C
Precipitation and Obscuration:			
Departure Point:	Duncan, OK (DUC)	Type of Flight Plan Filed:	None
Destination:	Duncan, OK (DUC)	Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Unknown

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	34.470832,-97.959724(est)

Administrative Information

Investigator In Charge (IIC):	Sauer, Aaron
Additional Participating Persons:	Lana West; Federal Aviation Administration; Oklahoma City, OK
Original Publish Date:	June 11, 2009
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=69223

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).