



Aviation Investigation Final Report

Location: 15N OF MEDFORD, Oregon Accident Number: SEA82DA068

Date & Time: May 9, 1982, 16:05 Local Registration: N1434Z

Aircraft: de Havilland 2 Aircraft Damage: Substantial

Defining Event: Injuries: 10 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE PILOT STARTED A DOWNWIND TAKEOFF ON RUNWAY 15 WITH 9 PARACHUTISTS ON BOARD. THE RUNWAY WAS UNIDIRECTIONAL REQUIRING TAKEOFFS ON RUNWAY 15 WHICH SLOPED DOWNHILL. AFTER BEGINNING THE TAKEOFF ROLL, THE PILOT HAD DIFFICULITY IN MAINTAINING DIRECTIONAL CONTROL AND INITIATED ABORT PROCEDURES. REPORTEDLY, THE AIRCRAFT CONTINUED TO VEER TO THE RIGHT IN SPITE OF THE USE OF HARD LEFT RUDDER AND BRAKING ACTION. AS THE AIRCRAFT DECELERATED, IT DEPARTED THE RIGHT SIDE OF THE RUNWAY, STRUCK 3 FENCE POSTS, AND COLLIDED WITH A PARKED STINSON, N368C. THE PILOT REPORTED THAT THE PARACHUTIST OCCUPYING THE COPILOT'S SEAT STATED THAT HE HAD PLACED HIS FEET BEHIND THE RUDDER PEDALS SHORTLY BEFORE TAKEOFF.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (F) PASSENGER BRIEFING - INADEQUATE - PILOT IN COMMAND

- 2. (C) FLT CONTROL SYST, RUDDER CONTROL MOVEMENT RESTRICTED
- 3. (C) CONTROL INTERFERENCE INADVERTENT PASSENGER
- 4. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAKEOFF

Findings

- 5. (F) WEATHER CONDITION TAILWIND
- 6. (F) TERRAIN CONDITION DOWNHILL
- 7. (F) OBJECT
- 8. (F) OBJECT AIRCRAFT PARKED/STANDING

Page 2 of 6 SEA82DA068

Factual Information

Pilot Information

Certificate:	Commercial	Age:	44,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 4, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3965 hours (Total, all aircraft), 63 hours (Total, this make and model), 3861 hours (Pilot In Command, all aircraft), 81 hours (Last 90 days, all aircraft), 42 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 3 of 6 SEA82DA068

Aircraft and Owner/Operator Information

Aircraft Make:	de Havilland	Registration:	N1434Z
Model/Series:	22	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	5116860
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	5100 lbs
Time Since Last Inspection:	46 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6476 Hrs	Engine Manufacturer:	P&W
ELT:	Installed	Engine Model/Series:	985-39
Registered Owner:	OREGON SKYSPORTS	Rated Power:	450 Horsepower
Operator:	RALPH A. HATLEY	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MFR	Distance from Accident Site:	9 Nautical Miles
Observation Time:	15:50 Local	Direction from Accident Site:	172°
Lowest Cloud Condition:	Scattered / 5000 ft AGL	Visibility	30 miles
Lowest Ceiling:	Broken / 6000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	55°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	15N OF MEDFORD , OR (OR96)	Type of Flight Plan Filed:	None
Destination:	15N OF MEDFORD , OR (OR96)	Type of Clearance:	None
Departure Time:	16:05 Local	Type of Airspace:	

Page 4 of 6 SEA82DA068

Airport Information

Airport:	BEAGLE SKY RANCH OR96	Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	15	IFR Approach:	None
Runway Length/Width:	3000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	9 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	10 None	Latitude, Longitude:	42.279384,-122.900451(est)

Page 5 of 6 SEA82DA068

Administrative Information

Investigator In Charge (IIC):

Additional Participating

Persons:

Original Publish Date: May 9, 1983

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=69625

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA82DA068