

Aviation Investigation Final Report

Location:	ANCHORAGE, Alas	ka	Accident Number:	ANC82DA066
Date & Time:	August 4, 1982, 08	:40 Local	Registration:	N4582H
Aircraft:	PIPER	PA-17	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General av	viation - Personal		

Analysis

WHILE LANDING WITH A LIGHT CROSSWIND, THE AIRCRAFT VEERED TO THE RIGHT AND THE LEFT GEAR COLLAPSED. THERE WAS NO EVIDENCE OF A PRE-ACCIDENT MALFUNCTION OF FAILURE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

1. DIRECTIONAL CONTROL - INITIATED - PILOT IN COMMAND

2. (F) WEATHER CONDITION - CROSSWIND

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

4. (C) GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

5. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL Findings 6. LANDING GEAR, NOSE GEAR - OVERLOAD

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	November 13, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	335 hours (Total, all aircraft), 8 hours (Total, this make and model), 182 hours (Pilot In Command, all aircraft), 55 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N4582H
Model/Series:	PA-17 PA-17	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	17-7
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2152 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	C-65
Registered Owner:	MICHAEL J. FULLERTON	Rated Power:	65 Horsepower
Operator:	MICHAEL J. FULLERTON	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MRI	Distance from Accident Site:	
Observation Time:	08:42 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 23000 ft AGL	Visibility	60 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ANCHORAGE , AK (MRI)	Type of Flight Plan Filed:	None
Destination:	ANCHORAGE , AK (MRI)	Type of Clearance:	
Departure Time:	08:30 Local	Type of Airspace:	

Airport Information

Airport:	MERRILL FIELD MRI	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	
Runway Length/Width:	4000 ft / 100 ft	VFR Approach/Landing:	Touch and go

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	61.160583,-149.990173(est)

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	August 4, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=69768

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.