



Aviation Investigation Final Report

Location: CHANDLER, Arizona Accident Number: LAX82DA323

Date & Time: August 28, 1982, 13:30 Local Registration: N47930

Aircraft: CESSNA 152 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

STUDENT PILOT DURING SOLO FLIGHT APPLIED RIGHT BRAKE TO CORRECT VEER AND AIRCRAFT VEERED RIGHT OFF RUNWAY. AIRCRAFT COLLIDED WITH BUSHES AND NOSED OVER ALONGSIDE RUNWAY. THE RIGHT BRAKE WAS LOCKED AFTER ACCIDENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) LANDING GEAR, NORMAL BRAKE SYSTEM - LOCKED

- 2. (C) RUDDER IMPROPER USE OF PILOT IN COMMAND
- 3. (C) BRAKES(NORMAL) IMPROPER USE OF PILOT IN COMMAND
- 4. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND
- 5. (C) GROUND LOOP/SWERVE UNCONTROLLED PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings 6. (F) OBJECT - TREE(S)

Page 2 of 5 LAX82DA323

Factual Information

Pilot Information

Certificate:	Student	Age:	22,Male
Airplane Rating(s):		Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 19, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	26 hours (Total, all aircraft), 26 hours (Total, this make and model), 4 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N47930
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	15283263
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1249 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-235-L2C
Registered Owner:	FRED SPEARS	Rated Power:	110 Horsepower
Operator:	VENTURE AVIATION	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX82DA323

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PHX	Distance from Accident Site:	16 Nautical Miles
Observation Time:	12:49 Local	Direction from Accident Site:	166°
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	45 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	102°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	PHOENIX , AZ (PHX)	Type of Flight Plan Filed:	None
Destination:	PHOENIX , AZ (PHX)	Type of Clearance:	
Departure Time:	13:00 Local	Type of Airspace:	

Airport Information

Airport:	MEMORIAL L07	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	30	IFR Approach:	
Runway Length/Width:	8577 ft / 300 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.320732,-111.869895(est)

Page 4 of 5 LAX82DA323

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: August 28, 1983

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=70190

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX82DA323