



Aviation Investigation Final Report

Location:	CONWAY, South Car	rolina	Accident Number:	ATL83LA076
Date & Time:	December 28, 1982,	09:55 Local	Registration:	N6537P
Aircraft:	CESSNA	152	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional			

Analysis

THE STUDENT PILOT STATED HE ATTEMPTED TO LAND BEYOND THE MID-POINT OF THE RUNWAY FROM A HIGH THRESHOLD POSITION WITH FULL FLAPS DEPLOYED. THE AIRCRAFT WAS FORCED ONTO THE RUNWAY, BOUNCED 3 TIMES, AND THE NOSE GEAR COLLAPSED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

(F) WEATHER CONDITION - TAILWIND
(C) WIND INFORMATION - NOT UNDERSTOOD - PILOT IN COMMAND
(F) LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND
(C) GO-AROUND - NOT PERFORMED - PILOT IN COMMAND

Occurrence #2: GEAR COLLAPSED Phase of Operation: LANDING - ROLL Findings 5. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND 6. (F) LANDING GEAR - OVERLOAD

Factual Information

Pilot Information

T not information			
Certificate:	Student	Age:	22,Male
Airplane Rating(s):		Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	December 8, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:		rs (Total, this make and model), 1 hou all aircraft), 1 hours (Last 24 hours, al	

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N6537P
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	15285030
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	44 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	45 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-235-L2C
Registered Owner:	NORTH AMERICN INSTITUTE OF AVI	Rated Power:	11 Horsepower
Operator:	NORTH AMERICN INSTITUTE OF AVI	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC))	Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 2	000 ft AGL	Visibility	15 miles
Lowest Ceiling:	Unknown		Visibility (RVR):	
Wind Speed/Gusts:	10 knots /		Turbulence Type Forecast/Actual:	/
Wind Direction:	225°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation			
Departure Point:	CONWAY	, SC (HYW)	Type of Flight Plan Filed:	None
Destination:	CONWAY	, SC (HYW)	Type of Clearance:	None
Departure Time:	00:09 Local		Type of Airspace:	

Airport Information

Airport:	CONWAY-HORRY COUNTY HYW	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	4	IFR Approach:	None
Runway Length/Width:	3700 ft / 60 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.829486,-79.039344(est)

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	December 28, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=70330

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.